

Kobe
23rd April 1909

Arthur L. Jones

Re: The Nippon Yusen Kaisha Survey the
Steel Screw Steamer "Awaji Maru" 1268 tons reg^d
of Tokio in order to ascertain the nature & extent of
damage alleged to have been sustained at 4.10 am.
of the 3rd April 1909 by colliding with the steamer
California at Taku Bar outer anchorage.
See the Log Books & a previous report made by
the Surveyors to Lloyds Agents at Newchwang
dated the 7th inst.

Upon examination of the vessel afloat in
Kobe harbour on the 17th inst. the following
damage was found, viz:- The plate next the stem
in the fore-castle deck sheer strake on the
starboard side broken: the stem bar broken
short off at the fore-castle deck: the bow plates
above the fore-castle deck on both sides broken:
the stringer plate of the fore-castle deck on the



© 2021

Lloyd's Register
Foundation

Starboard side bent & the fairlead displaced: one rail staunchion broken & one bent & rails bent for a few feet from the stem: Connections of fore mast stay & fore top mast stay at bow carried away: air pipe & goose neck from fore peak tank broken: and caulking of fore-castle wood deck started in places.

In the repair of the above damage the following recommendations were made, viz:— A new stem plate in the fore-castle sheer strake on the starboard side to be fitted: a new length of stem bar about four feet long to be fitted a new scarp being formed: new bow chock plates on each side to be fitted: the stringer plate of the fore-castle deck on the starboard side to be cut & pieced with a new plate 9ft 6ins by 1ft 6ins by 7/20 double riveted & fitted underneath the waterway angle: the fairleads on both sides to be resecured the wood deck partly recaulked near the stem & one deck plank of 6ins. by 3ins by thirteen feet of beam to be renewed: one rail staunchion to be welded & one straightened & refitted & bent rails to be straightened: Stays from fore-mast to be resecured at stem: a new piece & new goose neck to be fitted to the air pipe of the fore peak tank: also two short lengths of D bar moulding to be renewed. The repairs to be tested by water hose. These recommendations have been completed with.

W. Thos. Jones

Fee £100⁰⁰

W1378-0017 1/2