

# REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 19... When handed in at Local Office 18 JUN 1921 Port of London

No. in Survey held at London Date, First Survey 27th January Last Survey 2nd June 1920  
Reg. Book. on the Wood, Iron or Steel M. S. Evelyn Hope Master A. R. Hamilton

TONNAGE:— Built at Newcastle By whom W. Dobson & Co When 1916  
GROSS 134 Owners The Hope Lightering Co Ltd Port belonging to London  
UNDER DK. 120  
NET 94 Owners' Address 4A St. Dunstons Alley E.C.3  
(if not already recorded in Appendix to Register Book).

Surveyed Afloat or in Dry Dock? Yes Name of Dock Canal Dock Destined Voyage

WB=CellDBorDBa feet; uE&B feet; f feet; }  
total capacity tons. FPT tons; APT tons; MT feet tons. }  
N.B.—All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. Port

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined? Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR S. 5 No 3.

Now done. Vessel placed in Dry Dock, bottom and sides cleaned, examined and re-coated. Hold, peak, engine space examined and all steelwork sanded and re-coated as necessary. The shell plating was drilled with satisfactory results (see 1st Entry report 83144). After peak examined internally and tested. Cables, ranges, chain locker, anchors, general equipment, deck, hatches, pumps, air and sounding pipes, windlass, steering gear examined and found or made satisfactory. Freeboard verified

SUMMARY OF DAMAGE REPAIRS :—				Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :—
Renewed	...	...	...								
Removed and Faird or Repaired	...	...	...								
Faird or Repaired in place	...	...	...								
PRESENT CONDITION OF THE				Stringers							
Decks	Good			Inner Bottom Plating							
Caulking of Decks				State if Tanks have been examined inside	Yes						
Waterways				State if Tanks now tested	Yes						
Coamings				Bulkheads	Good						
Beams & Fastenings				Ceiling							
Outside Plating				Cement or Asphalt (State which.)	(Cement)						
Caulking of ditto				Rudder							
Rivets				Steering gear and its connections							
Breasthooks & Crutches				Windlass							
Transoms	Good			Have Pumps now been examined and found efficient?	Yes						
Frames				Have Sluice Valves now been examined and found efficient?	None						
Reverse Frames				Have Watertight Doors now been examined and found efficient?	None						
Floors											
Keelsons											
				Dblg. Plates under Sounding Pipes	Good						
				Engine Room Skylights							
				Coal Bunkers, Open'gs, Lids, &c.							
				Scuppers							
				Cargo Hatchways							
				Hatches							
				Planking of Wood Vessels							
				Caulking ditto							
				Treenails ditto							
				Breasthooks & Stemson ditto							
				Transoms, Pointers, & Crutches ditto							
				Timbers of Frame at openings ditto							
				Ditto ditto at other places ditto							
				Stringers, Clamps & Shells ditto							
				Spitting ditto (State if examined.)							
				Copper, or Y.M. of Wood Vessels (State if on Floor) When put on, Month Year							
				Boat	Good						
				Masts, Yards, &c. Signal mast							
				Condition, how ascertained when unshipped (State if wedges removed)							
				Sails							
				Equipment letter							
				Anchors, No. of	2 B. 15.						
				Cables (State if now ranged)	Yes						
				length 100 size 1 1/2							
				approx. on board							
				length 100 size 1 1/2							
				Hawser & Warps	Good						
				Standing & Running Rigging							

General Observations, Opinion as to Class, Recommendation, &c.:—  
State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,15," or "to remain as classed and to have record of survey, 1,15, and the notations of ss No. 1-15 and ptND15, &c."

This Vessel is now in Good Condition and eligible in my opinion to be Classed as Contemplated, and to have Notation of S. 5 LN. No 3 6-20

Special Damage or Repair Fee (if any) £  
Travelling Expenses (if chargeable) £  
Second Surveyor's Fee (if any) £  
Fees applied for, £  
Received by me, £  
TUE FEB 11 1921

Committee's Minute  
Character Assigned

Norman Dobson  
Surveyor to Lloyd's Register of Shipping.  
Lloyd's Register  
W1383-0131  
W1385-0132