

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 18.3.1942 When handed in at Local Office 18.3.1942 Port of Bombay
No. in Reg. Book. Survey held at Bombay Date, First Survey 14.3.1942 Last Survey 14.3.1942
(No. of Visits 1)

19882 on the Wood, Iron or Steel s/s "Bahadur"
TONNAGE:— Built at Port Glasgow By whom Lithgows Ltd. When 1929.9
GROSS 5424 Owners Asiatic Steam Nav. Co. Ltd. Owners' Address (If not already recorded in Appendix to Register Book).
UNDER DK. 5024 Managers Port belonging to London
NET 3397

Surveyed Afloat or in Dry Dock? Drydock Name of Dock Merewether Drydock Destined Voyage
WB=Cell D Bor D Ba feet; uE&B feet; f feet
total capacity tons. FPT tons; APT tons; MT feet tons.)

N.B.—All alterations in the existing records should be underlined.
If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 8050. Port LA.

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Particulars of Classification (which must be inserted precisely as in Register Book and Supplements).	
CHARACTER. + for Special Survey. Date of last Survey and of Periodical Surveys.	Machinery and Boiler surveys (including date of N.B., if any).
100 A1-3.41	LMC 1.38
	MBS 2.46
	TSC 2.41
	DBS 5.41
S.S. Cal. No. 2-38	
Society's Freeboard (if assigned) as painted on Ship and now verified	

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition:
NOW DONE: Vessel in dry dock: the bottom and rudder cleaned, examined and recoated. Decks, hatches, ventilators and coamings and the steering gear examined. The vessel generally examined as far as practicable. Chain cables ranged and examined.
S.R. LIST: Examined the 3 indented after keel plates and found them meanwhile efficient. Nothing was done towards repairing them at this time.

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired ..								
Faired or Repaired in place								

PRESENT CONDITION OF THE	State if Tanks have been examined inside	Air and Sounding Pipes	Copper, or Y.M. of Wood Vessels
Decks	State if Tanks now tested	Dbng. Plates under Sounding Pipes	(State if on Felt.)
Caulking of Decks	Bulkheads	Engine Room Skylights	When put on, Month Year
Coamings	Ceiling	Coal Bunkers, Open'gs, Lids, &c. ..	Boats
Beams & Fastenings	Cement or Asphalt	Oil Bunkers	Masts, Yards, &c.
Outside Plating	Rudder	Scuppers	Condition, how ascertained
" " in way of sidelights ..	Steering gear and its connections ..	Cargo Hatchways	(State if wedges removed)
Breasthooks	Windlass	Hatches	Sails
Transoms	Have pumps now been examined and found efficient?	Planking of Wood Vessels	Equipment letter
Frames	Have Sluice Valves now been examined and found efficient?	Caulking	Anchors, No. of
Reverse Frames	Have Watertight Doors now been examined and found efficient?	Treenails	Chain Locker
Longitudinals	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stems	Cables (State if now ranged)
Transverses		Transoms Pointers & Crutches	" length mean diamr.
Floors		Timbers of Frame at openings	" (on board) size
Keelsons		Ditto Ditto at other places	" Rule length
Stringers		Stringers, Clamps & Shells	Hawser & Warps
Inner Bottom Plating		Salting	Standing and Running Rigging

General Observations, Opinion as to Class, Recommendation, &c.:—
State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss. No. 1-24 and ptd 24, &c."
This vessel is eligible, in my opinion, to remain as classed with fresh record of Survey 3,42 deferred for completion of S.S. No. 3, subject to the 3 after keel plates being repaired at Owners convenience.

Survey Fee (Per Section 29) £ 115/-
Special Damage or Repair Fee (if any) £
(Per Sec. 29)
Travelling Expenses (if chargeable) £ 5/-
Second Surveyor's Fee (if any) £
Committee's Minute
Character Assigned

Fees applied for, 18.3.1942
Received by me,
Surveyor to Lloyd's Register of Shipping.

TUE. 7 JUL 1942
10001
Subject D