





Owners state they don't wish  
 to continue with the letter and endorsement  
 on this report

N.B.—If this Report is copied by Copying Press, special care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

Engine Repairs:— HP & MP Crank pin brasses  
 re-metalled. All astern guide bars skimmed up and  
 refitted. MP Quadrant block skimmed & refitted.  
 Suction & delivery valves for main engine helge pump renewed.  
 New continuous liner fitted to tail shaft. Spare  
 propeller fitted on tail shaft with new key.  
 Main steam and lower water gauge pipes removed to  
 shop, annealed, afterwards tested by hydraulic pressure  
 to 360 lbs per sq in, found satisfactory & refitted, and  
 other minor repairs effected.

R.R.

7/1/20  
 L.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.



© 2021  
 Lloyd's Register  
 Foundation