

manoeuvring satisfactory.

All fuel tanks have been tested as required and found tight.

The bilge pumps to main motor and to motor winch were found working satisfactory.

The intermediate shaft has been examined by me during construction, material tested as required and found good. Shaft stamped for identification

Lloyd's
CX-578
83-11-13

The copy of Stockholm report CV 1219. and the approved pumping plan is forwarded herewith.

The following spare gear has been applied on board:
One ignition ball, 4 piston springs, 2 fuel injection nozzles for each cylinder, 6 cleannings needles, one fuel pressure and one fuel suction ball valve, one lubricating valve for oil pump, 6 fuel valves and 6 springs for same, 2 speed regulators, 1 spiral spring and 1 ebony plate for regulator, 1 spring for reverse pump, packing for compressor, 1 lamp burner.

It has been recommended that the following spare parts should be supplied on the vessels arrival at London:
Two top end bolts and nuts, two bottom end bolts and nuts, two bearing bolts and nuts, 1 set of coupling bolts.

An approved fire extinguishing apparatus.

No marks could be found on the two air vessels although it was reported that same were tested, but it has been recommended that same should be tested to twice the working pressure on the vessels arrival at London to which port the vessel will sail at the end of this week from Antwerp.

G G Ochoa

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much dampened as to spread the ink, or to cause it to show through to the other side.

THE SURVIVOR ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.



© 2021

Lloyd's Register
Foundation