

The class is subject to the propeller being dealt with as next day docking.

3E

Received by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME

Champanois

Rpt.

Inst.

No.

10161

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/1924)

Nature of Survey

SPECIAL SURVEY OF ENGINES AND/OR BOILERS PARTLY HELD FOR S.S. No.2

LMC

~~LMC(M)~~

MS

BS

due *9.41*, partly held *now*--- *11.40* --- " " *2.41* *now completed.*

~~now further advanced~~ and the following repairs effected (due to damage from propeller fouling defence netting):—

*Screw shaft & all inboard shafting examined.
Two propeller blades failed.*

It is proposed to complete the survey:—*not valid.*

It is submitted that this proposal merits approval and the vessel is eligible to remain as classed, and WILL BE eligible for the record

+LMC-MS341 when the survey has been completed. *BS 2.41 } now, without
S.3.41 } special conditions.*

The following remains to be done to complete the Survey

All Rule requirements except examination of crankshaft journals, thrust & intermediate shafts.

It is concluded the oil fuel burning installation has been examined under working conditions.



© 2010

Lloyd's Register Foundation

W154-0111

commended (See Mdl. Rpt. N° 10141) and with a notation of MS Ch 3.41