

Report of Survey for Repairs, &c., of Engines and Boilers.

Date of writing Report 21 Dec 1898 When handed in at Local Office Grimsby Port of GRIMSBY
No. in Survey held at Grimsby Date, First Survey 8 Nov 97 Last Survey Dec 21 1901
Reg. Book 245 on the Machinery of the Wood, Iron or Steel John Howard Master
Gross 204 Vessel built at Leby By whom Cochran & Sons When 1904 10
Net 79 Engines made at Hill By whom C.D. Holmes & Co When 1904
Registered 60 Boilers, when made (Main) 1918 (Donkey)
Horse Power 1 Owners Howard & Co Port Grimsby Voyage Fishing
No. of Main Boilers 1 If Surveyed Afloat or in Dry Dock Not at present
No. of Donkey Boilers 1 Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)
Steam Pressure 180
In Main Boilers 180
In Donkey Boilers 1

Last Report No. 1 Port Grimsby
Particulars of Examination and Repairs (if any) Reclassification

Periodical surveys, when held, must be reported in detail and verbatim in the terms of the Rules. State clearly the nature of repairs, if any, and, in detail, the nature and extent of examinations and subsequent repairs. Repairs on vessels being detailed in the body of the report, should be briefly summarized at the end of the report. State also the date and initials of any letters respecting this case.

damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined?

Was a damage report made by anyone else? If so, by whom?

the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Do. " Donkey " " " "

his was not done, state for what reasons?

what parts of the Boilers could not be thus thoroughly examined?

what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

the Surveyor examine the Safety Valves of the Main Boiler?

the Surveyor examine the Safety Valves of Donkey Boiler?

the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?

the Surveyor examine the drain plugs of the Main Boilers?

the Surveyor examine all the mountings of the Main Boilers?

screw shaft now been drawn and examined? Yes Is it fitted with continuous liner? Yes or two liners? or is it without liners?

shaft now been changed? No If so, state reasons

shaft now fitted new? Has it a continuous liner? or two liners? or is it without liners?

the distance between ligament vane of stern bush and top of after bearing of screw shaft?

Survey is not complete state what arrangements have been made for its completion and what remains to be done?

slides, crank, shaft, pumps & Condenser, to be examined

will be done at the next overhaul in about 6 months.

crank shaft drawn & found cracked at aft end of cone

recommended a new shaft in 6 months.

the thrust shaft, sea connections, propeller, outside fastenings,

pumping arrangement examined & found satisfactory.

the Boiler described in Rept. 7158 now fitted in place

securely fastened.

mountings fitted are those from the old Boiler, now

examined & overhauled.

an steam pipe annealed & tested to 300 lbs water pressure

General Observations, Opinion, and Recommendation:—

the vessel will be eligible

clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also

any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, R.S. 5, 11, E.S. 5, 11, or L.M.C. 5, 11,

have her Class re-instated in the Register Book

the notation + H.M. with date + N.B. 12.18 when the survey

completed, subject to a new crank shaft being fitted

record of N.B. 18 in Black should now be made.

See (per Section 28) 2

Damage or Repair Fee (if any) 19

(per Section 28.) 19

Expenses (if chargeable) 19

Received by me, D. Ritchie

Engineer Surveyor to Lloyd's Register of Shipping.

Committee's Minute ERI.3 JAN. 1919

red no action

Reinstatement of class.

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

It is submitted that this vessel **WILL BE eligible** for the record. + L.M.C. 12-18, when the cylinders, pistons, slides, crank shaft, pumps and condenser, have been examined.

It is submitted that this vessel is eligible for **THE RECORD.** + N.B. 12-18.

274 G.S. 33½. H.S. 1155.

S. 12-18.

It is submitted that this vessel is eligible to remain as **CLASSED.** subject to the screw shaft being renewed before the end of June 1919.

JHA
30/12/18

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.



© 2021

Lloyd's Register
Foundation