

# Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office 128 SEP 1942)

Date of writing Report 19... When handed in at Local Office 17 SEP 1942 19... Port of NEWCASTLE-ON-TYNE

No. in Survey held at NORTH SHIELDS. Date, First Survey 24 Aug. Last Survey 10 Sept 1942  
2231. on the Machinery of the Wood, Iron or Steel S/S DALEBY (No. of Visits 6)

Age { Gross 4640. Vessel built at NEWCASTLE. By whom ARMSTRONG WHITWORTH & Co (ENGINEERS) LD. When 1929. 11.  
Net 2785. Engines made at NEWCASTLE. By whom ARMSTRONG WHITWORTH (ENGINEERS) LD. When 1929.  
Nominal Horse Power 419. Boilers, when made (Main) 1929. (Donkey)  
No. of Main Boilers 3 SB. Owners ROPNER SHIPPING CO. LD. Owners' Address  
No. of Donkey Boilers 1. Managers (if not already recorded in Appendix to Register Book.)  
Steam Pressure 180 LBS. Port W. HARTLEPOOL. Voyage  
No. of Main Boilers 180 LBS. If Surveyed Afloat or in Dry Dock SMITHS. FANTON. Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Last Report No. Port Particulars of Examination and Repairs (if any) DOCKING. GEN. EXAM.

Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined

as a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? NO.

" " Donkey " " " " " " " " " "

if this was not done, state for what reasons? BS. NOT DUE.

Did what parts of the Boilers could not be thus thoroughly examined?

What special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

State latest date of internal examination of each boiler. Present condition of funnel(s)

Did the Surveyor examine the Safety Valves of the Main Boiler? To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler? To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? , and of the Donkey Boilers?

Did the Surveyor examine the drain plugs of the Main Boilers? , and of the Donkey Boilers?

Did the Surveyor examine all the mountings of the Main Boilers? , and of the Donkey Boilers?

Has screw shaft now been drawn and examined? NO. Is it fitted with continuous liner? Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

Has shaft now been changed? If so, state reasons

Has the shaft now fitted been previously used? Has it a continuous liner? Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

State date of examination of Screw Shaft. State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft 7/32"

Engine parts, when referred to by numbers, should be counted from forward. Is electric light and/or power fitted YES.

Did the Surveyor examine the generators, motors, switchgear, cables and fuses? Electric Light Report attached YES.

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? YES.

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done COMPLETE.

DOCKING & GENERAL EXAMINATION:- Propeller, outer end of stern bush, and outside fastenings of sea connections, examined and found in good condition.

Main engines, shafting, pumps, condenser & all auxiliaries with steering engine, and windlass generally examined and found or placed in good condition. Steam pipes examined in place.

Following parts were opened up, examined and found or placed in good condition.

All crankshaft journals, and crankpins, air, feed & bilge pumps with valves, and connections, condenser tested, and dynamo engine.

Air pump cast iron bucket and bilge pump cover removed, remaining feed & bilge pump valves skinned & refreshed.

Levers in lower section renewed. Dynamo piston & rings renewed. Air feed pump valve gear adjusted.

Holding down bolts hardened up. 2 bolts renewed. (See also Electrical report.)

General Observations, Opinion, and Recommendation:- The machinery of this vessel so far as (State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9.11, B.&M.S. 9.11, & L.M.C. 9.11, or L.M.C. 140 lb., F.D., &c.) seems to be eligible in my opinion to remain as classed in the Register Book with fresh record of survey EXAMINED 9.42.

Survey Fee (per Section 29) £ : : Fees applied for 19  
Estimated fee £17.0  
Special Damage or Repair Fee (if any) £ : : Received by me, 19  
Travelling expenses (if chargeable) £ : :

Signature of Surveyor: A. Edmonds. Engineer Surveyor to Lloyd's Register of Shipping.

7% REPAIR LICENCE No 5040. FRL 9 OCT 1942  
Committee's Minute  
Assigned



Insert Character of Ship and Machinery precisely as in the Register Book

DALEBY

Electrical equipment.

General examination and wear and tear repairs.

The boiler pump lights were removed and the main cables were removed and replaced due to structural alterations. On completion the equipment was operated under working conditions with satisfactory results and the insulation resistance measured and found good. This equipment is now in my opinion in good order and safe working condition.

W. G. Cornell



MS 11.41 advanced.

It is submitted that this vessel WILL BE eligible for the record. H.M.S. 1041 on completion

& repaired 9.42 - 12 mod  
now,

ISA  
7/10/42

*[Faint, mostly illegible handwritten text, possibly bleed-through from the reverse side of the page]*