

# REPORT OF SURVEY FOR REPAIRS, &c., OF ENGINES AND BOILERS

(Received at London Office)

2 MAR 1954

Date of writing Report 13-2-54 When handed in at Local Office 13-2-54 Port of BOMBAY  
 No in Reg. Book. Survey held at BOMBAY Date. First Survey 19/11/53 Last Survey 21/1/54  
 (No. of Visits 8)

14371 on the Machinery of the Wood, Iron or Steel T.S.S. "JALADURGA"

Tonnage { Gross 3958 Vessel built at Glasgow By whom Barclay Curle & Co. Ltd. Year. Month. When 1910 - 11  
 Net 2162 Engines made at Glasgow By whom Barclay Curle & Co. Ltd. When 1910  
 Nominal Horse Power 573 Boilers, when made (Main) 1910 (Donkey) --  
 Owners Scindia Steam Nav. Co. Ltd. Owners' Address --  
 (if not already recorded in Appendix to Register Book.)  
 No. of Main Boilers 3 Managers -- Port Bombay Voyage --  
 No. of Donkey Boilers -- If Surveyed Afloat or in Dry Dock Merewether Dry Dock  
 Steam Pressure— (State name of Dock.)  
 in Main Boilers 215 lb.  
 in Donkey Boilers --

Last Report No. -- Port --  
 Particulars of Examination and Repairs (if any) BS & REPAIRS (M)

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined

Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a through examination at this time?

" " Donkey " " "

If not, state for what reasons

What special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

State latest date of internal examination of each boiler

Did the Surveyor examine the Safety Valves of the Main Boilers?

Did the Surveyor examine the Safety Valves of the Donkey Boilers?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?

Did the Surveyor examine the drain plugs of the Main Boilers?

Did the Surveyor examine all the mountings of the Main Boilers?

Has the screw shaft now been drawn and examined?

Has shaft now been changed? If so, state reasons

Is an approved oil retaining appliance fitted at the after end?

Is electric light and/or power fitted?

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms?

Engine parts, when referred to by numbers, should be counted from forward. Auxiliary machinery should be referred to by position in Machinery Space.

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done

NOW DONE: Vessel in dry dock; the propellers, sea fastenings and sea connections examined.

All boilers and their mountings examined throughout and their safety valves adjusted under steam.

Repairs now done: A few defective plain tubes and c.c. stays in each boiler were renewed.

In the Port aft boiler defective girder stays were renewed as follows:-

Starboard inboard c.c. Middle stay renewed.

Port outboard c.c. 1st Row from outboard middle and aft stays renewed.

Machinery Repairs Port L.P. piston now renewed. The bottom flange of the old piston was broken on the voyage Madras to Korea, apparently by an old 14" file having entered the cylinder by the bottom steam port and having turned on its edge.

During routine opening out of main engine cylinders now, the port M.P. cylinder cover was broken during turning the engine one morning as a large wooden baulk had been left standing on end on top of the piston the night before while the cover had been replaced loosely. A satisfactory repair to the cover was made.

## General Observations, Opinion, and Recommendation:-

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, BS 9,11, B&N 9,11, LMC 9,11 or RLMC 140 lb., FD, &c.)

CS 3,34

The machinery of this vessel is eligible to remain as classed with fresh record of B.S. 1.54.

Subject

B.S. Rs. 480/-

Dkg. Rs. 70/-

(Blr. &amp; Mach) Rs. 200/-

Special Damage or Repair Fee (if any)

(per Section 23.)

Travelling expenses (if chargeable) Rs. 64/-

Committee's Minute

Assigned

THURSDAY 25 MAR 1954

Deferred As not subject  
 Sub. BS 1.54

Fees applied for

13-2-54

Received by me,

19

*W. H. H. H.*  
 Engineer Surveyor to Lloyd's Register of Shipping.



Lloyd's Register  
 Foundation