

Report of Survey for Repairs, &c., of Engines and Boilers.

Date of writing Report Sept 24 40 When handed in at Local Office Sept 24 40 Port of New York
 No. in Survey held at New York Date, First Survey May 17 36 Last Survey Aug 5 38 19 40
 g. Book. 7260 on the Machinery of the Wood, Iron or Steel Swiss Re Ship BROOKLYN HEIGHTS (No. of Vessel) 18
 Gross 1030 Vessel built at Stockholm By whom Soderby & Soderby, Aktiebolaget Year. Month.
 Net 569 Engines made at " By whom Atlas Co. When 1917
 Nominal Horse Power " Boilers, when made (Main) (Donkey) 1926
 of Main Boilers 1 Owners Swiss Re American Ship Corp. Owners' Address 26 Broadway New York
 of Donkey Boilers 1 Managers " (if not already recorded in Appendix to Register Book.)
 Main Pressure " Port New York Voyage "
 Main Boilers 1200 If Surveyed Afloat or in Dry Dock Both, Sullivan Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

st Report No. " Port "

Particulars of Examination and Repairs (if any) Lme & S

Medical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the nature and extent of examinations and subsequent repairs. Repairs on account of damage (the cause of which must be stated) should be separated from repairs due to other causes; and sides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the names and initials of any letters respecting this case.

Damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined.

Is a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? Yes

Did the Surveyor personally go inside each Donkey Boiler separately and make a thorough examination at this time? Yes

Was a damage report made by anyone else? If so, by whom?

What parts of the Boilers could not be thus thoroughly examined?

What special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Latest date of internal examination of each boiler.

Did the Surveyor examine the Safety Valves of the Main Boiler?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?

Did the Surveyor examine the drain plugs of the Main Boilers?

Did the Surveyor examine all the mountings of the Main Boilers?

Has screw shaft now been drawn and examined? Yes Is it fitted with continuous liner? Yes

Has shaft now been changed? No If so, state reasons.

Has the shaft now fitted been previously used?

Latest date of examination of Screw Shaft 26/6/40

Engine parts, when referred to by numbers, should be counted from forward.

Did the Surveyor examine the generators, motors, switchgear, cables and fuses?

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms?

Is the Survey complete, state what arrangements have been made for its completion and what remains to be done. Complete.

Work done: Fuel found on dry dock. P.S. Tail Shaft drawn & examined & S. Sec. connections opened up & examined. Fastenings fixed.

S. main engine cylinders pistons rods, wrist pins & guides, heads & valves, including compressor & scavenging pump, and crank shaft examined. P.S.

tail & tunnel shafting examined. Steam & Diesel Generator cylinders, pistons rods, wrist pins & guides, cones, and valves, and crank shaft examined.

Steam Compressor cylinders pistons, rods, heads & valves & crank shaft examined.

lubricating oil, cooling water ballast, general service, bilge, fuel oil transfer & donkey boiler pumps examined. Starting tank, lub oil & donkey service tanks examined internally.

Hydraulic tank of 1500 lbs on high pressure air bottles applied by H.S. Dept.

General Observations, Opinion, and Recommendation: Bottles afterwards examined internally.

State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9.11, R.E.M.S. 9.11, & L.M. 9.11.

Machinery of this vessel is now in good working order and slightly over 10 years old.

and Lme 8.40. D.P.S. 8.40 and notation of Tail Shaft sec'd 0 7 6.40

Fee (per Section 29) \$215.00 Fees applied for 26-9-1940
 Damage or Repair Fee (if any) "
 Expenses (if chargeable) "
 Received by me, "

Committee's Minute

Signed See 1st Entry Report attached

H. Dwyer

Engineer Surveyor to Lloyd's Register of Shipping.

IR

Lloyd's Register
 Foundation

New York

"BROOKLYN HEIGHTS"

Cumulating arrangements examined. Electric installation examined and tested.

Returned to hydraulic test of 180 lbs and the donkey boiler and steam pipes applied by U.S. inspectors. The boiler was afterwards examined internally & externally & found in good condition, all mountings found good. Safety valves adjusted under steam to 120 lbs.

Miscellaneous machinery examined under working condition.

R.B.

Noted

For R.A. dme 840. NPS 840
Sb. 40 O.G.

Oil Region 2 to 4.

say 15 7/8 - 28 1/4

NHP 350.

NE 26.

NHP 26-120 1/2

Submitted the Surveyor
he asked the name of
the Oil retaining gland
under which it
received the
official approval

DA

14/12/40.



© 2020
Lloyd's Register
Foundation