

- 9 SEP 1953

LIVERPOOL

— "Colon" —

W.T. REPAIRS.

Rudder - All gudgeon bushes (steel) renewed.

2 pintles dressed up and 2 pintles ~~re~~ built up by electrically welding & machined on completion.

Rudder satisfactorily swung on completion of repairs.

Shell rubbing strake (P) - Fractured ^{EW} but cut out & rewelded.

Minor caulking & welding effected to stem plate edges P.S.

A few rivets caulked & ring welded in forward keel plate.

ENDORSEMENT Indented shell plts L6 & 7 & K3 (SSA) examined & found efficient.

Thos. J. Roberts :



© 2020

Lloyd's Register
Foundation

W1646 - 0019 2