

REPORT OF SURVEY FOR REPAIRS, &c., OF ENGINES AND BOILERS

Date of writing Report... 19... When handed in at Local Office... 3 SEP 1953... Port of... LIVERPOOL...
 No in Reg. Book. Survey held at Liverpool. Date. First Survey 6/8/53 Last Survey 28/8/53 19...
 6511 on the Machinery of the SS "COLON" Steel (No. of Visits 5)

Gross 1803 Vessel built at Liverpool. By whom H & C. Grayson Ltd. Year. Month. 1919 9
 Net 983 Engines made at -d0- By whom D. Rollo & Sons. When 1919
 As Per Rule 271 Boilers, when made (Main) 1919 (Donkey) - When 1919
 of Main Boilers 2 S Owners MacAndrews & Co. Ltd. Owners' Address...
 " " 5112 Managers... Port London.
 of Donkey Boilers - If Surveyed Afloat or in Dry Dock Langton Dry Dock Voyage...
 Main Pressure 180 (State name of Dock.)
 Main Boilers 180
 Donkey Boilers -

Particulars of Examination and Repairs (if any) Dkg. TS. Comp. BS. SRH.
 Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).
 HULL MACHINERY
*100A1 Shelter Dk. LMC.9.50.
with Fbd. 6.53 BS.5.52.
SS.LIV.10.46(Dr). TS.CL.4.52.
SS.LON.10.50.

Damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined.
 a damage report made by anyone else? If so, by whom?
 the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? Yes
 " " Donkey " " " "
 state for what reasons... What parts of the Boilers could not be thus thoroughly examined?
 special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?
 latest date of internal examination of each boiler Port 6/8/53
 the Surveyor examine the Safety Valves of the Main Boilers? Yes To what pressure were they afterwards adjusted under steam? Efficient 180 lb/sq. in.
 the Surveyor examine the Safety Valves of the Donkey Boilers? Yes To what pressure were they afterwards adjusted under steam? -
 the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? Yes and of the Donkey Boilers? -
 the Surveyor examine the drain plugs of the Main Boilers? None fitted. and of the Donkey Boilers? -
 the Surveyor examine all the mountings of the Main Boilers? Yes and of the Donkey Boilers? -
 the screw shaft now been drawn and examined? Yes Has it a continuous liner? Yes Is an approved oil retaining appliance fitted at the after end? -
 shaft now been changed? No If so, state reasons... Has the shaft now fitted been previously used? - Has it a continuous liner? -
 approved oil retaining appliance fitted at the after end? Yes State date of examination of Screw Shaft 6/8/53 State the wear down in the stern bush...
 Is electric light and/or power fitted? - If so, did the Surveyor examine the generators, motors, switchgear cables and fuses?
 the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms?
 ne parts, when referred to by numbers, should be counted from forward. Auxiliary machinery should be referred to by position in Machinery Space.

Survey is not complete, state what arrangements have been made for its completion and what remains to be done. Complete for Dkg. TS. BS. and SRH.
Done for Docking:- Vessel placed in dry dock. Propeller, stern bush & outside fastenings of sea connections examined and found satisfactory.
Done for Compl. BS:- The Port Boiler opened up and examined together with safety valves, mountings, manhole doors and fastenings. All found or placed in good condition. Subsequently both boilers examined under steam and their safety valves adjusted as above.
Done for S.R.H.:- Tail shaft and intermediate shaft removed ashore. Coupling flanges faced and edged in lathe. Subsequent installation alignment examined and found satisfactory. It is recommended that this item be now considered efficient and removed from the S.R. list.
Done for TS (CH):- The above item of S.R. necessitated drawing the Tail shaft and this opportunity was taken to examine same, and it was found satisfactory.
airs (W.S.) P. Boiler:- Minor repairs to mountings.
S. Boiler:- Safety valve springs renewed.

General Observations, Opinion, and Recommendation:-
 (State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, etc.)
The machinery of this vessel as now seen is in good condition and eligible in my opinion to remain as classed with fresh record now of BS. 7.53 as previously recommended. Notation now of "Tail shaft seen 8.53 (CH)" and without special condition attached to the 1-shaft coupling.

Survey Fee (per Section 23) Completion BS. 5
TS (CH) 3
SRH 4
 Special Repair Fee (if any) 4
 (per Section 23.)
 Travelling expenses (if chargeable) -
 Committee's Minute LIVERPOOL
 Assigned As now, without spl cond.
BS 7.53 TS 8.53
 Fees applied for, 3 SEP 1953
 Received by me, 8 SEP 1953
 Engineer Surveyor to Lloyd's Register of Shipping.
 Lloyd's Register Foundation

Noted
without the conditions

1679/53

182

[illegible]

Lloyd's Register
Foundation