

# REPORT OF SURVEY FOR REPAIRS, &c., OF ENGINES AND BOILERS

(Received at London Office 11 JAN 1947)

Date of writing Report 5/1/47 19 19 When handed in at Local Office 8/1/47 19 19 Port of NEWCASTLE-ON-TYNE

Survey held at Tyne Dock Date First Survey 19. 9. 46 Last Survey 3. 1. 1947  
(No. of Visits 3)

on the Machinery of the ~~Wood, Iron or Steel~~ S.T. 'Soranus'  
Gross 250 Vessel built at Selby By whom Cochrane & Sons When 1906 4  
Net 103 Engines made at Grimbsby By whom St. Central Coal, Eng & Ship Repairs & Co. When 1906  
Boilers, when made (Main) 1906 (Donkey) ✓  
Owners Northern Trawlers Ltd Owners' Address Port Grimbsby Voyage ✓  
Managers H. A. Bennett  
Main Boilers 180 lbs If Surveyed Afloat or in Dry Dock Afloat  
(State name of Dock.)

CHARACTER. for Special Survey Date of last Survey and of Periodical Surveys.	Years assigned now expired.	Machinery and Boiler Surveys (including date of N.B., if any).
<u>+ ...</u>		<u>+</u>
<u>6.10</u>		
<u>SPT Trawler</u>		
<u>Reclassification</u>		<u>Contemplated.</u>

Particulars of Examination and Repairs (if any) Re-class?

Medical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and details being detailed in the body of the report, should be briefly summarised at the end of the report. State also the names and initials of any letters respecting this case.

Damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined.

Is a damage report made by anyone else? If so, by whom? ✓

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? Yes

Did the Surveyor personally go inside each Donkey Boiler separately and make a thorough examination at this time? ✓

What parts of the Boilers could not be thus thoroughly examined? ✓

What special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? ✓

What was the latest date of internal examination of each boiler? 3. 1. 47

Did the Surveyor examine the Safety Valves of the Main Boiler? Yes To what pressures were they afterwards adjusted under steam? Not adjusted.

Did the Surveyor examine the Safety Valves of Donkey Boiler? ✓ To what pressure were they afterwards adjusted under steam? ✓

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? Yes and of the Donkey Boilers? ✓

Did the Surveyor examine the drain plugs of the Main Boilers? ✓ and of the Donkey Boilers? ✓

Did the Surveyor examine all the mountings of the Main Boilers? Yes and of the Donkey Boilers? ✓

Has the screw shaft now been drawn and examined? ✓ Is it fitted with continuous liner? ✓ Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? ✓

Has the shaft now fitted been previously used? ✓ Has it a continuous liner? ✓ Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? ✓

What was the date of examination of Screw Shaft? ✓ State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft. ✓

Did the Surveyor examine the generators, motors, switchgear, cables and fuses? ✓ Is electric light and/or power fitted? Yes

Was the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? ✓

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done. The remainder of the boiler requirements.

The vessel has now been laid up, pending a financial settlement with owners. In due course: Examined cylinders, pistons, valves, chest; Condenser internally; Main boiler internally. Repairs recommended: Condenser tubes clean, test & renew as necessary; HRD shafts done & renew; Main boiler, Comb. chamber top plate fire & after edges to be built up in way of girders & landings, several wasted rivets renew; girders stay renew as required. It is stated by the Owners' Rep. that it is intended to renew the screw shaft.

**SURVEY OF ELECTRICAL INSTALLATION.** Generator 1-7.5 K.W. The electrical installation has been completely stripped out. To complete the electrical survey all wiring to be installed, tested and found satisfactory.

**General Observations, Opinion, and Recommendation:** The machinery of the vessel, as far as is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9,11, B.M.S. 9,11, & L.M.C. 9,11, or 140 lb., F.D., &c.)  
The vessel is eligible in my opinion to be classed with rules of L.M.C. with date when survey is completed + of T.S. 1.46 C.C., as previously recommended.

Survey Fee (per Section 29) £ 7 : 0 : 0  
Special Damage or Repair Fee (if any) £ :  
NO LICENCE SUPERVISION.  
Travelling expenses (if chargeable) £ :

Fees Applied for 10 JAN 1947  
Received by me, 19

W. J. H. ...  
Engineer Surveyor to Lloyd's Register of Shipping.

Committee's Minute Deferred  
Assigned Deferred

WED. 29 JAN 1947



Insert Character of Ship and Machinery precisely as in the Register Book

Is a Certificate required? If so, to be sent to

Reclassification wrong, part held 1.46  
now advanced

The vessel has been laid up

It is submitted  
action be deferred.

J.S.

27-1-47.

*[Faint, mostly illegible handwritten text, possibly bleed-through from the reverse side of the page.]*

Please see page 12211 of volume 100

*[Faint handwritten notes and markings, including what appears to be a signature or initials.]*

