

Hall Trader

W179-0093

F.E.

Inspected by Chief Ship Surveyor 27. 2. 17.

Received from Chief Ship Surveyor

VESSEL'S NAME

Sheels Edith

Rpt.

Five

No. 696522

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. 44.33

Depth "d" 12.75

Framing: Table No. 3 page 10

Description Bulb Angle as approved.

Longitudinal No. 7890

Proportions $\frac{\text{Length}}{\text{Depth}} = 12.27$

Deck Sheerstrake as per Rule.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed * 100A.1. (Steel) as recommended.

* 100A.1. (Steel)

1 DK (Steel) Weld on.

Cell DB + 6' by 6'. FRT 606 A.P.T. 406

FK 4BH. Cen. Longitudinal. 292. B 15 F 18. 3. 2. 17.

It is concluded that D stroke of shell plating found of the half length umships is .36 in thickness and not .28 as would appear to be the case from the entry on the report is also that the plating on stem has been increased .02 as required by approved umship section.

Angles on upper edge
Spacing
BEAMS, Deck, Angle, Bulb Angle, Plate

Tie Plates
Deck. Material and thickness steel
Bridge Deck Stringer Plate, br'dth & thickness