

## Report of Survey for Repairs, &amp;c., of Engines and Boilers.

(Received at London Office 18 NOV 1941)

Date of writing Report Sept 27 1941 When handed in at Local Office Sept 28 1941 Port of New York  
 No. in Reg. Book 96400 Survey held at Mariners Harbor Date, First Survey Aug 4 Last Survey Aug 18 1941  
15705 on the Machinery of the Wood, Iron or Steel M.V. "INVERLEE" (No. of Visits 2)

Tonnage { Gross 9158 Vessel built at Kegonsch By whom Brown Vulkan Year. Month. 1938 3  
 Net 5496 Engines made at — By whom — When 1938  
 Nominal Horse Power 1001 Boilers, when made (Main) none (Donkey) 1938  
 No. of Main Boilers none Owners Mrs. Luchetti Owners' Address — When 1938  
 No. of Donkey Boilers 2 Managers A. Weir & Co (if not already recorded in Appendix to Register Book.)  
 Steam Pressure in Main Boilers — Port Flagst. Voyage —  
 in Donkey Boilers 180 If Surveyed Afloat or in Dry Dock Both  
 (State name of Dock.) Bethlehem (Sisco)

Last Report No. — Port —Particulars of Examination and Repairs (if any) Condition T.S.

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined.

Was a damage report made by anyone else? If so, by whom? noneDid the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? none" " Donkey " " Under steamIf this was not done, state for what reasons? —and what parts of the Boilers could not be thus thoroughly examined? —Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? —State latest date of internal examination of each boiler —Present condition of funnel(s) GoodDid the Surveyor examine the Safety Valves of the Main Boiler? noneTo what pressure were they afterwards adjusted under steam? —Did the Surveyor examine the Safety Valves of Donkey Boiler? —To what pressure were they afterwards adjusted under steam? —Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? noneand of the Donkey Boilers? —Did the Surveyor examine the drain plugs of the Main Boilers? —and of the Donkey Boilers? —Did the Surveyor examine all the mountings of the Main Boilers? noneand of the Donkey Boilers? —Has screw shaft now been drawn and examined? yesIs it fitted with continuous liner? yesIs an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? —Has shaft now been changed? — If so, state reasons —Has the shaft now fitted been previously used? —Has it a continuous liner? —Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? —State date of examination of Screw Shaft Aug 3

Engine parts, when referred to by numbers, should be counted from forward.

Is electric light and/or power fitted? —So, did the Surveyor examine the generators, motors, switchgear, cables and fuses? —Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? —If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done. none

none Vessel placed on drydock, propellers removed, tail shaft withdrawn  
 Examined, found in satisfactory condition & refitted

For M.C. main motor  
103 1 and 6 - cylinders, pistons, liners, valves, valve gears & covers Examined.

## General Observations, Opinion, and Recommendation:—

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9,11, B.E.M.S. 9,11, & L.M.C. 9,11, or L.M.C. 140 lb., F.D., &c.)

is in good order & eligible, in my opinion & remain as now classed with fresh record of M.C. when survey has been completed, and T.S. 8,41.

Survey Fee (per Section 29) £ 35  
 Special Damage or Repair Fee (if any) £ —  
 (per Section 29.)  
 Travelling expenses (if chargeable) £ —

Fees applied for

Sept 2 19 41

Received by me

Sept 26 19 41Committee's Minute NEW YORK 00 8 1941Assigned As nowT.S. 8,41.

M. L. Kinsale  
 Engineer Surveyor to Lloyd's Register of Shipping.

© 2019

Lloyd's Register Foundation

U6180-0006



Noted

*[Signature]*  
2/10/1911

*[Faint handwritten text, possibly a list or notes, mostly illegible due to fading.]*

*[Faint handwritten text, possibly a list or notes, mostly illegible due to fading.]*

*[Faint handwritten text, possibly a list or notes, mostly illegible due to fading.]*

*[Faint handwritten text, possibly a list or notes, mostly illegible due to fading.]*

*[Faint handwritten text, possibly a list or notes, mostly illegible due to fading.]*

*[Faint handwritten text, possibly a list or notes, mostly illegible due to fading.]*

*[Faint handwritten text, possibly a list or notes, mostly illegible due to fading.]*



© 2019

Lloyd's Register  
Foundation