

REC'D NEW YORK JAN 15 1923

Rpt. 8.

(Received at London Office)

MON. FEB. 4 1923

No. 4509

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 11th Jan 1923 When handed in at Local Office 11th Jan 1923 Port of Philadelphia.

No. in Survey held at Chester, Pa. Date, First Survey 11th Nov, 1922 Last Survey 5th Jan 1923
(No. of Visits 35.)

Reg. Book. 63258 on the Wood, Iron Steel S.S. "J.N. PEW" Master

TONNAGE:- Built at Chester, Pa. By whom Sun S.B. Co. YEAR. 1921
GROSS 9074 tons. FPT 100 ft. MONTH. 7
UNDER D.K. 8530 tons; APT 100 ft. Port belonging to Philadelphia.
NET 6473 feet; MT 100 tons.

Surveyed Afloat or in Dry Dock? Both Name of Dock Sun S.B. Co. Destined Voyage San Pedro.

WB=CellDBorDBa feet; ue&B feet; f feet; t feet;
total capacity tons. FPT tons; APT tons; MT feet tons.

N.B.—All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. L371 Port PHL

(Periodical Surveys, when held, must be reported in detail and *seriatim* in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.)

Damages cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined? Report made.

Was a damage report made by anyone else? If so, by whom? Salvage assu-

PAIRS, OR EXAMINATION AS PER RULE, FOR Damage stated to have been caused by an explosion of gas in N° 4 summer tank, port side, while the vessel was on the pontoon of the Sun S.B. Co., Chester, Pa., on the 11th Nov, 1922, for painting and minor repairs.

Now done:- Vessel on pontoon. Bottom and rudder examined. All main cargo & summer tanks, oil fuel tanks, cofferdams, pump room, forward cargo hold & tween decks, forecastle space, E & B spaces, fore and after peaks & tanks, and D.B. tanks in fore hold and under engines & boilers examined. Decks, masts, spars & general equipment; Hatchets & supports in position, ventilators & coamings, steering gear & connections, windlass and air & sounding pipes examined.

(Cont'd)

LIST OF DAMAGE REPAIRS :-	Plates.	TRANS. LONG.	R. Frames.	Floors.	BEAMS. LONG.	STR. PLATES.	DK. PLATES.	Other Items :-
Renewed	21	9 11			15 85	9	36	B. KEEL STR. ANGLES, SIDE GIRDERS, BRACKETS,
Removed and Fairied or Repaired	4	55	3 (DOUBLE)		22 90	3	1	C. L. & TRANS. BULK 2 nd EXP. TRUNK, HATCHES, MAST,
Fairied or Repaired in place	19			3	4		12	FA. GANGWAY, BRIDGE & BOAT DECK HOUSES, S. GEAR

GENERAL CONDITION OF THE	Good	Stringers	Good	Dblng. Plates under Sounding Pipes	Good	Copper, or F.M. of Wood Vessels	Pipes, FITTINGS, ETC.
Inner Bottom Plating	"	State if Tanks have been examined inside	"	Engine Room Skylights	"	(State if on Felt.)	
State if Tanks now tested	"	Bulkheads	Good	Coal Bunkers, Open'gs, Lids, &c.	"	When put on, Month	Year
Ceilings	"	Ceiling	"	Scuppers	"	Boats	Good
& Fastenings	"	Cement or Asphalt (State which.)	"	Cargo Hatchways	"	Masts, Yards, &c.	"
Plating	"	Rudder	"	Hatches	"	Condition, how ascertained	By examination
ing of ditto	"	Steering gear and its connections	"	Planking of Wood Vessels	"	(State if wedges removed)	/
ooks & Crutches	"	Windlass	"	Caulking	ditto	Sails	/
ms.	"	Have Pumps now been examined and found efficient?	None	Treenails	ditto	Equipment letter	E
e Frames	"	Have Sluice Valves now been examined and found efficient?	None	Breasthooks & Stemson	ditto	Anchors, No. of	38. 15. 1
is.	"	Have Watertight Doors now been examined and found efficient?	None	Transoms, Pointers, & Crutches	ditto	Cables (State if now ranged)	No

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—".....to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey 1,15," or "to remain as classed and to have record of survey 1,15, and the notations of ss No. 1-15 and PTND15, &c."

This vessel is eligible, in our opinion, to remain as classed and to have record of Survey 1,23.

Fee (per Section 28) £ : :

Damage or Repair Fee (if any) \$ 1500.00
for Sec. 29 Sunday fee \$ 10.00
ng Expenses (if chargeable) \$ 50.00

Surveyor's Fee (if any) £ : :

Fees applied for,

11th Jan 1923 906

Received by me,

29.1.1923 E. J. Evans. Marbets.

28/2

Surveyor to Lloyd's Register of Shipping.

No. Certificate required 2 My 60, to be sent to

Committee's Minute New York JAN 23 1923

Character Assigned

100A1
Shelter deck with floor
Carrying Pet in bulk
Fitted for oil fuel 7.21 F above 150°F



Lloyd's Register
Foundation
2019
W181-0075(17)

a.
of Philadelphia. Continuation of Report No. 4509 dated on the
S. S. "J. N. PEW."

Starboard verified.

DAMAGE REPAIRS.

Plates numbered from forward. Bulkheads & Transverses numbered from aft.

Shell. Port Side :- F₁₂, F₁₃, G₇, G₈, G₉, H₁₂, H₁₃, J₁₁, J₁₂, K₁₁, K₁₂, M₁₁, M₁₂ & M₁₃ (14 plates) renewed.

J₁₀ (1 plate) removed, fairied & replaced.

E₁₀, E₁₁, F₁₁, F₁₄, H₁₁, H₁₄, J₁₃ & K₁₃ (8 plates) fairied in place.

D₅, D₆ & E₄ (3 plates) and 2 lengths of bilge keel, indented in way of bilge blocks, fairied in place.

Starbd. Side :- F₁₂, F₁₃, G₇, G₈, H₁₂, J₁₁ & J₁₂ (7 plates) renewed.

D₁₁, E₁₀ & M₁₂ (3 plates) removed, fairied & replaced.

E₉, F₁₁, H₁₁, H₁₃, K₁₀, K₁₁, K₁₂ & M₁₁ (8 plates) fairied in place.

Shelter Deck. A is centre stroke & F is stringer plate.

Stringer Plates, Port Side :- F₉, F₁₀, F₁₁ & F₁₂ (4 plates) renewed.

F₁₃ (1 plate) removed, fairied & replaced.

Starbd. Side :- F₁₁ & F₁₂ (2 plates) removed, fairied & replaced.

Stringer angles part renewed on port & starbd sides.

Deck Plates :- A₁₀, A₁₁ & A₁₂ (3 plates) renewed.

A₉ (1 plate) fairied in place.

Port Side :- B₉, B₁₀, B₁₁, C₉, C₁₀, C₁₁, D₈, D₉, D₁₀, D₁₁, E₈, E₉ & E₁₀ (13 plates) renewed.

B₁₂, C₈, C₁₂, E₆, E₇ & E₁₁ (6 plates) fairied in place.

Starbd. Side :- B₁₀, B₁₁, C₉, C₁₀, D₉, D₁₀ & E₉ (7 plates) renewed.

E₈ (1 plate) removed, fairied & replaced.

B₉, C₁₁, D₈ & E₁₀ (4 plates) fairied in place.

Copper Deck. F is stringer plate.

Stringer Plates, Port Side :- F₁₁, F₁₂ & F₁₃ (3 plates) renewed.

Starbd. Side :- F₁₁ & F₁₂ (2 plates) renewed.

Stringer angles part renewed on port & starbd sides.

Deck Plates, Port Side :- D₉, D₁₀, D₁₁, D₁₂, D₁₃, E₇, E₈, E₉ & E₁₀ (9 plates) renewed.

Starbd. Side :- D₁₀, D₁₁, E₈ & E₉ (4 plates) renewed.


E₇ (1 plate) fairied in place.

Longitudinals & Brackets (Shell & Deck) and Transverses.

Main Tank, Port & Starbd. Sides.

Side girder (port side) plate between Bulkhead No. 27 & Transverse No. 28

© 2019



Lloyd's Register
Foundation

W181-0075(27)

Philadelphia. Continuation of Report No. H509 dated

on the

S. S. "J. N. PEW."

faired in place and top angles renewed.

Longitudinals to Shell:- 6 Pt. & 9 Sd. removed, faired & replaced.

-" - to Upper Dk:- 6 Pt. & 6 Sd. renewed.

-" - to Shelter Dk:- 5 Pt. & 5 Sd. renewed.

Brackets connecting Shell Roughs to Bulkds Nos 27 & 29:- 7 Pt. & 8 Sd. renewed. 2 Pt. & 2 Sd. removed, faired & replaced.

Brackets connecting Deck Roughs to Bulkds Nos 27 & 29:- 22 Pt. & 11 Sd. renewed.

Transverse Brackets connecting Expansion Trunk to Shelter Dk:- 4 Pt. & 3 Sd. renewed.

Transverse No 28, Port Side:- Upper Dk beam & knee and bracket to C.L. Bulkds renewed. Shelter Dk beam & knee and bracket to C.L. Bulkds renewed.

No 8 Main Tank, Port & Starbd. Sides.

Side girder (port side) plate between Bulkds Nos 25 & 27 renewed complete with top angles, vertical stiffeners & brackets.

Side girder (starbd. side) plate between Bulkds Nos 25 & Transverse No 26 renewed complete with top angles, vertical stiffeners & brackets.

Longitudinals to Shell:- 3 Pt. renewed. 5 Pt. & 8 Sd. removed, faired & replaced.

-" - to Upper Dk:- 6 Pt. & 6 Sd. renewed.

-" - to Shelter Dk:- 5 Pt. & 5 Sd. renewed.

Brackets connecting Shell Roughs to Bulkds Nos 25 & 27:- 28 Pt. & 16 Sd. renewed.

Brackets connecting Deck Roughs to Bulkds Nos 25 & 27:- 22 Pt. & 22 Sd. renewed.

Transverse Brackets connecting Expansion Trunk to Shelter Dk:- 4 Pt. & 4 Sd. renewed.

Transverse No 26, Pt & Sd:- Web frame & bilge bracket, upper deck beam & knee and brackets connecting beam and floor plate to C.L. Bulkds renewed.

Shelter deck beam & knee and bracket to C.L. Bulkds renewed.

Floor plate between brackets at bilge and C.L. Bulkds faired in place and double reverse bars on same removed, faired & replaced.

Vertical web stiffener on C.L. Bulkds (starbd. side only) renewed.

No 9 Main Tank, Port & Starbd. Sides.

Longitudinals to Shell:- 8 Pt. & 9 Sd. removed, faired & replaced.

-" - to Upper Dk:- 6 Pt. & 6 Sd. renewed.

-" - to Shelter Dk:- 5 Pt. renewed. 5 Sd. removed, faired & replaced.

Brackets connecting Shell Roughs to Bulkds Nos 23 & 25:- 23 Pt. & 9 Sd. renewed.

© 2019

Lloyd's Register
Foundation

14181 FOOT 75(317)

Philadelphia. Continuation of Report No. 4509 dated on the

S. S. "J. N. PEW."

Brackets connecting Deck Rongls to Bulkds Nos 23 & 25:- 22 Pt & 11 3d. renewed.

Transverse Brackets connecting Expansion Trunk to Shelter Dk:-
4 Pt. & 1 3d. renewed.

Transverse No. 24, Port Side:- Web frame & bilge bracket, upper deck beam & knee and bracket connecting beam to C.L.
Bulkd renewed.

Shelter deck beam & knee and bracket to C.L. Bulkd
renewed.

Floor plate between brackets at bilge and C.L. Bulkd
fairied in place and double reverse bars on same
removed, fairied & replaced.

Vertical web stiffener on C.L. Bulkd and bracket to upper
deck beam (starbd. side only) renewed.

10 Main Tank, Port Side.

Longitudinals to Shell:- 7 removed, fairied & replaced.

" to Upper Dk:- 6 renewed.

" to Shelter Dk:- 2 removed, fairied & replaced.

Brackets connecting Shell Rongls to Bulkd. No 23:- 6 renewed.

" Deck " " " ; - 11 renewed.

Transverse Brackets connecting Expansion Trunk to Shelter Dk:-
4 renewed.

13 Summer Tank, Port Side.

Longitudinals to Shell:- 1 removed, fairied & replaced.

" to Shelter Dk:- 2 part renewed. 4 fairied in place.

Brackets connecting Shell Rongls to Bulkd. No 29:- 14 renewed.

" Shelter Dk. " " " ; - 6 renewed.

Horizontal Brackets connecting Expansion Trunk to Bulkd. No 29:-
3 renewed.

14 Summer Tank, Port & Starbd. Sides.

Longitudinals to Shell:- 14 Pt & 2 3d. renewed. 2 3d. removed, fairied
& replaced.

" to Shelter Dk:- 6 Pt. & 6 3d. renewed.

Brackets connecting Shell Rongls to Bulkds Nos 25 & 29:- 8 Pt. & 14 3d. renewed.

" Shelter Dk " " " ; - 12 Pt & 6 3d. renewed.

Horizontal Brackets connecting Expansion Trunk to Bulkds Nos 25 & 29:-
6 Pt & 3 3d. renewed.

Transverses Nos 26, 27 & 28 Port and Nos 26 & 27 Starbd.:- Web frame,
shelter deck beam & knee and bracket connecting beam to
expansion trunk renewed.

5 Summer Tank, Port & Starbd. Sides.

Longitudinals to Shell:- 2 Pt. renewed. 2 Pt. removed, fairied & replaced.

" to Shelter Dk & 6 Pt. renewed.

Brackets connecting Shell Rongls to Bulkd. No 25:- 14 Pt. renewed.

2019

Lloyd's Register
Foundation

W181-0075(47)

S. S. "J. N. PEW."

Brackets connecting Shelter deck couple to Bulkhead No 25:- 6 Pt & 6 Sd. renewed.
Horizontal Brackets connecting Expansion Trunk to Bulkhead No 25:- 3 Pt. & 3 Sd.
renewed.

Transverse No 22, Port:- Bracket connecting shelter deck beam to
expansion trunk renewed.

—“— No 23, Port:- Bracket connecting web frame to upper deck,
shelter deck beam & knell and bracket connecting beam to expansion
trunk renewed.

—“— No 24, Port:- Web frame, shelter deck beam & knell
and bracket connecting beam to expansion
trunk renewed.

Centre Line Bulkhead.

Lower plates (Centre Girders) from Transverses Nos 24 to 28 renewed;
1 horizontal stiffener renewed and 2 horizontal stiffeners removed,
faired & replaced from Bulkhead Nos 23 to 27.

Bulkhead plating above centre girders and from Bulkheads Nos
23 to 27, including vertical plates at these bulkheads, renewed
complete with all horizontal stiffeners & brackets, shelf
plates & angles, shelter deck angles and vertical web stiff-
eners at Transverses Nos 24 & 26.

Between the vertical plates at Bulkheads Nos 27 & 29 the 3
upper horizontal strakes of plating removed, faired &
replaced and all horizontal stiffeners above centre
girders removed, 2 renewed and remainder faired & replaced.

Expansion Trunk Longitudinal Bulkheads.

Port Side:- Vertical plate at Bulkhead No 21 faired in place and all plating
and angles to upper & shelter decks from this plate forward
to and including the vertical plate at Bulkhead No 29 renewed.

Horizontal stiffeners from Bulkheads No 21 to 29 renewed
complete with all bracket connections at Bulkheads Nos 23, 25,
27 & 29. Vertical web stiffeners at Transverses Nos 24,
26 & 28 renewed.


Starboard Side:- Lower plate for about 11' 0" aft of vertical plate at
Bulkhead No 25 renewed. Vertical plate at Bulkhead No 25 and
all plating and angles to upper & shelter decks from this
plate forward to vertical plate at Bulkhead No 29 renewed.

Horizontal stiffeners from Bulkheads Nos 25 to 29 renewed
complete with all bracket connections at Bulkheads Nos 25 &
27. Vertical web stiffener at Transverse No 26 renewed.

Transverse Bulkheads in Main Tanks.

No 23, 25 & 27 Port side and Nos 25 & 27 Starboard side:-

All plating, boundary angles, horizontal stiffeners, vertical
web stiffeners & brackets, and angle or tee bar connect-
ions to brackets renewed.



© 2019

Lloyd's Register

K181 - 0075 (5/17)

S. S. "J. N. PEW."

No. 29, Port Side:- One vertical web stiffener & face angle removed, fairied & replaced. One vertical web stiffener plate fairied in place and face angle removed, fairied & replaced.

Transverse Bulkheads in Summer Tanks.

No. 25 & 29 Port Side and No. 25 Starbd. Side:- All plating, boundary angles, horizontal stiffeners, vertical web stiffeners & brackets, and angle bar connections to brackets renewed.

All cargo oil pipes, valves, rods & fittings, heating coils and mothering pipes in tanks overhauled, part renewed & tested.

T. Hatches.

Main Tanks:- Nos 8 & 9 Port and No. 8 Starbd. renewed complete.

Nos 9 & 10 Port and Nos 9 & 9 Starbd. removed, repaired & replaced with coaming angle to deck renewed.

Summer Tanks:- No. 4 Port renewed complete. No. 5 Port, coaming, deck angle, hinges, dobs & ventilator renewed, hatch cover refitted. No. 4 Starbd. removed, repaired & replaced with coaming angle to deck and hatch cover renewed.

Standards and lifting gear for hatch covers repaired & part renewed.

Mainmast:- Mast unshipped, lower mast plating part removed, fairied & replaced, foundation girders, plates & brackets to shelter deck renewed. Topmast & fittings, and all main rigging renewed and mast refitted. Ventilator extension from fuel oil line, led up mainmast, renewed complete with valves.

Aft & Aft Gangway from Bridge Deck to After Deckhouse:- Renewed complete for a length of about 100'-0" together with steering gear control rods, fuel oil, deck steam & exhaust, heater, sanitary, fire & fresh water pipes, valves & fittings.


at Deck, Port Side:- Stringer plate & angles, face plates, wood deck & covering boards, coaming stanchions & jackstays, handrails & stanchions part renewed. Port lifeboat repaired, boat cover and after Welin davit renewed. Wood deck recaulked & payed throughout.

Ridge Deck:- Wood deck recaulked & payed throughout.

Face plate at after end on port side fairied in place.

Midship Deckhouses:- Wood deckhouse on boat deck repaired & re fastened. Internal wood work & mouldings, doors & frames, fittings, compasses, telegraphs, telephones, indicators etc, repaired & part renewed.

After Deckhouse:- Wood deck over accommodation recaulked &



© 2019

Lloyd's Register
Foundation

XL181-0045(67)

Philadelphia

Continuation of Report No. 4509 dated

on the

S. S. "J. N. PEW."

painted throughout.

Upper Deck:- Rails & stanchions, mooring bits, fairleads, scuppers and minor deck fittings repaired & part renewed. All oil, steam & water pipes with their fittings overhauled, repaired & tested. One steam winch at mainmast renewed and other winches overhauled.

Ladders to main & summer tanks, and to bridge deck repaired and renewed.

Cielight glasses in crew's quarters renewed where broken.

Trollies installation overhauled & aerials renewed.

Painting and caulking throughout vessel tested, all started rivets renewed and caulking made good.

All removals in way of repairs replaced & made good.

On completion of repairs all main cargo tanks, summer tanks, cofferdams, oil fuel tanks, fore & aft peak tanks and P.B. tanks in fore hold and under engine & boilers tested under pressure as per Rules for new vessels.

Bottom cleaned & recoated and all new & repaired work coated as before.

Alterations:- O.T. Bulkhead fitted in No.1 summer tank (port & starb'd) over main transverse Bulkhd No.42 dividing these tanks into two sections. O.T. Hatch 32" high x 20" dia. fitted to each forward section.

E. J. Evans. Marrett.

© 2019



Lloyd's Register
W181-F0015(217D)