

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report June 1 1942 When handed in at Local Office June 1 1942 Port of New York.
No. in Reg. Book. Survey held at Brooklyn, New York Date, First Survey 11th May Last Survey 14th May 1942.
28123 on the Wood, Iron or Steel S.S. "MARGOT" (No. of Visits FOUR)

TONNAGE:— Built at Port Glasgow By whom J. & W. G. Ltd When 1926 12
GROSS 4545 Owners Valmar S.S. Co. Ltd Owners' Address —
UNDER DECK 4303 Managers Kaye Son & Co. Ltd (if not already recorded in Appendix to Register Book).
NET 2917 Port belonging to London

Surveyed Afloat or in Dry Dock? Afloat Name of Dock — Destined Voyage —
Cell DBor DBa — feet; uE&B — feet; f — feet
total capacity — tons. FPT — tons; APT — tons; MT — feet — tons.

Only alterations in the existing records of tanks should be inserted.

N.B.—All alterations in the existing records should be underlined.

Last Report, No. 117595. Port Liv.

(Periodical Surveys, when held, must be reported in detail and verbatim in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes, and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined. Not required. Society's Freeboard (if assigned) as painted on Ship and now verified — ft. — ins.

Was a damage report made by anyone else? if so, by whom? —

REPAIRS, OR EXAMINATION AS PER RULE, FOR Damage stated to have been sustained by grounding in Cape Cod Canal on 8th May 1942 on a voyage from Halifax to New York.

Now Done Soundings of tanks & bilges taken; also examined records of soundings & found no evidence of leakage.

No. 2 Hold. Bilge suction closing lengths of No. 1 Hold bilge port & starboard renewed at No. 2 hold after bulkhead.

Bilge suction closing length of No. 1 Hold Bilge port renewed at No. 2 Hold forward bulkhead.

Bilge suction closing length of No. 1 Hold Bilge starboard repaired at No. 2 Hold forward bulkhead.

SUMMARY OF DAMAGE REPAIRS:—
Renewed —
Removed and Falsed or Repaired —
Falsed or Repaired in place —

PRESENT CONDITION OF THE
Decks — Bulkheads — Engine Room Skylights — Copper, or Y.M. (State if on felt.)
Caulking of Decks — Ceiling — Coal Bunkers, Openings, Covers, &c. — When fitted, Month — Year —
Coamings — Cement or Asphalt — Bunkers — Boats —
Beams & Fastenings — Rudder — Scuppers — Masts, Yards, &c. —
Outside Plating — Steering gear and its connections — Cargo Hatchways — Condition, how ascertained (State if wedges removed.)
Frames — Have pumps been examined and found efficient? — Hatches — Equipment letter —
Reverse Frames — Have Bilge Valves been examined and found efficient? — Caulking — Anchors, No. of —
Longitudinals — Have Watertight Doors been examined and found efficient? — Treeneals — Cables (State if now ranged) —
Transverses — Have Ventilators and their Coamings been examined and found efficient? — Breasthooks & Stenson — " length — mean diameter —
Floors — Have Waterlight Doors been examined and found efficient? — Transoms, Pointers & Crutches — " Rule length — size —
Keelsons — Have Ventilators and their Coamings been examined and found efficient? — Timbers of Frame at openings — Chain Locker —
Stringers — Have Ventilators and their Coamings been examined and found efficient? — Stringers, Clamps & Shelves — Hawseers & Warps —
Inner Bottom Plating — Have the Tanks been examined internally? — Air and Sounding Pipes — Standing and Running Rigging —
Have the Tanks been tested? — Doubling Plates under Sounding Pipes — Salting (State if examined.) — Sails —

General Observations, Opinion as to Class, Recommendation, &c. —

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

This vessel is in good condition & eligible in my opinion to remain as classed without fresh record of survey, subject to bottom plating being specially examined at next dry docking, also subject to frame brackets etc. (S.S.) in boiler room, fidley & boiler room bulkheads (Port, Starboard and Ford) P.T.O.

Survey Fee (per Section 29) £ : :
Special Damage or Repair Fee (if any) (per Sec. 29) \$30. : :
Travelling Expenses (if chargeable) £ : :
Second Surveyor's Fee (if any) £ : :
Fees applied for, May 19 1942
Received by me, June 1 1942

Surveyor to Lloyd's Register of Shipping.

Committee's Minute

Character Assigned

Deferred for Dry Docking (Grounding)

Lloyd's Register Foundation

W194-0148

Contd.

17

Task

must be in

Y.S.D.

.....

.....

When And

ANCHORS.	
TEST	WEIGHT REQUIRED

1. The first step is to identify the problem or question that needs to be answered. This involves understanding the context and the specific requirements of the task.

*When a bo

CHAIN CABLES.

1944

Iron Stream Chain
10 or Steel Wire...

less, state Mechanical Test.