

# Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

27 FEB 1942

of writing Report 19... When handed in at Local Office 19... Port of New York  
 Survey held at Manhattan Harbor, N.Y. Date, First Survey Dec 9 Last Survey Dec 30 1941  
 on the Machinery of the Wood, Iron or Steel T.C.M.V. "PERSEPHONE" (No. of Visits 2)

Gross 8426 Vessel built at Kiel By whom Fid Knuff When 1925 5  
 Net 1414 Engines made at Delto By whom Delto When " "  
905 Boilers, when made (Main) here (Donkey) 1925  
 Owners Panama Transport Co Owners' Address  
 (if not already recorded in Appendix to Register Book.)  
 Managers Panama Port Panama Voyage  
 If Surveyed Afloat or in Dry Dock Both Particulars of Classification (which must be inserted  
 (State name of Dock.) Bethlehem Steel Co precisely as in Register Book & Supplements).

CHARACTER # for Special Survey Date of last Survey and of Periodical Surveys.	Years assigned now expired.	Machinery and Boiler Surveys (including date of N.B., if any)
<u>F 100 A 1, 8, 20</u>		<u>F LMC Cl.</u>
<u>with 7/13/41 - 1/1/42</u>	<u>5.41</u>	<u>1/27-11-40</u>
<u>S. Haw N-2-11-37</u>		<u>Cl P-7-39,</u>
		<u>8-10-40</u>
<u>Cylinder let out</u>		<u>DA 16-40</u>
<u>and Bulk</u>		

Report No. \_\_\_\_\_ Port \_\_\_\_\_  
 Particulars of Examination and Repairs (if any) Condition  
 Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the  
 Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on  
 of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and  
 being detailed in the body of the report, should be briefly summarised at the end of the report. State also the  
 initials of any letters respecting this case.

cases where the Surveyor has not made a special damage report he is required to state whether he  
 had his services for this purpose, and why they were declined.   
 damage report made by anyone else? If so, by whom?   
 Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? None  
 " " Donkey " " Yes

not done, state for what reasons?   
 parts of the Boilers could not be thus thoroughly examined?   
 special means, in the absence of internal examination, were adopted by the  
 Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?   
 date of internal examination of each boiler Dec 11 1941 Present condition of funnel(s) Good

Surveyor examine the Safety Valves of the Main Boiler? none To what pressure were they afterwards adjusted under steam? none  
 Surveyor examine the Safety Valves of Donkey Boiler? yes To what pressure were they afterwards adjusted under steam? 3-200 lb  
3-70 lb  
 Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? none and of the Donkey Boilers? yes  
 Surveyor examine the drain plugs of the Main Boilers? none and of the Donkey Boilers? yes  
 Surveyor examine all the mountings of the Main Boilers? none and of the Donkey Boilers? yes

shaft now been drawn and examined? no Is it fitted with continuous liner?  Is an approved appliance fitted at the after end of  
 the shaft to permit of it being efficiently lubricated?   
 now been changed?  If so, state reasons

shaft now fitted been previously used?  Has it a continuous liner?  Is an approved appliance fitted at the after end of  
 the shaft to permit of it being efficiently lubricated?   
 of examination of Screw Shaft  State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft 1/16  
 fine parts, when referred to by numbers, should be counted from forward.  Is electric light and/or power fitted? yes

the Surveyor examine the generators, motors, switchgear, cables and fuses?   
 insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms?   
 survey is not complete, state what arrangements have been made for its completion and what remains to be done

None! Vessel placed on hydroch, Propellers and other sea fastenings  
checked & found in good order placed in good order.  
Boilers examined internally & externally with mounting, steam pipes & tubes  
by hydrostatic pressure & same found in good order.  
Styrakes were adjusted under steam at pressures noted above.  
Fuel oil installation with piping valves and deck controls was  
examined under working conditions & found to be satisfactory.

for examination the following was effected:  
Main Motor N-2-1-374 Cylinder fitting, valves, valve parts & valves examined  
 Observations, Opinion, and Recommendation: - Continued on Page 2  
 clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also  
 any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9.11, B.G.M.S. 9.11, L.M.C. 9.11, or  
 L.M.C. 140 lb., F.D., &c.)

CS 3,34  
 machinery of this vessel is in good order & eligible in my  
 opinion to remain as now classed with fuel record of F LMC Cl.  
 the date when survey is completed and signed 12-41

Fee (per Section 29) 90 : : Fees applied for Jan 22 1942  
 Damage or Repair Fee (if any) 0 : :  
 (per Section 29.)  
 Expenses (if chargeable) 0 : :  
 Received by me, [Signature]  
 19

Committee's Minute \_\_\_\_\_  
 signed As above  
D. B. S. 12, 41.  
 NEW YORK JAN 21 1942  
 Lloyd's Register  
 Foundation  
 W207-0076(112)

Insert Character of Ship and Machinery precisely as in the Register Book

Is a Certificate required? If so, to be sent to

"Persephone"

Continued from page I.

Port main motor No 1 Connecting rod & Top End

Shot = main motor

No 2 Cylinder piston, rings, valves, & cover examined

No 4 Connecting rod & Top End.

Port main motor Lubricating oil pump.

Repairs - Adjustments & renewals to main motors and auxiliaries where necessary were effected. 2 Spare main motor pistons were taken to shop; overhauled & repaired on board following tests.

Boiler repairs Port Gas Boiler - all tubes were renewed

The main & auxiliary machinery were examined under working conditions and found to be in satisfactory order.

M.L.



© 2019

Lloyd's Register  
Foundation

W 207-0076(22)

