

# Report of Survey for Repairs, &c., of Engines and Boilers.

Date of writing Report	May 31 <sup>st</sup>	1941	When handed in at Local Office	June 9	1941	Received at London Office	23 JUL 1941
No. in Book. 2570.	Survey held at Brooklyn New York			Date, First Survey April 24 <sup>th</sup> 1941			Last Survey May 8 <sup>th</sup> 1941
on the Machinery of the Wood, Iron or Steel Steamship "CORMORA"							(No. of Visits) 4.
Gross Tons	6768	Net Tons	3976	Vessel built at Kiel, Germany. By whom Howaldtswerke	When 1937	Year. Month.	
Engine Power of Main Boilers	550	Engines made at Berlin Tegel.	By whom Rhinemetall Bochum	When 1937			
of Donkey Boilers	345	Boilers, when made (Main)	1934	(Donkey)			
Main Boilers in Pressure	228.	Owners Standard Transportation Co. Ltd.	Owners' Address	as given			
Donkey Boilers		Managers	Port London Voyage				
If Surveyed Afloat or in Dry Dock	Afloat - (State name of Dock)	Roman dry dock					

1st Report No. ✓ Port /

Particulars of Examination and Repairs (if any) Dr LMC.

*Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and des being detailed in the body of the report, should be briefly summarised at the end of the report. State also the date and initials of any letters respecting this case.*

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined ✓

Was a damage report made by anyone else? If so, by whom? ✓

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? ✓

Donkey " " "

Was not done, state for what reasons?

What parts of the Boilers could not be thus thoroughly examined?

What special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Latest date of internal examination of each boiler Post April 24<sup>th</sup>, Sat 8<sup>th</sup> May 2<sup>nd</sup>

Present condition of funnel(s)

Good.

Did the Surveyor examine the Safety Valves of the Main Boiler?

Yes.

To what pressure were they afterwards adjusted under steam?

228.

Did the Surveyor examine the Safety Valves of Donkey Boiler?

✓

To what pressure were they afterwards adjusted under steam?

✓

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?

✓

, and of the Donkey Boilers?

✓

Did the Surveyor examine the drain plugs of the Main Boilers?

✓

, and of the Donkey Boilers?

✓

Did the Surveyor examine all the mountings of the Main Boilers?

✓

, and of the Donkey Boilers?

✓

Has the screw shaft now been drawn and examined?

No

Is it fitted with continuous liner?

✓

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

✓

Has the screw shaft now been changed? If so, state reasons.

✓

✓

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

✓

Has the screw shaft now been previously used?

✓

Has it a continuous liner?

✓

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

✓

State of examination of Screw Shaft

✓

State the distance between lignum vitæ or bearing metal of stern bush and top of after bearing of screw shaft

Vessel aft.

Engine parts, when referred to by numbers, should be counted from forward.

Is electric light and/or power fitted?

✓

Did the Surveyor examine the generators, motors, switchgear, cables and fuses?

✓

Was the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms?

✓

Survey is not complete, state what arrangements have been made for its completion and what remains to be done.

*To complete the Special General Survey of Machinery for 2<sup>nd</sup> Line All Sea valves, Pumping arrangement, Propeller, Stem bush & all fastenings remain for examination*

## Special General (S.G.N.G.) Survey of Machinery.

All Cylinders removed from Main Engines, the cylinders, steam (gaskets etc) Seats, covers, Pistons with rings, valves, fittings, all Rods, Spindles and the Gear Compartments, Rameder through boat, all crossheads, Guide shoes and Guide Rammer together with all top & bottom end braces. All main bearings, to thrust carriage also spring bearings Rammer compartments with several Observations, Opinion, and Recommendation:

State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9,11, B&M.S. 9,11,  $\pm$  L.M.C. 9,11, or  $\pm$  E.M.C. 140 lb. F.D., &c.

CS 8,34.

Machinery Eligible to lay a claim to remain as now intact & if recommended that the record of E.L.M.C. (including boilers) 5/14/41 be made in Register Book when all sea valves, Pumping arrangement, Propeller, stem bush & all fastenings remain

Fee (per Section 29) L.M.C. £ 130. Fees applied for JUN 12 1941

Damage or Repair Fee (if any) (per Section 29) Boilers £ 45. Received by me,

ing expenses (if chargeable) £ : : 19

Committee's Minute NEW YORK JUN 11 1941

Signed As now B.S. 5,41.

lastly held.

A. W. Goodale & C. J. Astor

Engineer Surveyor to Lloyd's Register of Shipping.

Lloyd's Register Foundation

(1/2) W21-0201

S.S. 'Combra'.

Main cross shaft, thrust shaft & line section. Main & auxiliary Condensers examined & tested. All main & auxiliary attacked and independent pumps inclusive of Air, feed, bilge, ballast, circulating, transfer, oil fuel, fuel service, fresh water & Sewage pumps opened & examined through boat. Electric circuits & generating sets examined also feed tanks & evaporation.

Boilers:— Three main boilers opened cleaned & examined through boat with all mountings, steam pipes & fittings. All accessories (Circular N° 1748) tested under working conditions, air fuel service pumps opened & examined as aforementioned, the controls for fuel & steam distribution systems examined with valves, oil discharge pipes etc. now satisfactory. Safety valves adjusted under steam.

Repairs - MaKaal:— LD Engine cross shaft overhauled & adjusted. All Doppel Steam valves removed overhauled, ground in & two stems with bushings renewed. The HD piston rod removed, stuffing box reconditioned & rejoined. Main valve gear overhauled & adjusted. Both Condensers overhauled, tested & proven efficient with several tubes renewed & water tube & door specially treated. Main engine thrust Governor gear reconditioned with parts new & brackets renewed. Auxiliaries overhauled, glands replaced, the General Service pump, with bilge & fuel oil service pumps reconditioned with new fittings as required. The Main Heavy Cargo & Slipper pumps overhauled & new parts fitted. Several valves & fittings in the steam, water & air ranges reconditioned. Electric Generating sets overhauled, installation neccessary all tested out under working conditions. Several new steam fittings installed and an inspection drain tank in boiler room, accessibility located, with larger cover gauge glasses, Scumpan, drain & bilges & ejector connections, discharge etc. Boilers:— All boilers especially cleaned, several, smoke & air Lentz tubes renewed & stay bolts in fire & watertubes overhauled. Superheater drain fittings with Leader joints & elements renewed. All mountings reconditioned, all fire tube beach boiler renewed (9) with steel fittings also some top part of drain pipe & fittings renewed. Coal blowers reconditioned with parts renewed.

C/S.



© 2019

Lloyd's Register  
Foundation

1020-12M (2/2)

S.S. No 1 due 7-4-1  
new part need

Hobart

*Liu*  
5.8.41

© 2019

# Lloyd's Register Foundation