

14 JUL 43

**COPY**No. **1**

17

17086

- 2 JUL 1943

Sydney, N. S. W.

31464

20521

8789  
7697  
5015

Sydney N.S.W.

T.S.S. **PORT HUCKLAND** "Belfast -  
C. - dme Ld.

abst

23/7/42

Workman Clark &amp; Co. Ltd.

25/7/42

1932 - 3

London

4110

c/s.w.

00 A1 +1MC  
 Shallow water float  
 12/7/42 NSW. MS 10,35  
 51 km 203 - 6,34 BS 51115.42  
 55 km 201 - 88 T.S. ab 12,40  
 Tonnage opening  
 closed 241 (W.E.).

K

### Examination of Hull Repairs and Repair Schedule etc.

(Damage Report dated 29/7/42 - ~~joined~~)

At the request of Lloyds Agents & with the consent of the Owners, examined the temporary repairs carried out at Southampton, about June 1942 (see Southampton Surveyors Cert. dated 26/6/42) and recommended repairs to insulation etc. alleged to have been damaged as a result of the collision. In consequence of the shortage of refrigerated cargo space, it was desired to proceed with the repairs necessary to enable the vessel to carry refrigerated cargo in the forward holds. At the time it was convenient to commence repairs in the holds, no dry dock was available for the purpose of making an examination of the vessel, but an examination of the hull was

P.W.C.

Journey work back to the above

This vessel, as far as seen, is now in good condition - eligible in my opinion to remain as charred, subject to indicated plating (port side) & 35 ft. forward (starboard side), permanent repair abroad forward end of No 2 hatch as owners convenience & to plating etc in way of No 2 hold deck platings (collision) at owners convenience

31-10-0 29/7/42

FRI. 23 JUL 1943

As now  
Subject:

(flag) for C. S. L.

W210-0150



© 2020  
 Lloyd's Register  
 Foundation

made internally & externally as far as possible, in order to determine whether further repairs were considered necessary to the hull. This survey was made whilst the vessel was at sea in Sydney Harbour and the re-carried out at Southampton were found sufficient and in my opinion permanent repairs to shell plating etc may be deferred until the Owners convenience.

The insulation of No 2 Hold (which is not classed) & the brass piping in Nos 1, 2 & 3 holds & the No 4 tween decks were dealt with as detailed in the attached damage report

(Sgd) Jas C. Rustine.

