

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME *Stat S.S. 'GEMMA'*

Rpt. *Rot*

No. *12167*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

Transverse No. *91.50*

Depth "d" *17.75*

Framing: Table No. *3*

Description *Bull-angle as approved*

Longitudinal No. *41175*

Shelter

Proportions Length = *11.39*
Depth =

Deck Sheerstrake *as approved*

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed *100.A-1. (Stat)* "Shelter Deck with freeboard," as recommended. The Summer freeboard of *9' 10 1/2"* from centre of disc to top of statutory deck line at *Shelter* deck, now marked on the vessel's sides, to be inserted in the classification certificate, and recorded in the Register Book, and further, the remaining freeboards, as shown on the accompanying verification form to be inserted in the certificate of classification.

2 Dks (Stat) ✓ Shelter Dk (Stat)

*Cell Dks 369' 1399t, ITa 33' 665t, FPT 160t, APT 163t,
FK, 3BH to Shelter Dk, ABH to upper Dk, pt Cam Lights A. Ch.*

It is concluded that the Collision bulkhead extends to the Shelter Deck but the Surveyors should be requested to state if this is so and the numbers of bulkheads extending to the upper deck and to the Shelter Dk; they should also state whether the inner surface of the bottom plate clear of the oil tanks is protected by Cement

BEAMS, BRIDGE DECK, ANGLE, DUAL ANGLE, TEE BULB OR CHANNEL

Angles on upper edge

Tie Plates
Deck. Material and thickness

4214-0181