

pt. 9.

No. 116979.

REPORT OF SURVEY FOR REPAIRS, &c., OF ENGINES AND BOILERS

(Received at London Office.)

26 NOV 1941

When handed in at Local Office 19 NOV 1941 Port of LIVERPOOL

Survey held at Liverpool & Birkdale Date. First Survey 23/3/41 Last Survey 15/11/41
(No. of Visits 44.)

1298 on the Machinery of the Wood, Iron or Steel TWIN SC TACOMA STAR.

Year. Month.

Gross	7924	Vessel built at	Belfast	By whom	Workman-blair & son	When	1919
Net	4962	Engines made at	-do-	By whom	-do-	When	1919
Final se Power	1138	Boilers, when made (Main)	1919		(Donkey)		
of Main Boilers	3DR	Owners	Fredrick dyland & son	Owners' Address		Port	London.
of Donkey Boilers	✓	Managers		Port		Voyage	
Main Pressure	250	If Surveyed Afloat or in Dry Dock	Canada Id B.P.W.D.	Particulars of Classification (which must be inserted (State name of Dock.)			
Main Boilers	✓		Beller Id. Mercantile D. + Canada Id.				
Donkey Boilers	✓						

First Report No. Port Ige

Particulars of Examination and Repairs (if any) + LMC + TS.

Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the use of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and sides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined.

Is a damage report made by anyone else? If so, by whom?

Does the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? Yes

Donkey " "

This was not done, state for what reasons

What parts of the Boilers could not be thus thoroughly examined?

What special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

The latest date of internal examination of each boiler CASB 17-8-41 PB 19-9-41 Present condition of funnel, good.

Does the Surveyor examine the Safety Valves of the Main Boiler? Yes To what pressure were they afterwards adjusted under steam? 200 lb/ft²

Does the Surveyor examine the Safety Valves of Donkey Boiler? ✓ To what pressure were they afterwards adjusted under steam? ✓

Does the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? ✓ , and of the Donkey Boilers? ✓

Does the Surveyor examine the drain plugs of the Main Boilers? ✓ , and of the Donkey Boilers? ✓

Does the Surveyor examine all the mountings of the Main Boilers? Yes , and of the Donkey Boilers? ✓

Has the screw shaft now been drawn and examined? P.S.Y. Is it fitted with continuous liner? Yes Is an approved appliance fitted at the after end of the shaft to permit of its being efficiently lubricated? ✓

Has the shaft now been changed? No If so, state reasons. ✓

Has the shaft now fitted been previously used? P.S. 13-6-41 Has it a continuous liner? ✓ Is an approved appliance fitted at the after end of the shaft to permit of its being efficiently lubricated? ✓

State date of examination of Screw shaft. P.S. 26-10-41 State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft. Blow fit

Engine parts, when referred to by numbers, should be counted from forward.

Did the Surveyor examine the generators, motors, switchgear, cables and fuses? Yes Is electric light and/or power fitted yes

Was the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? Yes

Is the Survey not complete, state what arrangements have been made for its completion and what remains to be done. Complete.

How Done - Thrush placed in dry dock, propellers affixed to screw shafts, & fastenings of all sea connectors examined & found satisfactory

Boiler Repairs & I.M.C. - Examined the port boiler throughout with mounting doors & fastenings. The four low furnaces were found conforming & watertight along line of fire bars, these now removed & four new furnaces fitted. Identification marks checked & verified as per attached certificate. Boiler tubes found to be thin & leaking, all plain & stay tubes in this boiler now renewed & now growing on back tube plates between vertical rows of margin tubes, now leaded out & built up electrically. T.T.O.

General Observations, Opinion, and Recommendation: The machinery of the vessel is in

(State clearly what alteration, if any, is required to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9/II, B.D.M.S. 9/II, 2/2 L.M.C. 9/II, or 2/2 S.S. 9/II.)

General Observations, Opinion, and Recommendation: The machinery of the vessel is in a good & efficient condition & eligible in our opinion to remain classified with Fleet record of LMC 11-41, TS(C) P+S 10-41. Subject to the all engine heatplate repairs being examined before October 1942. & the all engine HP valve casing repair being examined before the end of May 1942.

Survey Fee (per Section 29) LMC £15.0.0

Special Damage - Repair Fee (if any) £15.0.0

Electrical Damage After £55.0.0

Electrical Survey £4.0.0

Commissioner's Minute L.I.C. 25 NOV 1941

Issued L.M.C. 11-41 Subject T.S. 10-41

CERTIFICATE WRITTEN 25 NOV 1941

W223-0067 (117)

Insert Character of ship and Machinery precisely as in the Register Book

Certificate required to be sent to

Lloyd's Register Foundation

15/11/41.

on the

TWIN SC TACOMA STAR

Boiler Repairs (cont.):- Some warpage was noted along the line of fire bars of the fore & after wing furnaces, warpage cleaned clean & furnaces built up electrically.

Sundry minor caulking & stay nut repairs carried out, on completion of boiler repairs the boiler hydrostatically tested & found satisfactory.

Machinery Repairs:- Temporary repairs to the starboard engine H.P. inboard cylinder lost have now been carried out by means of suitable plate patches & strong backs & found satisfactory. Sundry minor voyage repairs effected.

Damage:-

Having the completion of the above repairs, the vessel is stated to have sustained damage by enemy bombing. The bomb exploding in the after starboard side of the lower tween deck bunker whilst vessel lying in West Canada Dock on 3rd May 1941. The vessel partly submerged & engineroom flooded.

How Done for Damage & Damage Repairs:-


Kessel placed in dry dock, propellers, stem tubes sea cocks & valves, & other fastenings examined.

Pont & Starboard screw shafts drawn & examined, stem tubes newrodded.

The Pont & Starboard main engines with attached pumps completely opened up for cleaning & examination. Crank shafts lifted cleaned & examined, thrust & intermediate shafting opened up & exposed for cleaning & examined. All auxiliary machinery & condensers, steering engine opened up cleaned & examined. All engine room plating removed, engine bedplates & pipe lines cleaned & examined for fractures. All lagging removed from steam cylinders & steam piping for examination.

All boiler cradles & fastenings examined. lagging removed as required.

Damage Repairs:- The starboard main engine bedplate found fractured in way of M.P & L.P front column landing & horizontal fracture at no 6 main bearing girder. The bedplate in way of these fractures now reinforced by means of suitable boundary stiff plating, fastening bolts & screw stays, & long tie bolts extending from column fastening through bedplate fastening & tank top. These repairs have been efficiently carried out & considered efficient & satisfactory. It was recommended that the old bed plate repairs be specially examined before October 1942.



© 2019

Lloyd's Register
Foundation

15/11/41

on the

TWIN SC TACOMA STAR.

Damage Repairs (cont) :- The starboard engine H.P + I.P. cylinders cracked, now renewed, H.P front & back columns cracked through fastenings, now renewed, I.P. back column cracked now renewed, H.P quadrant bracket & intermediate stop valve cracked now renewed.

Boring reports of cylinders & stop valve attached.

M.P. piston rods bent & pitted due to immersion now renewed.

Forging report attached.

M.P. valve spindle bent & pitted, sent to engine makers & reconditioned

H.P + I.P. piston rods pitted, now skimmed & new gland & neck bushes fitted.

H.P expansion crack & fractured & damaged now renewed.

H.P ahead guide shoe white metal cracked, now remetalled.

M.P. Impulse valve & tee piece connection fractured now renewed.

Port Engine :- All piston rods pitted due to immersion, now skimmed & new neck & gland bushes fitted.

M.P. crank pin white metal brasses cracked now remetalled.

All main engine soldering down bolts hardened up & renewed as found necessary.

Attached Main Engine Pumps :- The starboard engine feed, sanitary, air & bilge pump vans placed in both lines for truth, skimmed & new neck & gland bushes fitted. After feed pump suc & sol valves elect. fractured, now renewed. Air pump C.I. suction pipe from condenser, fractured now renewed. Air pump tail valve fractured now renewed.

Auxiliary machinery :- All auxiliary machinery opened up cleaned examined & overhauled.

Port & Starboard condensers & auxiliary condenser opened up cleaned & tested.


Star condenser forward door fractured by explosion now renewed & about 200 damaged tubes & ferrules renewed, & four damaged G.h. through stays renewed.

G.I. pump (star side) badly damaged, now renewed complete makers Maywood & Taylor & Co. 9½ x 7 x 21. L. 385-85, also suction & delivery valve boxes renewed.

Star side Fan engine, casing & framework damaged. Fan engine now renewed complete with casing, framework through engine room & staterooms (James Howden & Co. Fan L. 814-75-).

Ford evaporator (star side) casing fractured, now renewed.

Andrew & Cameron & Co L. 1584



Lloyd's Register
Foundation

TWIN SC TACOMA STAR.

Damage Repairs (Cont.) :- Sanitary pump (stb. side) damaged & torn from fastenings, new complete pump now fitted
Meets to 18360 6x6x15."

The following pipes on all side of engine room found damaged & now renewed:-

Main circulating water inlet to all condenser.

Condensate pipe to all air pump.

Evaporator blow down. & salt water feed. & drain from coils
Tank suction line to G.L. pump.

Bilge suction line to G.L. pump.

Sea suction line to G.L. pump & sanitary pump.

Hotwell suction line to G.L. pump.

Bilge suction to ram pump.

Discharge to auxiliary range (fire) G.L. pump.

Discharge overboard G.L. pump. & deck discharge

Discharge from sanitary pump to manifolds

Leak discharge to filter.

Bilge & sanitary discharge from ram pump.

Induction pipe from all condenser.

The following steam & exhaust pipes damaged now renewed:-

Steam & exhaust lines to G.L. & sanitary pumps.

" " " to evaporators. & forced draught
fan engine.

Steam & exhaust lines to all circulating pump & dynamos.

Main & auxiliary steam pipes examined & tested

hydraulically & found satisfactory

Steering engine & windlass overhauls & examined.

Boilers:- The centre boiler stated to have been steaming at time of damage & boat submerged, has now been examined throughout & tested hydraulically & the following damage repairs carried out.

8 rolling stay studs fractured now renewed.

All combustion chamber stay nuts hardened up.

16 rolling stay studs fractured & now renewed on all boiler.

Boiler Survey:- The main boilers examined throughout with mountings doors & fastenings & now placed in good condition. The port & all boilers examined under steam & safety valves adjusted to pressures as above.

The centre boiler also examined under steam, but due to insufficient compression on safety valve springs, new springs have now been fitted, but no opportunity was offered to adjust these valves at this time.

TWIN SC TACOMA STAR.

(5).

Boiler Repairs (W + S)

St. Boiler :- St. wing C.C. :- One fractured shell stay renewed.

Cracks in fore & after furnace neck flanging now need "out" & welded electrically, a number of furnace landing cracks need out & welded. A number of leaky furnaces need renewed.

St. Bow C.C. :- Some grooving on back side plates between vertical rows of margin tubes now need "out" & welded electrically 18 stay & 14 plain tubes in way renewed.

Bow Bow C.C. :- Some grooving on back side plates between vertical rows of margin tubes now need out & welded electrically, 16 stay & 15 plain tubes in way renewed.

Bow Wing :- Cracks in fore & after furnace neck flanging now need "out" & built up electrically.

All furnaces where wasted along line of fire bars, built up electrically.

Centre Boiler :- Cracks in fore & after st. wing furnaces neck flanging now need out & built up electrically
Some grooving on st. wing back side plates between vertical rows of margin tubes now need out & built up electrically, 5 stay & 3 plain tubes in way renewed
All furnaces where wasted along line of fire bars, built up electrically.

Bottom manholes of centre & st. boilers where wasted built up electrically & doors fitted.

The last water gauge breast cocks of th. P+S boilers found wasted, now renewed (tapped). St. boiler blow down valve chest found this now renewed (tapped).

In completion of th. boiler repairs th. centre & starboard boilers examined under hydraulic pressure & found satisfactory.

Damage to 2 :- It is stated that whilst vessel was weighing anchor in River Mersey on completion of half stem trials of main engines, the vessel ran aground due to heavy weather on Blundell Sands, River Mersey on 18th October 1941.

How Done for Damage :- Vessel placed in dry dock, propellers stem tubes, sea cocks, valves & fastenings examined, grids removed & sand deposits cleared.

Bow & st. screw adaptors drawn & examined (26 Oct 1941).

P+S circulating pumps & condensers & injection pipes opened up cleaned of sand deposits & examined.

Bilge & Sanitary pumps & injection pipes opened up cleaned of sand deposits & examined.

TWIN Sc TACOMA STAR.

NOTE:- The opportunity was taken at this time to complete th. boiler survey (see body of report.) The centre boiler examined under steam + safety valves advised to 200 lb/IN².

Damage do. 3:- The following damage was stated to have been caused whilst vessel on final engine trials in River Mersey on 30th October 1941.

how done for Damage:- Starboard engine cylinders opened up + examined. Apparently one to a nut having been left in HP valve chest, it was found that the HP valve lever was broken, + casing cracked, also a set pin had passed through to under side of M.P. piston causing a bent piston rod.

Damage Repairs:- All st. engines cylinders, pistons values + casings opened up + examined.

New MP piston rod now fitted, stamped:- LLOYD'S NO
6320.
(Forgery report attached)

C.B. 31/10/41 E.P.B.

New HP valve lever fitted.

HP valve casing pinned at end of fracture, + suitable support plate fitted + steel reinforcing ring shrunk over bit of casing.

This repair in my opinion is efficient. meantime, but it is recommended that th. HP valve casing repair be examined before th. end of May 1942.

On completion of repairs th. machinery tried under full working conditions + found satisfactory. Pumping arrangements examined + tried.

The owners request that th. machinery examination now made be accepted as Lloyd's Machinery Survey.

NOTE:- The 90 kW generator engine stated not to have been in use for a considerable time has now been removed + placed ashore.

YOL.

s.s. "TACOMA STAR"Electrical Equipment.

Installation examined & tested under working conditions, generators, switchboard, cables, fittings etc examined, insulation test made.

Repairs:-

Generators:- one 90Kw and one 50Kw generator disconnected and removed to works for overhaul. Machines stripped & completely rewound. The 90Kw. generator has not been refitted on vessel. The 50Kw machine was re-assembled & fitted on board, new main cables fitted between generator & main switch board. One 15Kw & one 10Kw generator disconnected & removed to works for overhaul. Field coils retaped & varnished, 15Kw machine armature rewound, 10Kw armature cleaned & varnished, commutator skinned & micas undercut. Brush gear of both generators overhauled & made good. New main cables fitted between generators & main switch board. New governor gear fitted to engine driving 10Kw. machine. Main switchboard cleaned, overhauled & new parts fitted as necessary. Lathe motor control gear completely overhauled & repaired. New feeder cables fitted from main switchboard.

Engine Room Lighting:- Wiring renewed, fuse boxes overhauled, new fuses fitted where necessary. New fittings supplied as required.

Boiler Room Lighting:- Wiring renewed & fittings repaired or renewed as necessary. Tunnel lighting. Wiring renewed & fitting, made good.

Navigational Circuits. overhauled, new lanterns supplied, wiring partly renewed. Engineers accommodation partly renewed, fittings repaired or renewed, fuse boxes overhauled & made good.

Officers' accommodation wiring overhauled, fuse boxes cleaned & overhauled, fittings renewed as necessary.

Crew Quarters wiring overhauled, partly renewed & fittings made good.

Forward Accommodation. Faulty circuit renewed, remainder overhauled, fuse boxes cleaned & new fuses fitted as necessary, fittings repaired & some renewed.

Telephone Circuits overhauled & partly renewed, instruments repaired or renewed as necessary. Wiring for electric log partly renewed.

On completion the whole installation was examined & tested under working conditions & found satisfactory. The total generator capacity of this equipment is now 75Kw.

14/15C

۱۷۰

四庫全書

SHASTRA

1860-1861. The first year of the new century was a period of great change.

४

© 2019
Lloyd's Register
Foundation

iated

Subject is now recommended
without special endorsement

Dobler.

27/2/48

5/2/41