

REPORT ON OIL ENGINE MACHINERY.

No. 27299.

of writing Report 26 Feb 1927 When handed in at Local Office 26 Feb 1927 Port of New York Received at London Office 12 MAR 1927
 in Survey held at New York Date, First Survey 30 Sept 1926 Last Survey 25 Feb 1927
 on the Twin { Screw vessels M/V SAGAMI SECUNDUS Tons { Gross 4453
 Built at Hamburg By whom built Blohm + Voss Yard No. 210 When built 1913
 Engines made at Hamburg By whom made Blohm + Voss Engine No. When made 1913
 Boilers made at 2 By whom made 2 Boiler No. When made 1913
 Horse Power 2700 Owners SAGAMI NAVIGATION CO INC. Port belonging to New York
 Horse Power as per Rule 790 Is Refrigerating Machinery fitted for cargo purposes No. Is Electric Light fitted Yes

ENGINES, &c.—Type of Engines Diesel 2 or 4 stroke cycle 2 Single or double acting single
 Mean pressure in cylinders 500 lbs No. of cylinders 4 each engine No. of cranks 4 Diameter of cylinders 23.8"
 of stroke 36.2" Revolutions per minute 110 Means of ignition compression Kind of fuel used Fuel oil
 a bearing between each crank yes Span of bearings (Page 92, Section 2, par. 7 of Rules) 37.4"
 between centres of main bearings 59.5" Is a flywheel fitted yes Diameter of crank shaft journals 14.7"
 of crank pins 14.8" with 3.2" hole Breadth of crank webs 27.7" Thickness of ditto 11.7"
 of flywheel shaft on crank shaft Diameter of tunnel shaft 11.1" Diameter of thrust shaft 11.7"
 of screw shaft 12.65" Is the screw shaft fitted with a continuous liner the whole length of the stern tube no lines
 after end of the liner made watertight in the propeller boss yes If the liner is in more than one length are the joints burned yes
 liner does not fit tightly at the part between the bearings in the stern tube, is the space charged with a plastic material insoluble in water and non-corrosive yes
 liners are fitted, is the shaft lapped or protected between the liners yes If without liners, is the shaft arranged to run in oil yes
 outer gland fitted to stern tube Blohm + Voss Length of stern bush 54" Diameter of propeller 12.6"
 propeller 11.9" mean No. of blades 4 state whether moveable yes Total surface square feet
 of reversing Air Is a governor or other arrangement fitted to prevent racing of the engine yes Thickness of cylinder liners 2"
 cylinders fitted with safety valves yes Means of lubrication forced Are the exhaust pipes and silencers water cooled or lagged with
 insulating material yes If the exhaust is led overboard near the waterline, what means are arranged to prevent water from being syphoned back to the engine
Led up stack No. of cooling water pumps 3 each engine 2 independent Is the sea suction provided with an efficient strainer which can be cleared
 the vessel yes No. of bilge pumps fitted to the main engines 1 each engine Diameter of ditto 4 3/4" Stroke 25.6"
 be overhauled while the other is at work yes No. of auxiliary pumps connected to the main bilge lines 2 ballast How driven electrical drive
 pumps (1) 8.67" x 10" Centrifugal 12.8" Impeller No. and sizes of suction connected to both main bilge pumps and auxiliary bilge pumps:—In engine room 4 - 3 1/2"
 holds, etc. 2 - 3 1/2" each hold No. of ballast pumps 2 How driven electric Sizes of pumps (1) 8.67" x 10" Centrifugal 12.8" Impeller
 Ballast pump fitted with a direct suction from the engine room bilges yes State size 4" Is a separate auxiliary pump suction fitted in
 Room and size yes 4" Are all the bilge suction pipes fitted with roses yes Are the roses in Engine Room always accessible yes
 valves on Engine Room bulkheads always accessible yes Are all connections with the sea direct on the skin of the ship yes
 valves or cocks valves + cocks Are they fixed sufficiently high on the ship's side to be seen without lifting the floor plates yes
 discharge pipes above or below the deep water line above Are they each fitted with a discharge valve always accessible on the plating of the vessel yes
 pipes, cocks, valves and pumps in connection with the machinery accessible at all times yes Are the bilge suction pipes, cocks and valves arranged so as to prevent any
 contamination between the sea and the bilges yes Is the screw shaft tunnel watertight yes Is it fitted with a watertight door yes
 from upper deck yes If a wood vessel, what means are provided to prevent leakage of either fuel oil or of lubricating oil from saturating the woodwork yes
 main air compressors 1 each engine No. of stages 3 Diameters 5"-19.7"-22.2" Stroke 15.75" Driven by crankshaft
 auxiliary air compressors 2 Reavell type No. of stages 3 Diameters 4"-8"-(2) 6 1/2" Stroke 6" Driven by Aux. engines
 small auxiliary air compressors 1 No. of stages 2 Diameters 1.6"-4.72" Stroke 2" Driven by electric drive
 scavenging air pumps 2 each engine Diameter 33.5" Stroke 25.6" Driven by pump levers
 of auxiliary Diesel Engine crank shafts as per Rule 6.9" Are the air compressors and their coolers made so as to be easy of access yes
 as fitted 6.9"

RECEIVERS:—No. of high pressure air receivers 4 Internal diameter 2 @ 15" 2 @ 10" Cubic capacity of each 3.5 cu ft
steel Seamless, lap welded or riveted longitudinal joint seamless Range of tensile strength 17 3/4
5/8" x 1/2" working pressure by Rules 1000 lbs No. of starting air receivers 32 Internal diameter 17 3/4"
 capacity 850 cu ft Material steel Seamless, lap welded or riveted longitudinal joint seamless
 tensile strength 5/8" Working pressure by rules 950 Is each receiver, which can be isolated, yes
 a safety valve as per Rule yes Can the internal surfaces of the receivers be examined yes What means are provided for cleaning their
Removable Heads Is there a drain arrangement fitted at the lowest part of each receiver yes

yes.

二

PLANS. Are approved plans forwarded herewith for shafting yes Receivers no Separate Tanks ✓
(If not, state date of approval)

The foregoing is a correct description,

Manufacturer.

Dates of Survey while building	During progress of work in shops--	1926- Sept. 30. Oct. 1. 19. 22. Nov. 1. 10 - 1927- Jan. 28. Feb. 12. 21. 25.
	During erection on board vessel--	
	Total No. of visits	

Dates of Examination of principal parts—Cylinders 19+22/10/26 Covers 19+22/10/26 Pistons 19+22/10/26 Rods 19²²/10/26 Connecting rods 11/12

Crank shaft 28/1/27 Thrust shaft 10/11/26 Tunnel shafts 1/10/26 Screw shaft 1/10/26 Propeller 1/10/26 Stern tube 1/10/26 Engine seatings 2/1/27

Engines holding down bolts 21/2/27 Completion of pumping arrangements 21/2/27 Engines tried under working conditions 21/2/27

Completion of fitting sea connections 30/9/26. Stern tube 1/10/26 Screw shaft and propeller

Material of crank shaft ☒ Identification Mark on Do. ☒ Material of thrust shaft ☒ Identification Mark on Do. ☒

Material of tunnel shafts	Identification Marks on Do.	Material of screw shafts	Identification Marks on Do.

Is the flash point of the oil to be used over 150° F.

Is this machinery duplicate of a previous case no If so, state name of vessel

General Remarks (State quality of workmanship, opinions as to class, &c.)

Please see attached sheet.

The amount of Entry Fee	...	£	<i>Included</i>	:	When applied for,
Special	...	£	<i>in</i>	:	19
Doukey Boiler Fee	...	£	<i>Hull</i>	:	When received,
Travelling Expenses (if any)	£	<i>Fee.</i>	:	19	

Committee's Minute

Assigned LMC.MS. 2.27 subject

John S. Heck.

Engineer Surveyor to Lloyd's Register of Shipping

TUES. 29 NOV 1927

Continuation of Report No. 27299, dated 26 Feb 1927 on the

M. V. "SAGAMI"

12 MAR 321.

following however is respectfully submitted for the Committee's consideration:-

port engine crankshaft has given considerable trouble owing to the bearings heating. This my opinion was due to contamination of the lubricating oil. The engine is an early design with in crank case, and the design of the cylinder heads makes it difficult to keep the cooling water tight. As a consequence, the salt water leakage from cylinder jackets, the fresh water leakage from pistons and the burnt oil, etc., from cylinders fall into the bottom of the bed plate dilute the lubricating oil.

Owners have taken special care to make the joints as tight as possible and have put in two central machines for purifying the oil. The crank shafts ran successfully for 8 hours at sea at 110 R.M., and in my opinion, they are now in safe working condition and will run provided the crew pay attention to keep the joints tight and to changing the lubricating oils.

The cylinders and pistons are cooled by pumps worked from the main engines. Independent pumps are provided for use when the main engines are stopped but these are electrically driven. The steering gear is also electrical and therefore if the auxiliaries fail it becomes necessary to stop the main engines which leaves the cooling water stopped. It will therefore be necessary that in narrow waters the auxiliaries be kept running. In my opinion, this can be considered safe but it will be necessary to see that both auxiliaries are kept in good condition. This can only be done by thoroughly overhauling them after each voyage.

On the survey commenced there were ample spare parts, but difficulty has been experienced with the cracking of piston crowns and cylinder heads. The cylinder head is in two parts, the lower part only being water cooled. The cracking in my opinion, is in some part due to the cooling system as noted above.

The Owners desired to try acetylene welding the pistons and heads and as a result the position is as follows:-

	PORT ENGINE	STARBOARD ENGINE
No. 1 cylinder (aft)	Welded piston	Welded piston
No. 2 cylinder	Welded piston, welded spacer head,	
No. 4 cylinder (forward)	Welded piston,	Welded piston.

are three spare pistons, and three spare spacer heads on board, all welded. These welded stones have been tested to 1000 pounds and found good, and four of them have been examined after the hours trial and found still good.

my opinion, these welded pistons and heads are in safe working condition at present, but they could be again examined upon the vessel's return from her present voyage or in three months time whichever is sooner.

AUXILIARIES. Diesel auxiliary motor generators only are provided for power purposes. To heave up the anchor, or to work cargo, or to approach port, it is necessary to have both auxiliaries running. It will therefore be necessary to maintain the auxiliaries in a good state of efficiency.

my opinion, these engines are now in good and safe working condition and eligible to receive the notation of L.M.C. M.S. 2,27, D.B.S. 10-26 and T.S. (O.G.) 10-26, subject to annual survey of the water tube donkey boiler and subject to the welded pistons and cylinder head being again examined on the vessel's return from her present voyage, or in three months time whichever is sooner.

view however of the circumstances stated above, this opinion is respectfully submitted for the
 rial consideration of the Committee.

John S. Heck

Certificate (if required) to be sent to New York.

te. oil engine

© 2020

Lloyd's Register
202 (212)