

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

Writing Report 28 July 1931 When handed in at Local Office 19 Port of Rotterdam

Survey held at Krommerij van de Yper Date, First Survey 24 June Last Survey 24 July 1931 (No. of Visits) 11

on the Machinery of the Wood, Iron or Steel MAJA

Gross 8768 Vessel built at Krommerij van de Yper By whom C. J. A. Giesse in den Hoef When 1931

Net 4867 Engines made at Amsterdam By whom Werkspoor N.V. When 1931

Boilers, when made (Main) none (Donkey) Werkspoor N.V.

Owners Petroleum My La Corona Owners' Address The Hague (if not already recorded in Appendix to Register Book.)

Managers Port Voyage Voyage

If Surveyed Afloat or in Dry Dock Building (State name of Dock.)

Report No. _____ Port _____

Particulars of Examination and Repairs (if any) 1 Entry

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

| CHARACTER for Special Survey, Date of last Survey and of Periodical Surveys. | Years assigned for expired. | Machinery and Boiler Surveys (including date of N.B., if any) |
|--|-----------------------------|---|
| 100A1 Glass contemplated | | OIL ENGINE. |
| | | Carrying Petroleum in Bulk |

Special Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the nature and extent of Examinations and subsequent Repairs. Repairs on damage (the cause of which must be stated) should be separated from Repairs due to other causes; and being detailed in the body of the report, should be briefly summarised at the end of the report. State also the initials of any letters respecting this case.

In cases where the Surveyor has not made a special damage report he is required to state whether he has performed his services for this purpose, and why they were declined?

Has a special damage report been made by anyone else? If so, by whom?

Has the Surveyor personally gone inside each Main Boiler separately and made a thorough examination at this time?

Has the same been done for Donkey Boilers? If not done, state for what reasons?

Were special means, in the absence of internal examination, adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Has the Surveyor examined the Safety Valves of the Main Boiler? To what pressure were they afterwards adjusted under steam?

Has the Surveyor examined the Safety Valves of Donkey Boiler? To what pressure were they afterwards adjusted under steam?

Has the Surveyor examined all the manholes, doors and their fastenings of the Main Boilers? and of the Donkey Boilers?

Has the Surveyor examined the drain plugs of the Main Boilers? and of the Donkey Boiler?

Has the Surveyor examined all the mountings of the Main Boilers? and of the Donkey Boiler?

Has the main shaft now been drawn and examined? Is it fitted with continuous liner? Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

Has the propeller shaft now been changed? If so, state reasons. Has it a continuous liner? Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

What is the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft?

If the survey is not complete, state what arrangements have been made for its completion and what remains to be done.

The stern tubes and propeller shafts with continuous liners fitted in place and found good. Propellers will be fitted at Amsterdam. Sea connections fitted and good. The above shafting and machinery has been made by Messrs Werkspoor N.V. at Amsterdam and fitted at the builders' yard.

and tested steam heating coils as per Rules in all cargo oil tanks, oil fuel double bottom tanks in engine room and in lubricating oil tanks in double bottom.

The bilge pumping arrangement forward examined and found good and in accordance with the approved plan. The vessel has been forwarded to Amsterdam to receive her P.T.O.


General Observations, Opinion, and Recommendation:—

State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.: thus, for example, B.S. 9.11, B.&M.S. 9.11, or L.M.C. 9.11, 140 lb., F.D., &c.)

For the information of the Committee

Fees applied for
 £ 100.00
 Damage or Repair Fee (if any) £ : :
 Selling expenses (if chargeable) £ 16.00
 Received by me, 31.12.1931
 TUE. 8 DEC 1931
 See J.B. Rpt.

Engineer Surveyor to Lloyd's Register of Shipping.



Lloyd's Register Foundation

Insert Character of Ship and Machinery precisely as in the Register Book.

Is a Certificate required? If so, to be sent to

Committee's Minute

signed

No. of Visits

heavy oil machinery.
The Amsterdam Surveyors have been advised
A. Dyk.

N.B.—If this Report is copied by copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.



© 2021

Lloyd's Register
Foundation

For S.S.O.F. Lane

ing Re
urvey
IST
becn
Sur
gro
16
8.3
van
and
Reg
spect
rece
pecte
tha
hard
in
est
ature
and
bein
ing
Societ
sta
a.7.30.
terna
ssur
up we
Air
ap we