

## REPORT OF SURVEY FOR REPAIRS, &amp;c.

Writing Report... 19... When handed in at Local Office... 19... Port of *Ryghjovik*  
 in Survey held at *Ryghjovik* Date, First Survey *5 Dec* Last Survey *16 Dec* 19*41*  
 Book. (No. of Visits... *12*)

*470* on the Wood, Iron or Steel *7. Max Pemberton*  
 TONNAGE *32 1/2* Built at *Delby* By whom *Macrone & Sons L.R.* When *1917* - *2*  
 Owners *J. K. Thurstington* Owners' Address *Ryghjovik*  
 DER DK. *298* Managers *same* (Max Pemberton H/F in R.B.) (If not already recorded in Appendix to Register Book),  
*1358* Port belonging to *Ryghjovik*

eyed Afloat or in Dry Dock? *Slipway* Name of Dock *Sliplogid Ryghjovik* Destined Voyage.

DBorDBa feet; uE & B feet; f feet  
 capacity tons. FPT tons; APT tons; MT feet tons.

Only alterations in the existing records of tanks should be inserted.

N.B.—All alterations in the existing records should be underlined.

st Report, No. *867*. Port *Ryk*.

ical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules and items remaining to complete  
 Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations  
 subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to  
 other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the  
 placement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form.  
 Note also the dates and initials of any letters respecting this case.

amage cases where the Surveyor has not made a special damage report he is required to state whether he  
 offered his services for this purpose and to whom and why they were declined.

Society's Freeboard (if assigned) as }  
 painted on Ship and now verified } ft. ins.

Was a damage report made by anyone else? if so, by whom?

AIRS, OR EXAMINATION AS PER RULE, FOR *Comph 2 nd. Special Survey No 3.*

Vessel placed on Slipway, bottom, rudder, stemplate, keel and stem cleaned, examined  
 and found & put in good condition, afterwards recast. Holds, forward & aft peaks,  
 engine and boiler space and coal bunkers cleared for survey, ceiling after all fire  
 & aft, all oxidation removed from all parts, and all steel work throughout all parts  
 vessel carefully examined and found & put in good condition, afterwards recast.  
 ining on ship's removed in way of sightlights and plating in way of same examined  
 and found & put in good condition, hatchways, hatches, ceiling, air and sounding pipes,  
 sounding pipes, welders, steering gear, rods, chains, sheaves, etc. pumps, w.t.  
 ay, copper, skylights, boats, masts (wedges removed) rigging, anchors, chain cables (cables  
 anyed), hawsers & warps and the general equipment examined and all found & put in good

ARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—
Renewed ...								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place ...								

## ENT CONDITION OF THE

ing of Decks <i>good</i>	Bulkheads <i>good</i>	Engine Room Skylights <i>good</i>	Copper, or Y.M. <i>good</i>
ings <i>good</i>	Ceiling <i>good</i>	Coal Bunkers, Openings, Covers, &c. <i>good</i>	(State if on Felt.)
s & Fastenings <i>good</i>	Cement or Asphalt <i>good</i>	Oil Bunkers	When fitted, Month Year
le Plating <i>good</i>	Rudder <i>good</i>	Seuppers <i>good</i>	Boats <i>good</i>
in way of sightlights <i>good</i>	Steering gear and its connections <i>good</i>	Cargo Hatchways <i>good</i>	Masts, Yards, &c. <i>good</i>
is <i>good</i>	Windlass <i>good</i>	Hatches <i>good</i>	Condition, how ascertained. <i>checked</i>
se Frames <i>good</i>	Have pumps been examined and found effi- cient? <i>yes</i>	Planking	(State if wedges removed.) <i>no</i>
udinals <i>good</i>	Have Sluice Valves been examined and found efficient? <i>yes</i>	Caulking	Equipment letter <i>no</i>
verses <i>good</i>	Have Watertight Doors been examined and found efficient? <i>yes</i>	Treenails	Anchors, No. of <i>3</i>
ons <i>good</i>	Have Ventilators and their Coamings been examined and found efficient? <i>yes</i>	Breasthooks & Stemson	Cables (State if now ranged) <i>yes</i>
ers <i>good</i>	Air and Sounding Pipes <i>good</i>	Transoms, Pointers & Crutches	length <i>196</i> mean diam. <i>1 1/4</i>
Bottom Plating <i>good</i>	Doubling Plates under Sounding Pipes <i>good</i>	Timbers of Frame at openings	(on board.) <i>120</i> size <i>1 1/4</i>
the Tanks been examined internally? <i>yes</i>		" " at other places	Chain Locker <i>good</i>
the Tanks been tested? <i>yes</i>		Stringers, Clamps & Shelves	Hawsers & Warps <i>good</i>
		Salting (State if examined.)	Standing and Running Rigging <i>good</i>
			Sails

neral Observations, Opinion as to Class, Recommendation, &c.:— *This vessel is in good*

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon  
 this survey, thus, for example:— "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of  
 survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

*and efficient, condition, in my opinion, eligible to remain as classed and  
 to have the record of 100A1. S.M. Trawler. 2 nd. S.S. Ryk. No 3-12, 41 in  
 Register Book.*

urvey Fee (per Section 29)	£ 20 : 10 : 0	Fees applied for, <i>23/12 1941</i>
pecial Damage or Repair Fee (if any) (per Sec. 29)	£ 1 : 1 : 0	Received by me, <i>23/12 1941</i>
avelling Expenses (if chargeable)	£ : : :	<i>100</i>
cond Surveyor's Fee (if any)	£ : : :	

ommittee's Minute

TUES. 31 AUG 1943

Character Assigned

*12.41 Ryk.*  
*S.S. Ryk No 3-12.41.*

*+ LMC 12.41.*

Surveyor to Lloyd's Register of Shipping.



Lloyd's Register  
 Foundation

W253-0122

Because the heavy repairs carried out on the vessel in 1940, there was only to make some small and trivial repairs on the vessel. The steering line was disconnected and all the chains in some amount, also the chain cables were annealed.

The fishing outcrop was drilled in 1940 and all were shot in some renewal.

*St. George's*

When Anchors or Cables are supplied, the particulars are to be reported in the following form :

Number of Certificate.	Anchors.*	WEIGHT, EX. STOCK.			WEIGHT OF STOCK.			TEST PER CERTIFICATE.				WEIGHT REQUIRED BY RULE.			Description of Anchor.	Makers.	Where and when tested and Superintendent.
		Cwts.	qrs.	lbs.	Cwts.	qrs.	lbs.	Tons	Cwts.	qrs.	lbs.	Cwts.	qrs.	lbs.			
	1st Bower																
	2nd "																
	3rd "																
	Collective Weight																
	Stream.....																
	Kedge .....																

\* When a bower anchor is supplied it must be clearly stated whether it is a 1st, 2nd, or 3rd bower.

[illegible]