

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report Dec 8 1941 When handed in at Local Office Dec 9 1941 Port of Galveston Texas
 No. in Reg. Book. 43501 on the Wood, Iron or Steel 1 1/2 s/s E. M. Clark Date, First Survey Dec 7 Last Survey Dec 7 1941
 (No. of Visits 1)

TONNAGE:— Built at Kearny N.J. By whom Federal S.B. Co When 1921 YEAR. MONTH. 7
 GROSS 9647 Owners Standard Oil Co of New Jersey Owners' Address (if not already recorded in Appendix to Register Book)
 UNDER DK. 6020 Managers Port belonging to Wilmington (Del.)
 NET 6020

Surveyed Afloat or in Dry Dock? At Anchor in Roads Name of Dock Destined Voyage

Cell/Dor/DBa feet; uE&B feet; f feet
 total capacity tons. FPT tons; APT tons; MT feet tons.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

Only alterations in the existing records of tanks should be inserted.
 N.B.—All alterations in the existing records should be underlined.

Last Report, No. 4168. Port GAL.

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined Copy Attached

Was a damage report made by anyone else? if so, by whom? ✓

REPAIRS, OR EXAMINATION AS PER RULE, FOR Damage alleged sustained on 7th December 1941 by collision with wooden shell carrying barge 741 in tow of the tow boat "Capt Haden" the barge being empty & the vessel loaded on a voyage from Baytown to Wilmington North Carolina. The accident taking place in the Houston Ship Channel abeam of Beacons 22 or 23.

Now Done— The vessel was examined afloat at anchor. The fore peak spaces and the fore peak tank examined internally, no apparent damage was found in fore peak spaces, but in the fore peak tank slight sharp indentations were found between frames 4 & 5 from stem on Port side & between frames 3 & 4 on St side & about six feet below the tank top to varying depths of $2\frac{1}{2}$ & $3\frac{1}{4}$ over areas of about eight inches square, as this was below water line & no water was found to be entering the vessel, it was recommended that further survey should be held next dry docking period.

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates	Dk. Plates.	Other Items:—
Renewed ...								
Removed and Fair'd or Repaired ...								
Fair'd or Repaired in place ...								

PRESENT CONDITION OF THE

Decks	Bulkheads	Engine Room Skylights	Copper, or Y.M. (State if on Feet.)
Caulking of Decks	Ceiling	Coal Bunkers, Openings, Covers, &c.	When fitted, Month Year
Coamings	Cement or Asphalt	Oil Bunkers	Boats
Beams & Fastenings	Rudder	Scuppers	Masts, Yards, &c.
Outside Plating	Steering gear and its connections	Cargo Hatchways	Condition, how ascertained (State if wedges removed.)
" " in way of sidelights	Windlass	Hatches	Equipment letter
Frames	Have pumps been examined and found efficient?	Planking	Anchors, No. of
Reverse Frames	Have Stiffice Valves been examined and found efficient?	Caulking	Cables (State if now ranged)
Longitudinals	Have Watertight Doors been examined and found efficient?	Treenails	" length mean diam. (on board)
Transverses	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson	" Rule length size
Floors	Air and Sounding Pipes	Transoms, Pointers & Crutches	Chain Locker
Keelsons	Doubling Plates under Sounding Pipes	Timbers of Frame at openings	Hawsers & Warps
Stringers		" " at other places	Standing and Running Rigging
Inner Bottom Plating		Stringers, Clamps & Shelves	Sails
Have the Tanks been examined internally?		Salting (State if examined.)	
Have the Tanks been tested?			

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1.38," or "to remain as classed and to have record of survey, 1.38, and the notations of ss No. 1-38."

This vessel as far as now seen is in a fit & safe condition & eligible in my opinion to remain as classed without fresh record of survey. Subject to further examination in dry dock next Dry docking period of stem. Bow plating (due this collision)

Survey Fee (per Section 20) £ 40.00
 Special Damage or Repair Fee (if any) (per Sec. 20) £ 1.00
 Travelling Expenses (if chargeable) £ 10.00
 Second Surveyor's Fee (if any) £ 10.00
 Fees applied for, 9/12/41 W.K.
 Received by me, M. Dickson

Surveyor to Lloyd's Register of Shipping.

Committee's Minute

Character Assigned As now

NEW YORK DEC 23 1941

Subject H. & D. B.L.R.



© 2021

Lloyd's Register Foundation