

## REPORT OF SURVEY FOR REPAIRS, &amp;c.

of writing Report... 6-9-46. When handed in at Local Office 9 SEP 1946 Port of NEWCASTLE-ON-TYNE

No. in Survey held at Blyth Date, First Survey 20-12-46 Last Survey 9-8-1946

on the Wood, Iron or Steel sc. VARVASSI (In MOSCHA D KYDONIEFS) (No. of Visits 44)

TONNAGE :-

ROSS 2874

GROSS UNDER DK 3673

Net ET 2400

Built at Newcastle By whom Northumberland S.B. Co Ltd. When 1915 MONTH 3

Owners Sargenia Chanaris Owners' Address

Managers Port belonging to PIRAEUS.

Laid Afloat or in Dry Dock? yes. Name of Dock Blyth Dock S.B. Co Ltd. Destined Voyage

Depth of Water at Berth feet; uE &amp; B feet; f feet

Capacity tons. FPT tons; APT tons; MT tons. Particulars of Classification (which must be inserted precisely as in Register Book &amp; Supplements)

Only alterations in the existing records of tanks should be inserted.

B. All alterations in the existing records should be underlined.

Report, No. 113341. Port London

al Surveys, when held, must be reported in detail and seriatim in the terms of the Rules and items remaining to complete surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the cement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. Also the dates and initials of any letters respecting this case.

Where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined.

Resolutive. Not required.

Was a damage report made by anyone else? if so, by whom? No.

IRS, OR EXAMINATION AS PER RULE, FOR Damage and Special Survey.

Damage stated to have been caused by contact with S/S. JOHN BOWELL on 9th May 1943 in the city of Trip Lock Point, in River Thames, passage from Canada to London in loaded condition.

Result of above, this vessel was sunk and subsequently refloated. Temporary repairs were effected (see on Report No 113341) and the vessel was towed to Blyth where, after the removal of mud and wire cleaning, the vessel was dry docked and permanent repairs effected.

Done Damage - Vessel placed in dry dock. Bottom and rudder cleaned, examined and placed good order. Rudder lifted. Cables ranged.

Holds, peaks, tween decks, bunkers, machinery spaces & chain locker cleaned, cleaned and examined. Tanks including Air peak and all at tanks tested and examined internally. All bulge ceiling lifted. Examination also made of Air sounding pipes, masts and rigging, decks, windlass, steering gear

ARY OF DAMAGE REPAIRS :-	Shell Plates.	Frames.	Trans Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items :-
Renewed ...	16 5/8"	40	25	11	13 22 1/2"	3 5/8"	37 1/2"	2 4/8" (see sheet 11)
Removed and Faird or Repaired	7	3 5/8"	-	-	10	-	3	2 3" (2 1/2" of frames)
Faird or Repaired in place	5	3	-	5	-	-	1	-

## GENERAL CONDITION OF THE

ing of Decks	good.	Bulkheads	good.	Engine Room Skylights	good	Copper, or Y.M.	(State if on Felt.)
ings	good.	Ceiling	Blg. good.	Coal Bunkers, Openings, Covers, &c.	good.	When fitted, Month	Year
& Fastenings	good.	Cement or Asphalt	good.	Oil Bunkers	-	Boats	good.
Plating	good.	Rudder	good.	Scuppers	good.	Masts, Yards, &c.	good
" in way of sidelights	good.	Steering gear and its connections	good.	Cargo Hatchways	good.	Condition, how ascertained	from aloft.
Frames	none -	Windlass	good.	Hatches	good.	(State if wedges removed.)	
itudinals	-	Have pumps been examined and found efficient?	yes.	Planking	-	Equipment letter	x
verses	-	Have Sluice Valves been examined and found efficient?	-	Caulking	-	Anchors, No. of	30, 15, 15
ons	good.	Have Watertight Doors been examined and found efficient?	yes.	Treenails	-	Cables (State if now ranged)	46
ers	good.	Have Ventilators and their Coamings been examined and found efficient?	yes.	Breasthooks & Stemson	-	" length	225 mean diam. 2"
Bottom Plating	good.	Air and Sounding Pipes	good.	Transoms, Pointers & Crutches	-	" Rule length	270 size 2 1/8
the Tanks been examined internally?	yes.	Doubling Plates under Sounding Pipes	good.	Timbers of Frame at openings	-	Chain Locker	good
the Tanks been tested?	yes all			" at other places	-	Hawsers & Warps	sufficient
				Stringers, Clamps & Shelves	-	Standing and Running Rigging	good
				Sailing	(State if examined.)	Sails	-

## General Observations, Opinion as to Class, Recommendation, &amp;c. :-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example: "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1.38," or "to remain as classed and to have record of survey, 1.38, and the notations of ss No. 1-38."

This vessel is, in our opinion, eligible to remain as classed with Date of Drydocking 8-46 and notation S.S. Bly 8.46 (DR). Permanent repairs to be effected to 2 shell plates and a deck plate (SOS), united bulwarks etc (P.S.F), stem and stem plating etc at owners convenience. Large battens to place in order at next opportunity. (45 fathoms chain cable to be supplied)

Survey Fee (per Section 29)	£ 46 : 0 : 0	Fees applied for,	10 SEP 1946
Special Damage or Repair Fee (if any) (per Sec. 29) REFERENCE CASE 7-1-46	£ 63 : 0 : 0	Received by me,	John Tindley
Travelling Expenses (if chargeable)	£		
Second Surveyor's Fee (if any)	£		

Committee's Minute

Character Assigned

8.46 Bly subject (L)  
S.S. Bly - 8.46 (DR) + LMC 8.46 without spl. chr. (L)  
S. 7.46

Surveyor to Lloyd's Register of Shipping.

Lloyd's Register Foundation







9<sup>th</sup> VARVASSI. Sheet III

Starboard - 3 Hanger plates renewed. 116/7 - 82/3. 3 A Hatch plates renewed 105/6 - 83/4  
2 B Hatch plates renewed. 103/4 - 85/6. Deck doublers renewed at S. Aft corner Bunker hatch, between S. hatch and casing and at S. fwd corner of casing.

Port and Starboard gunwale bars renewed in way.

Fore and Aft Girders under sheller deck 1 Port & 1 Starboard between Bkr. hatch and Bkr. casing renewed. completely with brackets, beam & deck lugs.

Beams - Lower Deck. Port -

4 Renewed. (91.100.102.104) 7 Cropped and part renewed. (95.97.98.106.108.110.112) 10 Beam knees renewed. and 4 large flanged knees renewed. (97.98.106.107)

Starboard - No 92 beam renewed. No 91 Removed, faired and refitted 5 Beam knees renewed.

Beams - Shellier Deck Port -

Renewed. (99.100.101.102.103.104.105) 15 Cropped and part renewed (93.94.95.96.97.98.106. and 107 to 114 inclusive) 8 Beam knees renewed and 2 large flanged knees renewed.

Starboard - No 90 beam renewed. and 9 removed, faired & refitted (89, 91, and 99 to 105 inclusive) 7 Beam knees renewed.

Casings between Deck - 3 lengths foundation angle renewed. 2 Badly buckled casing plates on side, renewed.

Deck. 2A Hatch - Port and Starboard BA coamings and after end coaming badly distorted. Port coaming renewed. Starboard side and aft end coamings removed, faired refitted together with rest angles. Green deck pillars at Bunker hatch, removed, faired and refitted. 32 hatch cleats renewed.

Deck. 2A Hatch - Starboard coaming plates faired in place. Port coaming - 2 plates renewed. foundation angles cropped and part renewed. mouldings and beam shoes renewed. 8 cleats renewed.

Casings 11 plates renewed - 1 S. coaming plate 3 S. side plates S. corner plate 3 end plates P corner and 2 port side plates. 5 stiffeners renewed.

Tank in way 2A Hold - (Buckled at Stockholm bulkhead) 93'

margin plate, originally removed for access to internal work - afterwards renewed.

plates in B.C. shell port renewed. plates in A Port, A Starboard, B & C starboard and end tank margin plate - all cropped at suitable shift of butts and part renewed.

Starboard tank margin angles cropped and part renewed.

brackets - badly buckled (13) 95-101 incl, 103, 106, 107, 109, 110, 111 renewed. Port side brackets - 11 in No 2 Tank. Port

(2 Skeleton + 1 Hull). No 95, 98, 101 cropped and outer portions renewed. Bottom frames removed, and refitted and inner portions of floors faired in place.

7 Skeleton floors, outer brackets renewed, bottom frames removed, faired and refitted.

" " " " faired in place " " " " " "

3 " " bottom frames faired in place.

No - Outer No 95-98, 98-101 and inner 95-98 renewed together with connections.

Bulkhead (Stockholm) Badly distorted - completely dismantled - badly buckled and torn parts

Plate adjoining port wing cropped - torn upper part renewed, lower parts removed & faired

plate, torn, renewed. 2<sup>nd</sup> stanchion from port wing cropped, badly buckled upper part, renewed.

removed & faired. 3<sup>rd</sup> stanchion from port wing buckled - removed & faired. Centre plate in

5.

See sheet III



S/S VARVASSI Sheet III

Stokehold bulkhead contd.

Starboard wing plate badly buckled, renewed. Plate adjoining wing plate cropped, upper part renewed, remainder removed & fairer. 2<sup>nd</sup> strake from starboard wing, buckled, removed and fairer. 3<sup>rd</sup> strake from wing buckled, cropped, lower part renewed.

All bulkhead vert. stiffeners (21) removed, fairer and refitted together with connecting brackets etc.

6 Horizontal shell brackets Port and 6 starboard renewed together with shell frame lugs.

Bulkhead top foundation angle cropped and part renewed.

Valve boxes, suction pipes, gratings etc in way all removed for access, afterwards replaced in good order.

Water tight door 2. Removed, overhauled and refitted.

Pocket Bunkers Port and Starboard (aft of 93 bulkhead) - plating badly buckled - Both bunkers now completely renewed. 8 casing plates, corner angles, foundation angles, 9 stiffeners renewed.

Stokehold Vents. Badly buckled portions of 3 Stokehold Ventilators now part renewed.

Wood Bulkhead between nos 2/2A holds - entirely refitted with part new wood and connections

Samson Post - Buckled and bent port samson post at 80 casing - completely renewed.

Steering gear - completely opened out. one broken buffer spring renewed. 17-0 of strained steering chain renewed.

Masts and Rigging - Rigging, screws and shackles found badly wasted. all remaining rigging on foremast and mainmast including topmasts, screws and shackles, renewed.

Several missing ventilator cowls, wood plugs and canvas covers replaced.

200 hatch wedges supplied. missing wood hatch covers made good and several minor repairs effected.

No 2 Tank Starboard side - Buckled floor stated to have been grounding damage but no details of time and place available.

Repairs - one tank top plate removed for access.

6 Buckled floors. (solis) cropped and part renewed (nos 110, 113, 116, 119, 122, 125) slightly buckled floor 125 fared in place.

How done Special Survey. - Vessel placed in dry dock. Bottom and rudder cleaned, examined, placed in good order and coated. Rudder lifted. Cables ranged.

All holds, peaks, tween decks, bunkers, machinery spaces & chain locker cleared, cleaned & examined. All tanks (Aft peak rail at tanks) tested as per Rules and examined internally. All ridge ceiling lifted. Oxidization removed where necessary, steelwork including plating in way of sunlight, examined and surfaces recoated.

Examined also made of W.T doors, air sounding pipes, masts and rigging (report attached) Decks, windows, steering gear chains, hatches, hatchways, casings, ventilators and their coverings, and the general equipment.

Pumps tried, anchors & cables examined, foreboard verified and shell drilled.

A Renewal Foreboard survey held. Aft steering gear rigged tried. Spare gear made good.

Repairs, wear and tear - (Plating numbered from forward).

Shell etc - F14. Port and Starboard Renewed.

G14. 15 Port and Starboard Doubled full length of both plates.

Star J. No 2 Doubled over Fore Peak Bulkhead. Star G. 2 Doubled where locally thin.

Port and Starboard E No 1 plates doubled full length. Thin and fractured at frames.

See list Shell Drillings on back of Page 1 Rept 8

P. J3. P. C7. Fared in place.

See Sheet (5)



S/S. VARYASSI (5)

Under- nos 2, 3 bushes hardened. 5 Gudgeon bushes renewed.

Wales - Mainboard nos 1 + 9 lengths found below size. now removed leaving total 225 fms. 2" dia

Wales - several slack studs hardened. Port anchor shackle pin renewed.

Wales - DEMS. equipment. gun mountings, platforms, plastic armour etc removed and all structures in way made good.

150 wood hatch covers renewed. Forepeak Air pipe gooseneck renewed. Forepeak hatch coaming part renewed. Handrails generally throughout, repaired made good. Several nursing vent cowls, wood plug and canvas covers made good. Fore Peak hand pump overhauled. Several hatch battery bars supplied.

Rust bound fidley casing rivets, renewed. Doubler fitted to Shellier Dk. P.S. alongside accommodation under steam pipes. Wash Dk pipes. Dk steam exhaust pipes repaired.

All 8 vouchers lifted and winch seating angles renewed.

Deck plating abreast foremast S. Side released and fanned in place. Beams in way fanned in place and angle stiffeners fitted (See also S.R. list)

Several deck doublers fitted at locally thin places - eq. way galley, & in way W.C. Port side saloon casing doubled where thin Port side bunker casing doubled.

2 Beams P. & 2 S. main flying bridge, renewed together with beam knees

Forepeak storm covers part renewed.

Air pipes from at tanks - normally discharging overboard in Tween decks now altered & led up to Shellier Dk with goosenecks.

Foremast deck caulked spayed. P. Forecastle forelead renewed. Aft P forelead seating on poop fanned.

Bunker hatch beams. 1 Plate renewed. Top angles renewed.

Deck - Lowest stringer Panels S. face angles fitted to plate. 2<sup>nd</sup> lowest stringer plates P & S cropped and part renewed. Aftermost thwartship beam at this level, fitted with reverse angle.

Frames. nos 3, 9 S.S. nos 1, 2 P.S. cropped and part renewed.

Thwartship angle stiffener on chain locker, renewed. Chain locker bottom plating renewed.

3 Bulkhead stiffeners below chain locker part renewed.

Forepeak bulkhead coaming plate doubled at Tween Dk.

Face angles fitted to P & S stringer plates in chain locker and Reverse angles fitted to forward casing of chain locker at wanted plate flanges. Forepeak sounding pipe repaired.

Tween Decks.

Deck Doubler fitted to S. Aft corner. no 1 hatch at fracture.

2 - new 2 1/2 Scuppers P and 2 S now fitted & led to machinery spaces with lead weighted corks. Broadboard scuppers blanked off. Several Ventilator tubes repaired. (9)

Tween Deck Frames S.S. 90, 91 Renewed. 83 (web) 84 to 89, 92, 94, 95, 96, 97, 99, 100, 101, 102, 103 all cropped and lower portions renewed. 93 (web) fanned in place.

Deck plating under saloon - Port fore corner plate cropped and part renewed. Casing foundation angle cropped and part renewed. Plating in pantry cropped and part renewed. Cement in saloon accom lifted for examination renewed

ment in mesship accom P & S lifted for exam<sup>n</sup>. afterwards renewed.

Double fitted to B strake on lower dk plating at fore end of bunker hatch. Centre strake fore end of bunker hatch cropped and thwartship plate fitted. C strake plate between end bunker hatch and Btr casing, renewed.



S/S. VARVASSI (6)

over holds etc.

no1. Tank top doublers fitted to locally thin plates P. A plate no 3. S.B. plate no 3. S.C plate no 1. Laming pipe part renewed. Lower parts of mast seating webs cropped and part renewed. Several Bulge gusset angles renewed.

no2+2A Forward hold pillar secured to tank top with new brackets & lugs. 3 hold pillars removed, faired and refitted with new brackets and connections to tank top. new BA stiffeners fitted to fore and aft pillars at bunker hatch.

PS fore Air pipes repaired. PS aft air pipes renewed.

Tank top doubled right across on every strake in way of wood divisional bulkhead between no2 + 2A holds.

no138 Bulkhead (fore end) 4 bulkhead stiffeners renewed together with brackets and lugs.

Bulkhead doublers fitted 1P. 15 at wings.

Several gusset angles renewed. P. 14. S. 2.

Bulge Brackets 27 Renewed Port side 16 Renewed Starboard side.

no3 Bulk Room - 2 Doublers fitted to LR Tank top Port side where locally wasted.

9 Bulge Brackets renewed S. Side Eng Room. 5 Renewed SS Boiler room.

no3 Hold One tank top plate port, one starboard removed for access to internal repairs. one plate port side cropped and part renewed.

14 Bulge brackets port and 4 starboard, renewed.

no4 Hold Flange cropped from 21 Bulge brackets S. Side + 20 Port side and face angles fitted.

one Tank top plate S.S. fore doubled. 1 Port side plate cropped and part renewed.

Tanks. no1. Tank end between fore Peak and no1. PS. doubled. Tank end between no1 + 2 tanks port side, doubled.

no2 Tank. Port Tank end (aft) no43 renewed. Floors 46. 49 52 55 58 61 64 67 70 71 (10) cropped and part renewed. Interentials 5 renewed 43/46. 46/49. 49/67.

Starboard Tank end plate renewed. Floors. 46. 49 52 55 58 61 (6) cropped and part renewed

Interentials 4 renewed. together with vertical lugs and shell bars.

no4 Tank - 1 Tank top plate PS. cropped and part renewed.

no42 floor S.S. side, inner bay, renewed. no40, 41 entire Keelson brackets S. Side, renewed.

the interentials 42/43 renewed.

Special Reasons List - Permanent repair now carried out to buckled deck plating beams (SS) abreast foremast.

Permanent repair now effected to indented plating, frames etc (S.S. amidships). Bow plating in way port house pipe exam'd. no repair deemed necessary, indent very minor. Indented no3 sheerstrake plate (PS) now faired in place.

Reinforcing overhauls in 2 shell plates & deck plate S. 9th - (very minor damage) Shell plate C7 (PSA) now faired in place

Indented bulwarks etc (PS) not dealt with. Cargo battens will be placed in order when timber available.

huller judicious especially exam'd and found in good condition. Internal structures in F Peak now dealt

with. Stem plating etc not dealt with - remains efficient. FP pumping arrangement now in

good order.



S/S VARVASSI Sheet 1

Boilers examined together with their safety valves, mountings, doors and fastenings and placed in safe working order. Safety valves adjusted under steam to 180 lbs p.s.i.

Chain Damage -

Calocks - All chests scraped out & coated. Main injection valve - broken stalk renewed.

Main Engines - HP valve chest, MP cylinder & HP cylinder - all slightly pitted and now skimmed out. HP piston valve rings renewed. MP & HP piston rings renewed.

MP valve false face pitted, machined. HP, MP, & HP piston rods and valve spindles machined. Valve spindle guide braces renewed. New neck gland bushes fitted to HP & MP piston rods. Rocking shaft machined bearings reinstalled. Radius links dressed up.

Top end pins lapped & brasses adjusted

Crank shaft removed and all main bearing journals machined. Bottom end pins filed up & lapped. Bearings adjusted to suit.

Pump crosshead machined. Brasses adjusted. Lever pins dressed up. Forward link bottom brasses renewed.

Shafting. Thrust shaft and all intermediate shafting removed and bearing surfaces machined. Bearings adjusted & all shafting aligned.

Pumps - Ballast - New water and main fitted. New piston and bucket rods fitted. Piston rings renewed. Slide valves dressed up. Buckets renewed. Inlet & outlet valves overhauled & refitted.

- Feed Pumps (2) Port Pump - Piston rings renewed. Slide valve renewed. 2 Delivery valves renewed. Piston rod stuffing box renewed. Starboard Pump - Slide valve faces dressed up. Piston and bucket rings renewed.

2. In Admiralty Main Feed Pumps installed 8 1/2" x 6" x 14" Steam and exhaust pipes altered to suit.

2 - Reconditioned generators satisfactorily installed. Steam and exhaust pipes altered to suit. Generator engines Cyls marked LLOYDS TEST 300 lbs. 8/4/42 A.W. 7 1/2" dia cyls. 4 1/2" stroke

Turning Engine - New piston rings fitted.

Reversing Engine - Rods machined. Piston rings renewed. New crank pin fitted for Reversing arm.

Condenser - All tubes drawn and tested. Several new tubes fitted. Considerable number of ferrule holes retapped and new ferrules fitted.

Evaporator - Coils annealed & tested. Drain valve renewed.

Boilers - Mountings cleaned & overhauled. Several valves and seats machined. A considerable number of cover studs renewed. Main Br - Aux stop seat & safety valve caps renewed. Centre Br - Main & Aux check valve lids & blow down lid, renewed. Port Boiler - aux check valve lid & one missing safety valve cap, renewed.

Starboard Br - 173 plain and 82 Stay Tubes renewed. 1 CC Back stay, renewed.

Centre Br - 173 " " 82 " " " 15 back & 3 partition stays renewed.

Port Boiler - 173 " " 82 " " "

Some wastage at back CC stay holes built up.

Centre Boiler - Centre Furnace - Two places where old welding had fractured cut out, prepared and rewelded.

Several minor repairs and adjustments effected.

Lagging part renewed on all boilers (See back of Report 9)



100

1-1

122076A

© 20  
Lloyd's  
Found

*Handwritten text, likely bleed-through from the reverse side of the page.*

[illegible]

10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100 101 102 103 104 105 106 107 108 109 110 111 112 113 114 115 116 117 118 119 120 121 122 123 124 125 126 127 128 129 130 131 132 133 134 135 136 137 138 139 140 141 142 143 144 145 146 147 148 149 150 151 152 153 154 155 156 157 158 159 160 161 162 163 164 165 166 167 168 169 170 171 172 173 174 175 176 177 178 179 180 181 182 183 184 185 186 187 188 189 190 191 192 193 194 195 196 197 198 199 200 201 202 203 204 205 206 207 208 209 210 211 212 213 214 215 216 217 218 219 220 221 222 223 224 225 226 227 228 229 230 231 232 233 234 235 236 237 238 239 240 241 242 243 244 245 246 247 248 249 250 251 252 253 254 255 256 257 258 259 260 261 262 263 264 265 266 267 268 269 270 271 272 273 274 275 276 277 278 279 280 281 282 283 284 285 286 287 288 289 290 291 292 293 294 295 296 297 298 299 300 301 302 303 304 305 306 307 308 309 310 311 312 313 314 315 316 317 318 319 320 321 322 323 324 325 326 327 328 329 330 331 332 333 334 335 336 337 338 339 340 341 342 343 344 345 346 347 348 349 350 351 352 353 354 355 356 357 358 359 360 361 362 363 364 365 366 367 368 369 370 371 372 373 374 375 376 377 378 379 380 381 382 383 384 385 386 387 388 389 390 391 392 393 394 395 396 397 398 399 400 401 402 403 404 405 406 407 408 409 410 411 412 413 414 415 416 417 418 419 420 421 422 423 424 425 426 427 428 429 430 431 432 433 434 435 436 437 438 439 440 441 442 443 444 445 446 447 448 449 450 451 452 453 454 455 456 457 458 459 460 461 462 463 464 465 466 467 468 469 470 471 472 473 474 475 476 477 478 479 480 481 482 483 484 485 486 487 488 489 490 491 492 493 494 495 496 497 498 499 500 501 502 503 504 505 506 507 508 509 510 511 512 513 514 515 516 517 518 519 520 521 522 523 524 525 526 527 528 529 530 531 532 533 534 535 536 537 538 539 540 541 542 543 544 545 546 547 548 549 550 551 552 553 554 555 556 557 558 559 560 561 562 563 564 565 566 567 568 569 570 571 572 573 574 575 576 577 578 579 580 581 582 583 584 585 586 587 588 589 590 591 592 593 594 595 596 597 598 599 600 601 602 603 604 605 606 607 608 609 610 611 612 613 614 615 616 617 618 619 620 621 622 623 624 625 626 627 628 629 630 631 632 633 634 635 636 637 638 639 640 641 642 643 644 645 646 647 648 649 650 651 652 653 654 655 656 657 658 659 660 661 662 663 664 665 666 667 668 669 670 671 672 673 674 675 676 677 678 679 680 681 682 683 684 685 686 687 688 689 690 691 692 693 694 695 696 697 698 699 700 701 702 703 704 705 706 707 708 709 710 711 712 713 714 715 716 717 718 719 720 721 722 723 724 725 726 727 728 729 730 731 732 733 734 735 736 737 738 739 740 741 742 743 744 745 746 747 748 749 750 751 752 753 754 755 756 757 758 759 760 761 762 763 764 765 766 767 768 769 770 771 772 773 774 775 776 777 778 779 780 781 782 783 784 785 786 787 788 789 790 791 792 793 794 795 796 797 798 799 800 801 802 803 804 805 806 807 808 809 810 811 812 813 814 815 816 817 818 819 820 821 822 823 824 825 826 827 828 829 830 831 832 833 834 835 836 837 838 839 840 841 842 843 844 845 846 847 848 849 850 851 852 853 854 855 856 857 858 859 860 861 862 863 864 865 866 867 868 869 870 871 872 873 874 875 876 877 878 879 880 881 882 883 884 885 886 887 888 889 890 891 892 893 894 895 896 897 898 899 900 901 902 903 904 905 906 907 908 909 910 911 912 913 914 915 916 917 918 919 920 921 922 923 924 925 926 927 928 929 930 931 932 933 934 935 936 937 938 939 940 941 942 943 944 945 946 947 948 949 950 951 952 953 954 955 956 957 958 959 960 961 962 963 964 965 966 967 968 969 970 971 972 973 974 975 976 977 978 979 980 981 982 983 984 985 986 987 988 989 990 991 992 993 994 995 996 997 998 999 1000 1001 1002 1003 1004 1005 1006 1007 1008 1009 1010 1011 1012 1013 1014 1015 1016 1017 1018 1019 1020 1021 1022 1023 1024 1025 1026 1027 1028 1029 1030 1031 1032 1033 1034 1035 1036 1037 1038 1039 1040 1041 1042 1043 1

[illegible]

978-979 small extent nearly white - brown wood above shade only, underneath

2. *Arctostaphylos* *uva-ursi* *diffusa* *Michx.* *var.* *uva-ursi*

五言古詩

and so on the American clergyman when he has become fully acquainted with the

find a *biograph* *original* *history* of *the*

with the same of course and with the same result. The same result is obtained with the same of course and with the same result.

children and the priest and women perhaps thinking the two parts were

April 2nd 1861

island. It is found in series with shells about the same but - shells -

[illegible]

color possible & however color shift. Assume open white? - open in (5) open all?

*The first part of the manuscript is written in a cursive hand, and contains the following text:*

Answers given below are often

middle upper boundary has width  $\frac{1}{2} \times 0.5 \times 0.18$  millibars equal half inch difference of 1.5

1892

*Siphonophora* - *Physalia physalis* - *Velella velella*

48. 5/14/12. 000000 TEST. 20°C old. Unknown info. original returned. This is double.

上  
下  
中  
下  
中  
上

White paper - white mud -  
- - - - -

not a lot and shows well. Brown open water. Amphibian and - bird. 1945

111

no more advanced. still not good. still some more will be - 200000

filled almost with new supplies and almost to

Protona color magis. Hylar abnormis. - Placenta

[illegible]

... paper & was very much improved about Nov. 9. ...  
... ..

*[Faint handwritten notes or bleed-through from the reverse side]*

Ammonia  
from 2501. Ammonia about 58 and mixed 671 - 1000  
Ammonia

1. 1000  
 2. 1000  
 3. 1000  
 4. 1000  
 5. 1000  
 6. 1000  
 7. 1000  
 8. 1000  
 9. 1000  
 10. 1000

671 - 13 25 "

of hand and puts 33 feet to opposite end

one - amount owed - 1000 dollars

44444444  
 4444  
 44444444  
 44444444  
 44444444

[illegible]

(see verso of volume)

Cell  
Engineering