

Report of Survey for Repairs, &c., of Engines and Boilers. No. 45575

Date of writing Report 25th Sept. 19 44 When handed in at Local Office 25th Sept 19 44 (Received at London Office 17 NOV 1944)  
No. in Survey held at New York Port of New York  
B. Book 24227 on the Machinery of the XXXXXX Steel Date, First Survey 16th Sept Last Survey 16th Sept. 19 44  
5551 S.S. "FLOMAR" (No. of Visits 2)

Age { Gross	5551	Vessel built at	Portland, Or.	By whom	Columbia River S.B. Corp.	Year.	Month.
Net	3422	Engines made at	Los Angeles, Calif.	By whom	Llewellyn Iron Works	When	1919 11
Indicated Power	582	Boilers, when made (Main)	1919		(Donkey)	-	When 1919
No. of Main Boilers	3	Owners	Calmar S.S. Corp.	Owners' Address			
Donkey Boilers	-	Managers	-	(if not already recorded in Appendix to Register Book.)			
Pressure—Main Boilers	210 lbs.	If Surveyed Afloat or in Dry Dock	Afloat	Port	New York	Voyage	
Donkey Boilers	-	(State name of Dock.)	Pier 58, New York	Particulars of Classification (which must be inserted precisely as in Register Book.)			

[illegible]

as not done, state for what reasons? \_\_\_\_\_ Not submitted for survey

What special means, in the absence of internal examination, were adopted by the }  
Inspector to assure himself of the thorough efficiency of those parts of each Boiler? {

st date of internal examination of each boiler.....

Present condition of funnel(s).....

urveyor examine the Safety Valves of the Main Boiler?.....

To what pressure.....

Surveyor examine the Safety Valves of Donkey Boiler? ..... To what pressure were they afterwards adjusted under steam? .....

Surveyor examine all the manholes, doors and their fastenings of the Main Boiler? ..... To what pressure were they afterwards adjusted under steam? .....

Inspector examine the drain plugs of the Main Boilers?....., and of the Donkey Boilers?.....

Inspector examine all the mountings of the Main Boilers?....., and of the Donkey Boilers?.....

shaft now been drawn and examined? No Is it fitted with continuous liner? Is an approved appliance fitted at the after end of the shaft to permit of its being efficiently

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? ☐

State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft. \_\_\_\_\_

Is electric light and/or power fitted? \_\_\_\_\_

insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms?—

is stated to have been sustained on Sept. 14, 1944, while berthed at Pier 58, North River, when New Central barge "Fordham" and Erie R.R. Barge 350

ONE: The propeller was under water and was

water and was examined by diver, who reports no visible damage.  
py of diver's report attached. The main engines turned over and found in order.

Observations, Opinion, and Recommendation:— The machinery of this vessel, so far as now nearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and the alteration required to be made in the records of the vessel's machinery, boilers, working pressure, &c.

is in safe working condition and is eligible, in my opinion, to remain as now classed with  
fresh record of survey.

.....

(under Section 29) \_\_\_\_\_  
 License or Repair Fee (if any) \_\_\_\_\_  
 (under Section 29.) \_\_\_\_\_

\$ - : : Fees applied for  
 \$ - : : \_\_\_\_\_ 19 \_\_\_\_\_

Certificate

Expenses (if chargeable) ..... £ - : :  
 Received by me, .....  
 19.....  
 J. A. Moore © 2019  
 Engineer Surveyor to Lloyd's Register of Shipping.

As now

W312-0203



© 2019  
Lloyd's Register  
Foundation