

FACTS AND DELIVERIES ARE SUBJECT TO THE USUAL STRIKE CLAUSES, ACCIDENTS TO MACHINERY AND OTHER UNFORESEEN CIRCUMSTANCES.

Telephone, Nos 962 & 963. Telegrams, "CONDENSER, DUNDEE."

Codes { LIEBERS 5 LETTER CODE.
A B C 5TH EDITION.



GREIG LTD.,

Engineers
makers.

IRALTY
D
CE LISTS.

H. M. GOVERNMENT.

TO BE ADDRESSED
COMPANY

BRITANNIA WORKS,
EAST DOCK STREET,

DUNDEE.

TBC/EM

7th January, 1921.

Mrs. Lloyd's Register of Shipping,
71, Fenchurch Street,
London, E.C.

LLOYD'S REGISTER,
LONDON.

REC'D 10 JAN 1921

ANSD

Sirs,

We are in receipt of Classification Certificates for
entry of s.s. "Rowanpark" and s.s. "Sunspot", for which we
are obliged.

We wish, however, to refer to the condition added to
Certificate of the s.s. "Rowanpark" concerning leakage in
Main Boilers. We may say that this is the first instance
in our experience where any condition has been laid down and we
are of opinion that if it was thought necessary to make special
mention of anything of this nature, the point should have been
particularly brought forward before Boilers left our hands and
the opportunity given to us to put the matter right. We may also
say that we are of the opinion that we have been unfairly

Yours,
ed/



Lloyd's Register
Foundation

W338-0066 (1/3)

Spacing
Bridge Deck, Angle, Bulb Angle, Plate, }
Tee Bulb, or Channel.....

Forecastle Deck Stringer Plate, Edth

- 2 -

Register of Shipping.7.1.21.

ted in this matter and we think you will agree that a Builder
ot very well forward such a certificate to Owners and expect
to be satisfied. The leakage referred to was made good
e Lloyd's Surveyor left this Vessel after the Trial trip and
as asked to satisfy himself that this had been done. The
s in question are machine rivets and are a splendid job, the
being countersunk as in the case of hand rivets but it had
been thought necessary to set up the heads in way of the bottom
filers. There were not more than two rivets leaking in each
r - in fact on one Boiler our man reported only one leaking,
very slightly, so slight in fact that, as already stated, they
entirely tight after having been knocked up with the head of
mar, but over and above this, we sent our man to the Tyne to
them properly set up before Vessel left on her first voyage.

We think the fact of these rivets being machine rivets
were absolutely tight during hydraulic tests before leaving
- not even requiring to be set up for this purpose - should
been sufficient guarantee to Lloyd's Surveyor who attended
trip that they were absolutely sound and a good job.

We really think it is most unfortunate that such stress
been put upon such a small matter as this and feel quite sure

Referred to the Chief Engineer Surveyor.

Referred to the Chief Engineer Surveyor.

ad.
10 Oct 1921

For A. Wood
Referred to Mr. Mayne.

SPL

W. G. Clark



© 2020
Lloyd's Register
Foundation