

## REPORT OF SURVEY FOR REPAIRS, &amp;c., OF ENGINES AND BOILERS

(Received at London Office)

3 OCT 1941

Date of writing Report	When handed in at Local Office	30. 9. 1941	Port of Glasgow.
No. in Survey held at	Glasgow.	Date. First Survey	29. 4. 41
Reg. Book. No. 23305	on the Machinery of the Wool, Iron or Steel Sc "Empire Tarpon"	Last Survey	20th Sept 1941
Tonnage { Gross 6085	Vessel built at Groton Conn. By whom Groton Iron Works	(No. of Visits) 21	Year. Month. When 1920-12
Net 3748	Engines made at Jersey City. By whom Vulcan Iron Works		When 1920
Nominal Horse Power 684	Boilers, when made (Main) 1941 (Donkey) ✓		
No. of Main Boilers 3 M.T.	Owners Ministry of War Transport	Owners' Address	
No. of Donkey Boilers ✓	Managers Douglas & Ramsay.	Port London Voyage	
Steam Pressure in Main Boilers 225 lbs	If Surveyed Afloat or in Dry Dock Yes		
in Donkey Boilers ✓	(State name of Dock) King George V Dock		

Report No. 63700 Port

## Particulars of Examination and Repairs (if any) of Machinery before and after Survey

Surveys, when held, must be reported in detail and scat in the terms of the Rules. State clearly the repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on damage (the cause of which must be stated) should be separated from Repairs due to other causes; and being detailed in the body of the report, should be briefly summarised at the end of the report. State also the initials of any letters respecting this case.

In cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined.

damage report made by anyone else? If so, by whom?

Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? Yes

Donkey, ✓

was not done, state for what reasons

what parts of the Boilers could not be thus thoroughly examined?

what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

last date of internal examination of each boiler Starb 12.8.41, Port 15.8.41 Centre 19.8.41

CHARACTER. * for Special Survey Date of last Survey and of Periodical Surveys.	Machinery and Boiler Surveys (including date of N.B., if any).
Years assigned below expired.	
+100 A.I.	L.M.C. 1-41
Reclassification	C.L.
Contemplated 5th.	(1)
Examined 2-41	Fitted fuel oil fuel 12-20 F.P. above 150° Fahr

- Surveyor examine the Safety Valves of the Main Boiler? Yes To what pressure were they afterwards adjusted under steam? 225 lbs per sq. in
- Surveyor examine the Safety Valves of Donkey Boiler? ✓ To what pressure were they afterwards adjusted under steam?
- Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? ✓ Yes, and of the Donkey Boilers?
- Surveyor examine the drain plugs of the Main Boilers? none, and of the Donkey Boilers?
- Surveyor examine all the mountings of the Main Boilers? ✓ Yes, and of the Donkey Boilers?

the screw shaft now been drawn and examined? No Is it fitted with continuous liner? ✓ Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

shaft now been changed? ✓ If so, state reasons. ✓ Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

the shaft now fitted been previously used? ✓ Has it a continuous liner? ✓ Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

date of examination of Screw Shaft ✓ State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft

Engine parts, when referred to by numbers, should be counted from forward. Is electric light and power fitted Yes

did the Surveyor examine the generators, motors, switchgear, cables and fuses?

the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms?

Survey is not complete, state what arrangements have been made for its completion and what remains to be done Complete.

done. Three water tube boilers removed ashore and replaced by three new water tube Babcock & Wilcox boilers. (See Glasgow F.E. Report No. 64433) Boiler mountings removed from old boilers.

examined hydraulically tested and fitted to new boilers.

These boilers after being satisfactorily erected on board were hydraulically tested to 380 lbs per sq. inch and found sound & tight.

Safety valves afterwards adjusted under steam to 225 lbs per sq. inch and found satisfactory. Oil fuel installation examined under working conditions and found good. H.P & L.P. turbines

opened up. Casings and rotors examined and found good. P.T.O.

General Observations, Opinion, and Recommendation:—The machinery of this vessel

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B. 9.11, B.M.S. 9.11, \*L.M.C. 9.11, or \*L.M.C. 140 lb. F.D., &c.)

as far as now seen is in a safe working condition and eligible in my opinion to remain as classed and to have the notation + N.B. 941.

Survey Fee (per Section 29) £ : : Fees applied for 1 OCT 1941

Special Damage or Repair Fee (if any) £ 12.12.0 Received by me,

Travelling expenses (if chargeable) £ : : 19

Committee's Minute GLASGOW 1 OCT 1941

Assigned. Referred

- NB 9.41 (W10)

G. S. Murdoch  
Engineer Surveyor to Lloyd's Register of Shipping.

MADE AND PRINTED IN ENGLAND  
(The Surveyors are requested not to write on or below the space)

Is a Certificate required? If so, to be sent to

S.E.U.10

S. S. Empire Tarpon

pt. 5

Main condenser re-tubed and hydraulically tested. Auxiliary condenser re-tubed with the best tubes removed from the main condenser and hydraulically tested. Dual air pump examined. Two independent feed pumps renewed. Forward and after dynamo engines removed ashore completely overhauled afterwards placed on board and tested under full load.

Now done. See London letter 9/8/41.

Four three inch holes have been cut in the funnel clamps. The uptake dampers have been removed, and the following notice has been placed in the stokehold in a well lighted position:

- (1) When lighting up from cold, the funnel damper must be opened at least 10 minutes previously in order to clear the bosome and uptakes of any gases which may have accumulated.
- (2) When steam is available, the fan is to be run with the funnel damper closed, before lighting or re-lighting the burners.

Repairs. Circulating pump top and bottom end bushes re-metalled after dynamo engine crank shaft renewed.

Forward and after dynamo engine governors renewed.

Two main steam and 2 feed pipes renewed.

G. T. Murdreh.

OK

OK

W.D.

Rebundled by Steamer to be  
asked to state why the  
Boilers were renewed &  
Main condenser retubed.

Noted  
rebundled by steamer to be  
asked to state why the  
Boilers were renewed &  
Main condenser retubed.

W.H.S. H.G.G.B.  
N.H.P. 7/54  
Delete (Set).

B.A.  
9/54

0-21-21

© 2020



(S1W) 14.12.20

Lloyd's Register  
Foundation