

Lloyd's Register of British and Foreign shipping

2 JAN. 93


4 Commercial Buildings.

Calcutta, the 27<sup>th</sup> September 1892

This is to certify that

J. D. Mc Kellar \_\_\_\_\_ the  
undersigned Surveyor to this Society did at the  
request of Messrs Turner Morrison & Co., and Captain of  
Atkinson, on the 19<sup>th</sup> September 1892, proceed to the ship the Osborne lying in the Port Commissioners new dry Dock at  
Fidderpore to survey the bottom of that vessel and report on  
the damages under water, and on other days subsequent to that  
date, surveyed in conjunction with Captain Mc Gregor, Second  
Surveyor, the damage in the lower hold of the vessel, the whole  
of the salt cargo having been discharged, the sparring battens  
removed and all the floor and bilge ceiling which is fitted  
in stanches except at the ends, and the planking adjoining  
the Keelsons lifted, and the Hold washed down with fresh  
water, and having made most careful surveys now report  
as follows:-

The after bolts of the third strake of plating from the  
Keel (C Strake), on each side, are open and the rivets slack  
and the butt straps started from the plating. The two butt  
straps should be taken off, refitted and the rivet holes gaiced  
and re-riveted and the butt puttied and caulked. Almost  
all the bolts of the Garboard strakes on each side are weeping  
and many of the Keel rivets are slack, specially at the <sup>221</sup> bolts



Lloyd's Register  
Foundation

W35782-00154

of the Garboard Strakes and the Keel rivets in the Fore part, in the forward length of Garboard Strake, are quite slack from the butt up to the forward end of the plate and water leaking from between the Keel and plates on both sides. The Keel rivets from stem to stern should be carefully examined and all slack rivets taken out and replaced with sound ones. A large number of bolts under the bottom and on the bilges on each side are showing moisture, and there are many rivets in the bottom plating and butt rivets apparently slack. Many of the intercostal Rivets & rivets on the port side aft under the after hatchway are slack and the plates appear to be very slightly set upwards at that place as if the vessel had rested or struck on something. The bottom should be scraped to the bare iron now and ast on both sides, and all rivets which have the appearance of being slack or defective should be examined and those found slack or defective should be taken out and replaced with sound rivets, and the bolts & showing moisture should be puttied and caulked, and when the repairs are completed the bottom should be painted with three coats of white zinc paint up to the second strake of plating from the gunwale and a coating of white zinc and tallow mixed up to the 21st mark.

On the Starboard side the forward end of the fifteenth or length of Garboard strake plating from the sternpost is fractured at the butt in the knuckle of the plate, the fracture is about seven inches long and is leaking, this should be covered with a piece of steel plate tapped on to the Garboard strake over the fracture, and a small hole drilled at the end of the fracture to prevent it from extending, and filled with a tapped bolt. The two plates of the Garboard strake on the same side are fractured in the same way, vizt., the forward ends of the 5<sup>th</sup> and 9<sup>th</sup> plates from ast, but these need not be patched but tapped bolts put in the ends of the fracture and the fractures puttied and caulked.

On the Port side on the third strake of plating from the Keel, about thirty feet from the stern the plate is bent between

W35782-0015 2/4



©2021

Lloyd's Register  
Foundation

the frames to the extent of about an inch deep, and two or three of the frame rivets started and the cement inside is broken as if the plate had received a blow or rested on something. The cement should be cut out and the slack and defective rivets changed.

A large number of frame rivets in the bilges on both sides, specially on the starboard side, immediately above the close ceiling, from the foremast to between the mizen and jigger masts are very slack. All the frame rivets fore and aft on each side from the cement up to the tweendeck stringers must be carefully tested and all slack and defective rivets changed.

Binding on previous surge that many of the rivets were slack and bolts leaking in the lower hold I recommended that the spurring buttons should all be removed and the sides scraped to the bare iron from the tweendecks down to the bottom cement, and that all the floor ceiling should be lifted, being mostly all in Hatches, fore and aft, for examination of the cement, and that recommendation has been carried out. The centre and side weldons and many of the floors and reverse angles of floors were much rusted apparently by the brine from the salt mixing with the leakage through the bottom and washing up against them. All should be scraped clean and recated with paint and cement.

Some rivets in nearly all the butt straps of the angle stringers in the lower hold are slack and the bolts of many of the angles are drawn. Many of the rivets connecting the two angles and intercostal plates of the stringers in the lower hold and some of rivets in the intercostal angles & through the sides and the vertical rivets of the intercostal angles, and the rivets connecting the stringer angles to the reverse bars of frame are slack. All the stringers should be carefully examined and any slack or defective rivets found should be taken out and replaced with sound rivets, and when the bolts of the angles are drawn they should be fitted up with liners. One bolt of the lower angle, middle stringer, on the starboard side, abt the main mast, is drawn open, about  $\frac{1}{4}$  inch, and the bottom angle butt strap is started. The butt strap should be taken off and the butt fitted up with a liner, and a new angle butt strap worked on long enough to take three frames and should be closely fitted and well riveted.

N35782-00015<sup>3/4</sup>



Lloyd's Register  
Foundation

The after end of the vessel appears to have vibrated and panted very much. The rivets in the stringer angles and in the after end of the twelfth stringer plates are slack and the breast plate on the middle stringers is buckled and seven frame angles on each side, viz: from the third to the tenth frame forward as the after end of centre keelson are fractured on the vertical web of the frame at and below the top of floor plates and the reverse bars on the ninth frame on both sides are fractured. To compensate for those fractures the two after frames on each side, viz: the third and fourth frames forward of the after end of centre keelson, being straight frames, should have  $\frac{5}{8}$ " fish plates about 3. 6 long worked over the fractured parts and fitted close into the bosom of the frame angle and riveted through with six rivets. The other frames, of which are fractured in two places should have bracket plates worked over the floor plate well up on the frame above the floor plate, the edges of the plates well fitted against the bosom of the frame angle and riveted to the frame angle and to the floor plate, the cement in the chamber to be cut and to admit of the bracket plates and fish plates being fitted well down on the frame angle, a similar bracket plate should also be fitted on the eleventh frame angle from the end of keelson, in order to repair this damage the close ceiling aft must be removed and refitted or renewed when the repairs are completed.

To counteract the panting in the after end of the vessel, after a careful survey in conjunction with Captain M<sup>c</sup> Gregor and on consultation with Captain Atkinson and Mr. Collett of the firm of Messrs John Smeed & Co., Engineers and Contractors, I decided that six Panting Beams should be fitted immediately below the Bulbous intercostal stringer, about half way between the keel and the twelfth, that is the continuation right aft, of the stringer above the Dilge. The Beams to be composed of two angle bars  $5\frac{1}{2} \times 3\frac{1}{2} \times \frac{1}{8}$ , riveted back to back and to have  $\frac{5}{8}$ " bracket plates fitted between the angles at the ends to connect the Beams to the frame and to have stringer plate at the ends, 21 inches broad by  $\frac{5}{8}$ " thick, extending from the breast plate at the after end to the fourth frame forward of the sixth beam, the projecting ends to be supported by bracket plates riveted to the frame angles.

N 35577 B 22-001547



© 2021

Lloyd's Register  
Foundation

angles and stringers. The stringer plates to be riveted to the beams and connected to the sides with angle bars, fitted on top of stringer plates and to the reverse bars at frames, and riveted to the reverse frames and lug pieces with two rivets in each frame and riveted to the stringer plates in the usual way. The four forward beams to be supported in the middle with pillars 3" diameter riveted to the beam and to the side Nelson. The after ends of the stringer plates to be connected to a breast plate 3. 6 long x  $\frac{3}{8}$  thick, fitted between the double angle bars and joined with double riveted butt straps, the lower angle to be formed like a Breast hook to take two frames on each side and riveted thereto and to the gusset plate of the frame at the after end.


The first side Nelson extends right aft and is connected with a breast plate 2. 9 long, that breast plate to be extended further forward by riveting another plate four feet broad, lapped over the original breast plate and double riveted thereto.

The second side Nelson terminates, on the lower angle, two frames and on the upper angle six frames abaft the gigge mast, and is to be extended right aft with two angle bars  $5\frac{1}{2} \times 3\frac{1}{2} \times \frac{3}{8}$  riveted back to back and to the reverse bars at the frames, to reverse bar lugs fitted on the frames for that purpose, having four rivets in each frame, the new length will be about 35 feet on each side. The ends to be connected with a breast plate 2 feet long fitted between the two angle bars of the stringers and through riveted.

The breast plate in line of tweendeck to be extended to the aftermost tweendeck beam and riveted to the stringer plates on each side and to the beam, and all the slack rivets in the original breast plate and tweendeck stringers, of which there are a large number, must be taken out and replaced with sound ones. To admit of this being done the tweendeck must be removed at the after end and replaced or renewed as required after the repairs to stringers are completed.

In my opinion the above mentioned additional strength will efficiently counteract the extreme panting and vibrating at the after end of the vessel experienced on the passage out. - © 2021

There is slight leakage in the main deck at the wings.



Lloyd's Register  
under  
Foundation

EF 001554  
12855732

under the forward part of poop, where the spaces between the frames are filled with cement, the cement appears to have started, probably, by the working of the Stop at sea, and should be cut out and the spaces either re cemented or filled with wood and caulked.

Observe that many of the nuts of the deck fastening bolts under the iron deck and on the beams are slack and not up against the iron. They should be all examined and secured tight up to the iron deck.

In the spaces between the floors from the main mast to the collision bulkhead the cement is hollow and broken in many places, this is also the case from the Mizzen mast aft and should be cut out where defective and re cemented.

As anticipated on my former survey I find that many of the floor ceiling Hatches and the fixed ceiling adjoining the Keelsons have been split and damaged by being washed up by the water in the bilge and will have to be repaired as already recommended for the first portion. A number of the cap pieces of the ceiling on the bilge are also washed off and must be replaced and cemented over as before.

The three forward tweendeck scupper pipes on the starboard side are bent buckled and fractured close up to the deck must be cut and new upper parts flanged and fitted and connected with plumbers joints.

The whole of the plates angles and stringers in the lower hold from the bilge ceiling up to and inclusive of the tweendeck stringer, and the beam ends having been scraped to the bare iron will have to be recoated with three coats of good zinc paint and also all the new beams, breast plates and all new iron work in the after end.

I also recommend that all the butt straps in the two strakes of plating above the Bilge ceiling should be covered with cement about an inch thick, and that some (about ten butts) of the butts of the second strake of plating from the gunwale ~~should be~~ <sup>202</sup> cemented over on the lower part by spreading the cement between

357821-001567

1

the frames higher up to cover the lower parts of the butts.

The stay from the starboard forward corner of the fresh water tank to the beam, being broken must be taken down, repaired and riveted and reriveted.

Survey fee  
No 208 }

*A. M. Fullerton*

W35782-00152/4



© 2021  
Lloyd's Register  
Foundation