

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office 20 JUL 1933)

Date of writing Report 20 JUL 1933

When handed in at Local Office

20 JUL 1933

Port of LONDON.

No. in Reg. Book. Survey held at Purfleet Date, First Survey and, Last Survey 1933 July 1933
23815 on the Machinery of the Wood Iron or Steel CLAN MACNAB
 Tonnage { Gross 6076 Vessel built at Irvine By whom Argshire Dryd C^o Ltd. When 1920-12
 Net 3705 Engines made at Glasgow By whom Dunsmuir & Jackson Ltd. When 1920
 Nominal Horse Power 692 Boilers, when made (Main) 1920 (Donkey) 1920
 No. of Main Boilers 3 Owners The Clan Line Steamers Ltd. Owners' Address Glasgow
 No. of Donkey Boilers 1 Managers Carter, Irvine & C^o Ltd. Port Glasgow Voyage Glasgow
 Steam Pressure in Main Boilers 200 lbs If Surveyed Afloat or in Dry Dock Afloat - Purfleet
 in Donkey Boilers 100 lbs (State name of Dock.)

Last Report No. 1125 Port BatParticulars of Examination and Repairs (if any) Engine Repairs

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined

Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? NoDo. " Donkey " " " NoIf this was not done, state for what reasons? Boilers not offered for survey.

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

State latest date of internal examination of each boiler

Did the Surveyor examine the Safety Valves of the Main Boiler?

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? - and of the Donkey Boilers?Did the Surveyor examine the drain plugs of the Main Boilers? - and of the Donkey Boiler?Did the Surveyor examine all the mountings of the Main Boilers? - and of the Donkey Boiler?Has screw shaft now been drawn and examined? - Is it fitted with continuous liner? - Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? -Has shaft now been changed? - If so, state reasons -Has the shaft now fitted been previously used? - Has it a continuous liner? - Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? -State date of examination of Screw Shaft - State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft -If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done Complete.

Now done:- Repair to hollow cone shaft examined. Shrink on rings on coupling flanges & bolted clamps around shaft examined & tested & found to be efficient as a temporary repair.

The engine crankshaft & intermediate shaft was examined as far as practicable without dismantling. The engine crankshaft appears to be somewhat down as compared with the intermediate shaft & it is now recommended that the shafting be tested for alignment upon the vessel's arrival at Glasgow where it is stated by the 2nd Engineer, permanent engine repairs will be effected.

General Observations, Opinion, and Recommendation:-

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 911, B.&M.S. 911, or L.M.C. 911, 120 lb., F.D., &c.)

The machinery of this vessel is eligible in my opinion to remain as classed, subject to hollow conical shaft being renewed & shafting being tested for alignment upon the vessel's arrival at Glasgow where she is now bound via home ports.

Survey Fee (per Section 29) £ :
 Special Damage or Repair Fee (if any) £ :
 Travelling expenses (if chargeable) £ :
 Fees applied for
 Received by me,
 19

Committee's Minute

Assigned

TUE. 1 AUG 1933

WED. 4 APR 1934

Engineer Surveyor to Lloyd's Register of Shipping.

Lloyd's Register Foundation

W377-0237