

## Report of Survey for Repairs, &amp;c., of Engines and Boilers.

(Received at London Office

MAY 21 1940

Date of writing Report

When handed in at Local Office

20 MAY 1940

Port of

HULL

No. in Survey held at

Hull

Date, First Survey

and. Last Survey

2.5. 1940

(No. of Visits one)

Reg. Book.

07011 on the Machinery of the Wood, Iron or Steel

K. DUNGNESS

Tonnage } Gross 263  
Net 103

Vessel built at

Selby

By whom

Bochane &amp; Sons. Ltd

When 1914 11

Engines made at

Hull

By whom

Amos &amp; Smith Ltd

When 1914 11

Nominal Horse Power } 78 A.H.P.

Boilers, when made (Main)

1914

(Donkey)

No. of Main Boilers

One

Owners

Tribent Steam Fishing Co. Ltd

Owners' Address

(if not already recorded in Appendix to Register Book.)

Port

Hull

Voyage

Fishing

No. of Donkey Boilers

nil

Steam Pressure in Main Boilers

200 lb

Managers

J. A. Ledger

If Surveyed Afloat or in Dry Dock

St Andrew Dr

(State name of Dock.)

in Donkey Boilers

✓

Last Report No.

Port

Particulars of Examination and Repairs (if any) Elect. install.

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined

Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Did the Surveyor personally go inside each Donkey Boiler separately and make a thorough examination at this time?

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

State latest date of internal examination of each boiler

Did the Surveyor examine the Safety Valves of the Main Boiler?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?

Did the Surveyor examine the drain plugs of the Main Boilers?

Did the Surveyor examine all the mountings of the Main Boilers?

Has screw shaft now been drawn and examined?

Has shaft now been changed? If so, state reasons

Has the shaft now fitted been previously used?

State date of examination of Screw Shaft

Engine parts, when referred to by numbers, should be counted from forward.

If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses?

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms?

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done

Now done

a new 6 Kw. 110v. dynamo

has been fitted in place of old generator

required for de-Gaussing apparatus.

General Observations, Opinion, and Recommendation:— The machinery of this vessel, so far as now seen, is in an efficient condition and eligible in my opinion to remain as now classed, without fresh record of survey.

Survey Fee (per Section 29) £ : :  
Special Damage or Repair Fee (if any) £ : :  
Travelling expenses (if chargeable) £ : :  
Fees applied for  
19  
Received by me,  
19

Committee's Minute

Assigned

+ 11.39  
Subject

John Douglas

Engineer Surveyor to Lloyd's Register of Shipping.

Lloyd's Register  
Foundation

W383-0044