

## Report of Survey for Repairs, &amp;c., of Engines and Boilers.

(Received at London Office)

APR 24 1940

Date of writing Report 22<sup>nd</sup> April 1940. When handed in at Local Office 23<sup>rd</sup> April 1940. Port of CARDIFF.No. in Survey held at Cardiff Date, First Survey 29<sup>th</sup> Jan Last Survey 12<sup>th</sup> April 1940. No. of Visits 13.

38961 on the Machinery of the Wood, Iron or Steel SCREEN 'ELMCREST' ex 'Jagled'

Tonnage Gross 4343 Vessel built at Newcastle By whom W. Dobson &amp; Co. When 1911. 3.

Net 2659 Engines made at Newcastle By whom W. B. Mac Eneaney &amp; Co. Ltd. When 1911.

Nominal Horse Power 342 Boilers, when made (Main) 1911 (Donkey)

No. of Main Boilers 3 Owners Best Shipping Co. Ltd. Owners' Address

No. of Donkey Boilers 1 Managers Commercial D.D. Port London Voyage

Steam Pressure in Main Boilers 180 lbs. Surveyed Afloat in Dry Dock South Dock Basin Particulars of Classification (which must be inserted precisely as in Register Book &amp; Supplements).

in Donkey Boilers Last Report No. Port PART M.S.

Particulars of Examination and Repairs (if any) B.S.; T.S.; DMGE. 100A 1.6.39

Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case. 10-1-40 (M)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined Offered Not required.

Was a damage report made by anyone else? If so, by whom? Yes. See also Surveyor.

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? Yes.

" " Donkey " " " "

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

State latest date of internal examination of each boiler C. &amp; ST. 6/2/40 PT. 27/2/40. Present condition of funnel Good.

Did the Surveyor examine the Safety Valves of the Main Boiler? Yes. To what pressure were they afterwards adjusted under steam? 180 lbs/sq"

Did the Surveyor examine the Safety Valves of Donkey Boiler? Yes. To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? Yes. and of the Donkey Boilers?

Did the Surveyor examine the drain plugs of the Main Boilers? Yes. and of the Donkey Boilers?

Did the Surveyor examine all the mountings of the Main Boilers? Yes. and of the Donkey Boilers?

Is screw shaft now been drawn and examined? Yes. Is it fitted with continuous liner? Yes. Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? Yes.

Is shaft now been changed? No. If so, state reasons

Is the shaft now fitted been previously used? Yes. Has it a continuous liner? Yes. Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? Yes.

State date of examination of Screw Shaft 10.2.40. State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft R. Wooded.

Engine parts, when referred to by numbers, should be counted from forward. Is electric light and/or power fitted Yes.

So, did the Surveyor examine the generators, motors, switchgear, cables and fuses? Yes.

Is the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? Yes.

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done To complete M.S., main

engine cylinders, pistons &amp; valves, Auxiliary machinery, pumping

arrangements, Steam pipes, &amp; windlass engine to examine. Stated the

Survey will be advanced at the first opportunity.

Now done. Vessel drydocked, &amp; outside fastenings examined &amp;

found satisfactory. Main boiler examined throughout,

and found in good order. Safety valves adjusted under

steam to 180 lbs/sq"

Now done on account of stated grounding near Old Stairs Bay

7<sup>th</sup> Jan. 1940, on voyage Lisbon to Antwerp: - Propeller, sea

connection valves &amp; cocks, condenser under test, crank. (cont)

General Observations, Opinion, and Recommendation:—

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &amp;c.; thus, for example, B.S. 9.11, R.A.M.S. 9.11, &amp; L.M.C. 9.11, or

L.M.C. 140 lb., F.D., &amp;c.)

The machinery of this vessel, so far as now seen, is eligible in my opinion

to remain as classed with fresh records of B.S. 4.40 &amp; propeller shaft.

See C.L. 2.40. Record of M.S. (with date) to be deferred until completion

of the Survey as above. Subject to governor being fitted to dynamo engine at

the first opportunity &amp; to main engine

bedplate being re-examined before

the end of April 1941.

Survey Fee (per Section 29) B.S. 4 0 0 Fees applied for 23 April 1940

Special Damage or Repair Fee (if any) L.M.C. Ins. 1 0 0 Received by me, 19

(per Section 29.) Damage 5 5 0

Travelling expenses (if chargeable) £

Committee's Minute TUE. 2 MAY 1940

Assigned Deferret

Engineer Surveyor to Lloyd's Register of Shipping.

Frank D. Richardson.

Lloyd's Register  
Foundation

W386-0078

1/2



Port of Cardiff. Continuation of Report No. 5339/1. dated 22<sup>nd</sup> April 1940 on the

STEEL SCREW "ELMCREST"

Thrust, & tunnel shafts and bearings examined. Propeller shaft drawn in & examined. Stern bush examined.

Now done on account of stated heavy weather 1<sup>st</sup> & 2<sup>nd</sup> Jan. 1940, on voyage Lisbon to Waymouth:- Steering engine examined & found satisfactory.

Now done on account of stated fire damage in bunker 'ween deck space, (S.S.), no particulars available:- Electric cables partly renewed, installation megger tested & found satisfactory on completion of repairs; dynamo examined under working conditions.

There is no governor fitted to the dynamo engine. The Owners' Superintendent has requested that all items as above, examined on account of damage, be credited towards the Machinery Survey.

REPAIRS (Dmg.)

- Tips of propeller blades dressed.
- Lower half of stern bush rewooded.
- New Key fitted to propeller shaft.
- S.p. engine bottom end bearings re-metalled.
- Car thrust shaft shot re-metalled.

REPAIRS (W&T.) Minor repairs to boiler mountings carried out. Electrical installation wiring etc. examined & repaired as found necessary.

S.R. LIST:- Crack in main engine bed plate in way of No. 1 bearing examined. Repair remains efficient. It is submitted that this be re-examined in 12 months time.

*Y.H.*

