

Report of Survey for Repairs, &c., of Engines and Boilers.

No. 15,923.

FRI. MAR. 30 1921

(Received at London Office)

Date of writing Report 28th March 1921 When handed in at Local Office 28th March 1921 Port of Lith
 No. in 156 Survey held at Lith Date, First Survey 17 Feb 1921 Last Survey 25th March 1921
 on the Machinery of the Wood, Iron or Steel S.S. "Deedimona" Master James Wilson
 Gross 1225 Vessel built at Lubeck By whom Schiffers v. Hart Koch When 1911
 Net 700 Engines made at Altona By whom Ottosen When 1915
 Registered 124 Boilers, when made (Main) 1914 (Donkey)
 Horse Power 2 Owners (J. Currie & Co. (Mgt)) Port London Voyage Hamburg
 No. of Main Boilers 2 If Surveyed Afloat or in Dry Dock Edinburgh & Alexandria Particulars of Classification (which must be inserted
 No. of Donkey Boilers 199 lb (State name of Dock.)
 in Main Boilers 199 lb
 in Donkey Boilers

Last Report No. Port L.M.C.

Particulars of Examination and Repairs (if any) L.M.C.
 Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

On damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined? Yes
 Was a damage report made by anyone else? If so, by whom? Yes

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? Yes

Do. " Donkey " " " " " " "

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler? Yes

To what pressure were they afterwards adjusted under steam? 500 lbs

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? Yes

, and of the Donkey Boiler?

Did the Surveyor examine the drain plugs of the Main Boilers? None

, and of the Donkey Boiler?

Did the Surveyor examine all the mountings of the Main Boilers? Yes

, and of the Donkey Boiler?

Has screw shaft now been drawn and examined? Yes

Is it fitted with continuous liner? Yes or two liners? ✓ or is it without liners? ✓

Has shaft now been changed? No If so, state reasons

or two liners? ✓ or is it without liners? ✓

Is the shaft now fitted new? ✓ Has it a continuous liner?

or two liners? ✓ or is it without liners? ✓

State the distance between lignum vitae of stern bush and top of after bearing of screw shaft? 5/32"

If the Survey is not complete state what arrangements have been made for its completion and what remains to be done? Complete

Cylinders, pistons, slides, pumps, condenser, crank, thrust, barrel & tail shafts, sea cocks & sea cock connections, propeller & stern bush, examined & put in good order

Main boilers carefully examined throughout & found in good order

Safety valves adjusted under steam to above pressure.

Crank shaft lifted, bottom bearings scraped up. No 3 & 3 top half main bearings re-metalled: A.O. bottom end re-metalled: condenser tested & found tight

main steam pipes taken down, cleaned out & tested by water to 600 lbs per sq. in.

special 2 1/2" large section fitted to Ballast Donkey: pumping arrangements

overhauled & tried on hold sections & found satisfactory: palisometer & test

cocks on both boilers renewed: double shut off cocks fitted at steam & water

ends of water gauge column pipes: water gauge column copper steam & water

P.T.O.

General Observations, Opinion, and Recommendation:—

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.: thus, for example, B.S. 9,11, B.&N.S. 9,11, or L.M.C. 9,11, 140 lb., F.D., &c.)

The machinery of this vessel is in a good & efficient condition, and eligible in my opinion to have a record of L.M.C. 3.21 in the Register Book, also notation for tail shaft 3.21. Main Boilers approved for a working pressure of 199 lbs per square inch

Survey Fee (per Section 25) £15
 Special Damage or Repair Fee (if any) (per Section 25.) £
 Travelling Expenses (if chargeable) £

Fees applied for
 per 19 to 4/10
 Received by me,
16-4-1921

Committee's Minute FRI. 22 APR. 1921

Assigned L.H.C. 321
C.L.

A. T. Thomas
 Engineer Surveyor to Lloyd's Register of Shipping.

FRI. 31 MAR 1921
 FRI. JUL 14 1922
 FRI. MAR 7 1924
 FRI. 27 MAR 1925

Lloyd's Register
 Foundation

Date of writing Report
No. in Survey
Reg. Book
on the

Master

Engines made at

Boilers made at

Registered Horse Power

Nom. Horse Power

ENGINES,

Dia. of Cylinder

Is the screw shaft

in the propeller

between the bed

liners are fitted

Dia. of Tunnel

collars 92

No. of Feed pipes

No. of Bilge pipes

No. of Donkey

In Engine Room

No. of Bilge

Are all the bilge

Are all connected

Are they fixed

Are they each

What pipe

Are all Pipes

Are the Bilge

Is the Screw

BOILER

Total Heat

Working

Can each

each boiler

Smallest of

Thickness

long. sea

Per cent

Size of

Length

Working

Pitch of

Material

Material

Area

Thick

Diam

Pitch

thick

Wor

Diam

Pitch

SUP.

Date

Dia

S. S. "Desdemona"

Pipes taken down cleaned out & annealed: with water showing in glass there was found to be about 3 1/2" of water above combustion chamber tops: a portion of one blade of propeller found broken off, but not in my opinion detrimental to its efficiency: a new one is now in hand: engines tried under steam on completion of overhaul & found to work satisfactory

The Superheaters have now been removed from both boilers

A. T. Thomas

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

General Observations, Opinion, and Recommendation.
The machinery of this vessel is in a good & efficient condition, and capable of performing its duty to the satisfaction of the Surveyor. The hull is in good condition, and the cargo hold is clean and dry. The stowage of cargo is in accordance with the regulations. The vessel is well equipped with stores and provisions, and is ready to receive cargo. The crew is well trained and experienced, and the vessel is well managed. The vessel is in good condition to receive cargo, and is ready to depart.

A. T. Thomas



© 2020

Lloyd's Register
Foundation