

REPORT of SURVEY for REPAIRS, &c.

of writing Report 8.9.1927 When handed in at Local Office 8.9.1927 Port of CARDIFF
No. in Survey held at Cardiff Date, First Survey 31st Aug Last Survey 8.9.1927
g. Book. on the Wood, Iron or Steel PRERADOYIC Master

23361 TONNAGE:- Built at Vegesack By whom Bremer Vulcan When 1907
GROSS 5341 Owners Jugoslavensko-Amerikanska Plovidba Port belonging to Split
UNDER DE. 5020 Owners' Address
NET 3418 (if not already recorded in Appendix to Register Book).

Surveyed Afloat or in Dry Dock? Afloat Name of Dock Queen Alexandra Destined Voyage Chili
WB=CellDBorDBa feet; uE&B feet; f feet; Particulars of Classification (which must be inserted
total capacity tons. FPT tons; APT tons; MT feet tons. precisely as in Register Book & Supplements).

N.B. All alterations in the existing records should be underlined.
If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, and of the inner bottom plating, especially in the boiler space.

Last Report, No. Port

Periodical Surveys, when held, must be reported in detail and verification in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes, and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined? Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR Completion of S.S. No. 3 for Classification (Rot. Rpt 16722a).

How done:- Side bunkers (lower) cleared and examined and, except as stated below, found in good condition; double bottom tanks in way tested. Limbers lifted - no ceiling on tank top.

Repairs required:- On port side, slight repairs are required to the bottoms of the athwartship bulkheads at the forward & after ends.

To complete the survey:- Athwartship bulkheads of lower side bunker on port side to repair at lower parts (see above).

Tank top where locally wasted port & stbd in cross bunker, forward of port & stbd doors to this compartment, to repair (Liv. Rpt 91674).

15 fathoms of cable of proper weight & test to be supplied (Rot. Rpt. 16722a). (P.T.O.)

SUMMARY OF DAMAGE REPAIRS:-	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:-
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE	State if Tanks have been examined inside	Dblng. Plates under Sounding Pipes	Copper, or I.M. of Wood Vessels
Decks	no		(State if on Fell.)
Caulking of Decks	See Report	Engine Room Skylights	When put on, Month Year
Waterways		Coal Bunkers, Open'gs, Lids, &c. (Side) - Good	Boats
Coamings		Scuppers	Masts, Yards, &c.
Beams & Fastenings Side bunkers - Good		Cargo Hatchways	Condition, how ascertained
Outside Plating		Hatches	(State if wedges removed)
Caulking of ditto		Planking of Wood Vessels	Sails
Rivets		Caulking ditto	Equipment letter
Breasthooks & Crutches		Treenails ditto	Anchors, No. of
Transoms		Breasthooks & Stemson ditto	Cables (State if now ranged)
Frames Side bunkers - Good		Transoms, Pointers, & Crutches ditto	length size
Reverse Frames		Timbers of Frame at openings ditto	(on board) size
Floors		Ditto ditto at other places ditto	Rule length size
Keelsons		Stringers, Clamps & Shells ditto	Hawser & Warps
Stringers Side bunkers - Good		Salting ditto	Standing & Running Rigging
Inner Bottom Plating		(State if examined.)	
	Have Pumps now been examined and found efficient? no		
	Have Sluice Valves now been examined and found efficient? no		
	Have Watertight Doors now been examined and found efficient? no		
	Have Ventilators and their Coamings been examined and found efficient? no		

General Observations, Opinion as to Class, Recommendation, &c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:- "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,15," or "to remain as classed and to have record of survey, 1,15, and the notations of ss No. 1-15 and ptND15, &c."

Submitted for the information of the Committee. This vessel is eligible in my opinion to have record of survey 3,27 (Liv.) and notation S.S. Liv. No. 3-3,27, subject to repairs being effected in the bunkers and to 15 fathoms of cable being supplied at the first convenient opportunity, when the class has been assigned by the Committee.

Shell plating to be drilled when vessel is 24 years old or at next S.S. thereafter.

Survey Fee (per Section 28) £ 5 : 0 : 0 Fees applied for, 23.9.1927
Special Damage or Repair Fee (if any) £ Received by me, 4.10.1927
Travelling Expenses (if chargeable) £
Second Surveyor's Fee (if any) £

Committee's Minute TUES. 20 SEP 1927
Character Assigned See Rot J.E. Rpt 16722

Shipping. TUES. 15 MAY 1928
FRI. 21 JUN 1928

FRI. 12 OCT 1928
FRI. 18 MAY 1928
FRI. 24 AUG 1928
TUE. 10 NOV 1931
Surveyor to Lloyd's Register of Shipping
FRI. 23 JAN 1931

Lloyd's Register Foundation

Ex. 13.

ANCHORS.

* When a bower anchor is supplied it must be clearly stated whether it is a 1st, 2nd, or 3rd bower.

CHAIN CABLES.

LR

© 2020

Lloyd's Register
Foundation