

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

MAR 16 1938

of writing Report

When handed in at Local Office

11 MAR 1938

Port of LIVERPOOL

Survey held at Birkenhead

Date, First Survey 21st Feb Last Survey 4th March 1938

on the Machinery of the Wood, Iron or Steel

FOYNES

(No. of Visits 9)

Gross 822

Net 390

Vessel built at Gool

By whom Gool S. B. Ref. C. L. When 1916-4.

Engines made at Hull

By whom Carter C. L. When 1916

Boilers, when made (Main) 1916

(Donkey) -

Owners Limerick S. S. Co. Ltd.

Owners' Address

Managers S. J. K. Raycroft

Port Limerick Voyage

Surveyed at in Dry Dock Cannell Limerick

(State name of Dock.)

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Report No. Port

Particulars of Examination and Repairs (if any) BS & Repair

Medical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the nature and extent of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and details being detailed in the body of the report, should be briefly summarised at the end of the report. State also the names and initials of any letters respecting this case.

Where cases where the Surveyor has not made a special damage report he is required to state whether he has offered his services for this purpose, and why they were declined.

Has a damage report made by anyone else? If so, by whom?

Has the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Donkey " " "

was not done, state for what reasons?

What parts of the Boilers could not be thus thoroughly examined?

What special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Latest date of internal examination of each boiler

Has the Surveyor examine the Safety Valves of the Main Boiler?

Has the Surveyor examine the Safety Valves of Donkey Boiler?

Has the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?

Has the Surveyor examine the drain plugs of the Main Boilers?

Has the Surveyor examine all the mountings of the Main Boilers?

Has the crew shaft now been drawn and examined?

Has the shaft now been changed? If so, state reasons

Has the shaft now fitted been previously used?

Date of examination of Screw Shaft

Engine parts, when referred to by numbers, should be counted from forward.

Has the Surveyor examine the generators, motors, switchgear, cables and fuses?

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms?

Survey is not complete, state what arrangements have been made for its completion and what remains to be done

Complete.

Vessel placed in dry dock, propeller and outside fastenings examined and found in order. Wears down not taken gland not removed.

Main boilers examined internally & externally with their safety valves, doors and mountings. Furnaces and cc backs distorted but considered efficient. Lower manhole doors made a good fit, some plain tubes renewed and other minor repairs effected.

Boilers afterwards examined under steam and safety valves adjusted as above.

Condenser tubes and tube plates removed on account of leakage between water and steam space. It was found that the after tube plate joint

General Observations, Opinion, and Recommendation:— The machinery of this vessel

State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9, 11, B. & M.S. 9, 11, & L.M.C. 9, 11, or

140 lb., F.P., &c.)

is eligible in my opinion to remain as classed with fresh record of BS 3, 38.

BS 3, 38.

Fees applied for

1-4 MAR 1938

Received by me, 8.4.1938

15 MAR 1938

Engineer Surveyor to Lloyd's Register of Shipping.

W. R. Howells.

Liverpool

BS 3.38.

Committee's Minute

BS 3.38.

BS 3.38.

BS 3.38.

BS 3.38.

BS 3.38.

BS 3.38.

BS 3.38.

BS 3.38.

BS 3.38.

BS 3.38.

BS 3.38.

BS 3.38.

BS 3.38.

BS 3.38.

BS 3.38.

BS 3.38.

BS 3.38.

BS 3.38.

BS 3.38.

BS 3.38.

BS 3.38.

BS 3.38.

BS 3.38.

BS 3.38.

Foyres.

face was badly wasted at bottom in way of cooling water inlet port; a new tube plate extending over the existing inlet port has now been fitted and this inlet has been permanently blanked. A new inlet pipe has now been satisfactorily fitted to the lower part of the after door. The forward tube plate and some tubes and junctions also renewed. On completion of the repairs the condenser was examined under test and found satisfactory.

A new feed water heater marked:-
has been satisfactorily fitted at this time.

H. R. Howells

N: 2935
LLOYD'S TEST
SHELL 100 LBS/0"
COILS 450 LBS/0"
W.P. 180 LBS/0"
22.7.37. R.D.B.

RETAIN

