

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

MAY 18 1940

Date of writing Report 16 May 1940 When handed in at Local Office 17-5-1940 Port of Survey

Survey held at Port Talbot Date, First Survey 7 May Last Survey 9 May 1940

on the Machinery of the Wood, Iron or Steel FRANCES MASSEY (No. of Visits 2)

Gross 4212 Vessel built at Sunderland By whom Sir J. Priestman & Co. Year. Month

Net 2538 Engines made at Sunderland By whom G. Clark, Ltd. When 1927 9

375 Boilers, when made (Main) 1927 (Donkey)

Main Boilers 3SB Owners W. A. Massey & Sons Ltd. Owners' Address (if not already recorded in Appendix to Register Book.)

Donkey Boilers 1801b Managers Port Hull Voyage

If Surveyed Afloat or in Dry Dock (State name of Dock.)

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER, Date of last Survey and of Periodical Survey, Year, Month, Machinery and Boiler Surveys (including date of N.B., if any).

-100A1 with Beeboard 11, 39. MS 11, 39.

SS. Hul No 3-11, 39. BS 2, 39.

TS (CL) 10, 39.

Special Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the nature and extent of examinations and subsequent repairs. Repairs on account of damage (the cause of which must be stated) should be separated from repairs due to other causes; and details being detailed in the body of the report, should be briefly summarised at the end of the report. State also the names and initials of any letters respecting this case.

In cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined.

A damage report made by anyone else? If so, by whom?

The Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? Yes

Donkey " " "

If was not done, state for what reasons? Centre boiler now done

What parts of the Boilers could not be thus thoroughly examined?

What special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Latest date of internal examination of each boiler 7 May 1940 Present condition of funnel(s) Good

The Surveyor examine the Safety Valves of the Main Boiler? Yes To what pressure were they afterwards adjusted under steam? not adjusted

The Surveyor examine the Safety Valves of Donkey Boiler? Yes To what pressure were they afterwards adjusted under steam?

The Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? Yes, and of the Donkey Boilers?

The Surveyor examine the drain plugs of the Main Boilers? Yes, and of the Donkey Boilers?

The Surveyor examine all the mountings of the Main Boilers? Yes, and of the Donkey Boilers?

Screw shaft now been drawn and examined? No Is it fitted with continuous liner? Yes Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

Shaft now been changed? If so, state reasons

The shaft now fitted been previously used? Has it a continuous liner? Yes Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

Date of examination of Screw Shaft State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft

Engine parts, when referred to by numbers, should be counted from forward. Is electric light and/or power fitted?

Did the Surveyor examine the generators, motors, switchgear, cables and fuses?

The insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms?

If Survey is not complete, state what arrangements have been made for its completion and what remains to be done

No complete survey

A fresh record of BS 2,40 The Starboard boiler remains to be surveyed in its entirety and the safety valves of all boilers to be adjusted. No definite arrangements could be made for completion of survey.

Now done, Centre boiler together with its safety valves and mountings examined internally and externally and found in order.

General Observations, Opinion, and Recommendation:—

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9,11, B.&M.S. 9,11, & L.M.C. 9,11, or L.M.C. 140 lb., F.D., &c.)

Eligible in my opinion to remain as classed and to have fresh record of BS 2,40 when survey has been completed as above

Fees applied for 17-5-1940

Received by me, 19

Committee's Minute

Signed

Deferred for Comp B.S. to No

FRC 24 MAY 1940

Lloyd's Register Foundation

W395-0030

Is a Certificate required? If so, to be sent to