

## REPORT OF SURVEY FOR REPAIRS, &amp;c.

Date of writing Report *16 Nov 40* When handed in at Local Office *18/11/40* Port of *NEWCASTLE-ON-TYNE*  
No. in Survey held at *Blyth* Date, First Survey *and* Last Survey *13 Nov 1940*  
Reg. Book. *Le 'FARMSUM'* (No. of Visits *1*)  
Tonnage: *5237* Built at *Capelle a/d Ysel* By whom *A. Vrijk & Zonen* When *1929*  
GROSS *4916* Owners *Stoom Maats 'Doelje'* Owners' Address *(if not already recorded in Appendix to Register Book).*  
UNDER DK. *3185* Managers *Vinke & Co* Port belonging to *Amsterdam*  
NET *3185*

Surveyed Afloat or in Dry Dock? *yes* Name of Dock *at Blyth* Destined Voyage  
Cell DB or DBa feet; uE&B feet; f feet  
total capacity tons. FPT tons; APT tons; MT feet tons.

Only alterations in the existing records of tanks should be inserted.  
N.B.—All alterations in the existing records should be underlined.

Last Report, No. *2650* Port *C. In*

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys.	Machinery and Boiler Surveys (Including date of N.B., if any).
<i>+100A1 with ftd 7.40 SS Rot. 102.37</i>	<i>+L.M.C MB 2.37 BS. 3.40 CL.N. 3.40</i>

Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.

Was a damage report made by anyone else? if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR *Damage alleged to have been sustained on 10<sup>th</sup> Sept 40 at Cape Town due to vessel ranging and bumping against wooden fender (S Sins Quay).*  
*Vessel examined in loaded condition by Cape Town Surveyors and Sublim Certificate issued, after slight leakage has been suspected in No 2 hold starboard bilge.*  
*The Master reports that no leakage was apparent on voyage Cape Town - London*  
*Vessel discharged in London this since made voyage, in ballast from London - via*  
*Type to Blyth and Master reports no leakage observed*  
*how done - No 2 Hold Starboard Bilge examined before vessel loaded. no leakage*  
*of any kind found bilges dry.*

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								
PRESENT CONDITION OF THE								
Decks	Bulkheads	Engine Room Skylights	Copper, or Y.M.					(State if on Felt.)
Caulking of Decks	Ceiling	Coal Bunkers, Openings, Covers, &c.	When fitted, Month					Year
Coamings	Cement or Asphalt	Oil Bunkers	Boats					
Beams & Fastenings	Rudder	Scuppers	Masts, Yards, &c.					
Outside Plating	Steering gear and its connections	Cargo Hatchways	Condition, how ascertained					(State if wedges removed.)
" " in way of sidelights	Windlass	Hatches	Equipment letter					
Frames	Have pumps been examined and found efficient?	Planking	Anchors, No. of					
Reverse Frames	Have Sluice Valves been examined and found efficient?	Caulking	Cables (State if now ranged)					
Longitudinals	Have Watertight Doors been examined and found efficient?	Treenails	" length mean diamr.					(on board)
Transverses	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson	" Rule length size					
Floors	Air and Sounding Pipes	Transoms, Pointers & Crutches	Chain Locker					
Keelsons	Doubling Plates under Sounding Pipes	Timbers of Frame at openings	Hawser & Warps					
Stringers		" " at other places	Standing and Running Rigging					
Inner Bottom Plating		Stringers, Clamps & Shelves	Sails					
Have the Tanks been examined internally?		Salting (State if examined.)						
Have the Tanks been tested?								

## General Observations, Opinion as to Class, Recommendation, &amp;c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1.38," or "to remain as classed and to have record of survey, 1.38, and the notations of ss No. 1-38."

*This vessel is, in my opinion eligible to remain as now classed, without fresh record - subject to her being specially examined when next in Dry Dock.*

Survey Fee (per Section 20)	£	:	:	Fees applied for,
Special Damage or Repair Fee (if any) (per sec. 20)	£	:	:	19
Travelling Expenses (if chargeable)	£	:	:	Received by me,
Second Surveyor's Fee (if any)	£	:	:	19

Committee's Minute

Character Assigned

*As now*

*Subject 196*

Surveyor to Lloyd's Register of Shipping.

Lloyd's Register  
Foundation

W396-0167