

WTA

Rio de Janeiro,

23rd August 1932.

H. E. Inman, together with J. H. Barbour, Surveyor to the Registro Italiano,

the Representatives of the Owners and Underwriters attend on board the Steel Sc SR "CAPINERA", 6019 tons net register, of Genoa, on the 5th August 1932 and subsequent dates as she lay in the Lahmeyer Dry Dock, Nictheroy, for the purpose of ascertaining the nature and extent of the damage sustained by the vessel owing to having run on the rocks at Ilha Mae, off the port of Rio de Janeiro, on the 1st June 1932, the vessel being later refloated and placed in dry dock on the 4th August 1932.

For further particulars see Log Book and Protest.

The undersigned upon examination:

Found

Recommended

Keel plating:

No.1 plate broken at the after end and buckled and set up over about 8 feet.

To be renewed.

No.2 plate broken at forward end and buckled and set up over whole length.

To be renewed.

No.3 plate buckled, set up and scored, buttstrap at after end broken.

To be renewed, together with buttstrap.

No.4 plate cracked at forward end, badly buckled and set up over whole length.

To be renewed.

No.5 plate buckled and set up over whole length.

To be renewed.



W4-0099

No.6 plate badly buckled.

To be renewed.

S/S "CAPREIRA" cont.

<u>Found</u>	<u>Recommended</u>
No.6 plate slightly set up over whole length.	To be removed, faired and refitted.
No.7 plate badly set up over whole length.	To be renewed.
No.8 plate set up.	To be removed, faired & refitted.
<u>Port side, Shell plating:</u>	
<u>A Strake:</u> No.1 plate buckled and crushed in over whole length.	To be renewed.
Nos.2,3 & 4 plates badly buckled over whole length.	To be renewed.
No.5 plate slightly set up.	To be removed, faired & refitted.
Nos.6 & 7 plates badly buckled and set up.	To be renewed.
<u>B Strake:</u> Nos.2 & 3 plates slightly buckled.	To be removed, faired & refitted.
Nos.4,5,6,7 & 8 plates badly buckled and set up.	To be renewed.
No.9 plate slightly set up at fore end.	To be removed, faired, refitted or faired in place.
<u>C Strake:</u> No.3 plate set up at after end.	To be removed, faired & refitted.
Nos.4,5,6,7 & 8 plates badly buckled and set up.	To be renewed.
<u>D Strake:</u> No.4 plate badly buckled, set up and scored.	To be renewed.
Nos.5,6 & 7 plates buckled and set up.	To be renewed.
No.8 plate badly buckled and set up.	To be renewed.
No.9 plate slightly buckled.	To be removed, faired & refitted.
<u>E Strake:</u> Nos.3 & 4 plates slightly set in and indented.	To be removed, faired & refitted.
No.5 plate set in, indented, scored and broken.	To be renewed.
Nos.6 & 7 plates badly buckled, set in and torn.	To be renewed.
No.8 plate slightly set in at fore end.	To be faired in place.
<u>F Strake:</u> No.7 plate set in and broken at after end.	To be renewed.
No.8 plate badly buckled and torn.	To be renewed. Plate and angle to be renewed.
<u>Bilge Keel on F Strake:</u> broken and set up in way of plates 7 & 8.	To be renewed.
No.6 plate badly buckled.	To be renewed.



S/S "CAPRERA" cont.

<u>Found</u>	<u>Recommended</u>
Plate slightly bent in way of F.9	To be faired in place.
<u>G Strake:</u> No.2 plate slightly indented in three places.	To be faired in place
No.6 plate slightly indented.	To be faired in place.
No.8 plate set out at lower landing.	To be faired in place.
<u>H Strake:</u> Nos.4,5,6 & 7 plates slightly indented.	To be faired in place.
<u>Starboard side, Shell plating:</u>	
<u>A Strake:</u> Nos.1 & 2 plates badly buckled and set up.	To be renewed.
Nos.3 & 4 plates badly buckled, set up and broken.	To be renewed.
No.6 plate badly set up (16 inches) over whole length.	To be renewed.
No.7 plate badly set up at fore end.	To be renewed.
<u>B Strake:</u> Nos.2 & 3 plates buckled.	To be removed,faired & refitted.
Nos.4 & 6 plates badly buckled and set up.	To be renewed.
Nos.5 & 8 plates badly buckled, set up and broken.	To be renewed.
No.7 plate set up at after end.	To be faired in place.
No.9 plate set up at fore end.	To be faired in place.
<u>C Strake:</u> No.3 plate slightly buckled.	To be removed,faired & refitted.
Nos.4 & 5 plates badly buckled, set up and broken.	To be renewed.
Nos.6,7 & 8 plates buckled and set up.	To be removed,faired & refitted.
No.9 plate set up.	To be removed,faired & refitted.
<u>D Strake:</u> No.4 plate buckled and set up at after end.	To be removed,faired & refitted.
Nos.5 & 6 plates badly buckled, set up and broken.	To be renewed.
Nos.7 & 8 plates badly buckled, set up and scored.	To be renewed.
No.9 plate set up.	To be removed,faired & refitted.
<u>E Strake:</u> No.3 plate buckled and set in for after half length.	To be removed,faired & refitted.
Nos.4,5 & 7 plates badly buckled, set in and broken.	To be renewed.
No.6 plate badly buckled.	To be renewed.



S/S "CAPRERA" cont.

Found

Recommended

F Strake:

No.5 plate set in over after half length.

To be removed,faired & refitted.

Nos.6,7 & 8 plates badly buckled, set in and broken.

To be renewed.

No.9 plate slightly set in at fore end.

To be faired in place.

Bilge Keel in way of F Strake:

The bilge keel plate and angles in way of F 6,7,8 & 9 badly buckled and torn.

The damaged plates and angles to be renewed.

G Strake: Nos.2 & 3 plates slightly indented.

To be faired in place.

One plate on first strake below sheer strake and two ditto on fourth strake cut during salvage operations, also one sidelight removed.

The three plates to be renewed or repaired as required and the sidelight to be refitted.

Double Bottom in way of Nos.1 & 2 Holds:

No.1 hold: The tank top plating cracked right across at after end of the hold and set up for about 50 ft.in length.

The broken plates to be renewed and the remainder to be removed faired and refitted where set up.

The tank margin plates and angles on both sides broken and/or buckled,

The broken and buckled plates and angles to be renewed.

No.2 hold: The tank top plating broken in way of the after bulkhead brackets and the whole of the plating set up.

The broken plates to be renewed and the remainder to be removed faired and refitted.

The tank margin plates and angles on both sides broken and/or buckled.

The broken and buckled plates and angles to be renewed.

Centre & Side Girders, Floors and Longitudinals:

The plates and the angles on the shell and tank top buckled,bent and/or broken in way of the damaged shell and tank top plating.

To be renewed or repaired as required.

Main Transverse Web Frames and Tank Margin Bracket Plates and connections on both sides in Nos.1 & 2 holds all more or less buckled and broken.

All to be renewed or repaired as required.

Bulkheads:

Between Nos.1 & 2 holds, the bilge plate and plate above it on the star-board side and the boundry angle broken.

The two plates and damaged boundry angle to renew.

Between Nos.2 & 3 holds, the bilge plate on the starboard side broken.

To be renewed.

Hold Pillars & Girders in Nos.1 & 2 Holds:

The rivets in the angles and gusset plates all more or less started.

The rivets to test and renew as necessary.

Tween Deck Pillars in Nos.1 & 2 Holds: Six tubular pillars cut and cemented during salvage operations.

To be repaired as necessary.

© 2021

Lloyd's Register Foundation

W4-0099 4/6

"CAPRERA" cont.

Found

Recommended

ventilators in Nos.1 & 2 Holds:

Painted and cemented during salvage operations.

To be repaired or renewed as necessary.

Nos.1 & 2 Hatchways:

Number of hatch covers and tarpaulins destroyed during salvage operations and the remainder soaked with fuel oil, also several hatch battens missing and cleats broken.

Approximately 100 hatch covers and 8 tarpaulins to be renewed, -ns also 5 galvanized iron hatch battens and several cleats.

Drum and Sounding Pipes in Nos.1 & 2 Holds:

All the pipes disconnected and plugged during salvage operations and the protecting angles displaced.

All the pipes to be made good and angles refastened.

Coaming and Sparring in Nos.1 & 2 Holds and Tween decks.

All more or less broken, damaged and soaked with fuel oil.

To be renewed as necessary.

Upper Deck:

Steel plate on starboard side of No.2 hatchway cut during salvage operations.

To be renewed or repaired.

Removal of 3rd Class saloon dismantled during salvage operations

To be replaced and made good.

Removal of accommodation, rivets burnt out.

Rivets to be renewed.

Removal of bulwark brackets and the rails and stanchions more or less bent in several places.

To be faired and repaired as necessary.

Removal of lito-silo on the deck broken in places.

To be renewed where broken.

Removal of port bow fairlead and starboard stern fairlead started.

To be renewed or repaired.
-d.
The two fairleads to be refastened

Removal of accommodation ladder on starboard side broken.

To be renewed.

Lower Deck, Nos.1 & 2 Holds:

Removal of trimming hatches closed with cement and covers missing.

The cement to be removed and new covers fitted.

Lifeboats:

No.3 Lifeboat chafed and damaged
No.1 part equipment missing.
No.2 small boat, ditto ditto.

To be repaired as necessary and equipment made good.

Ballast, ballast and steam heating pipes in Nos.1 & 2 ballast tanks:

Number of pipes bent and displaced.

The pipe lines to be overhauled, repaired as necessary and tested.

© 2021

Lloyd's Register Foundation
W4-0099 5/6

H.E. 2/2

Found

Recommended

Equipment:

The ^{port} starboard bower anchor and 120 fathoms of chain cable employed during salvage operations and not yet recovered.

The starboard bower anchor and chain cable to be replaced and the remaining cable to be ranged for examination.

A 90 fathom length of 8" manila hawser and three steel wire towing hawsers stated to have been destroyed during salvage operations.

To be replaced by new.

General Recommendations:

The rudder to be lifted for examination. The main and auxiliary machinery to be opened up for examination, also the screw shaft to be drawn in and sea and bilge valves and connections opened up. The outside shell plating and the inside plating in way of Nos. 1 & 2 holds and tween decks to be cleaned and painted one coat as before and all new and disturbed work to be painted two coats.

These recommendations are made so as to place the vessel in the same good and efficient condition as before the damage was sustained.

J. B. Barbour.

Surveyor to the Registro Italiano.

H. E. Suman.

Surveyor to Lloyd's Register.



© 2021

Lloyd's Register Foundation

W4-0099 6/6

[Faint, illegible text, possibly bleed-through from the reverse side of the page]

#



© 2021

Lloyd's Register
Foundation