

-9 SEP 1925

(Received at London Office)

## Report of Survey for Repairs, &amp;c., of Engines and Boilers.

Date of writing Report 1. 9. 1925 When handed in at Local Office 4. 9. 1925 Port of Greenock.

No. in Reg. Book, Survey held at Port Glasgow. Date, First Survey 13th July, 1925. Last Survey 1st Sept 1925.

12120 on the Machinery of the ~~Wood, Iron or Steel~~ S.S. ACHROITE. (No. of Vents 12.)

Tonnage { Gross 1196  
Net 410 Vessel built at Glasgow. By whom J. Shearer & Son. When 1898-8

Nominal Horse Power 126 Engines made at " By whom Muir & Houston Ltd. When 1898.

No. of Main Boilers 1 Boilers, when made (Main) 1925 (Donkey)

No. of Donkey Boilers 1 Owners W. Robertson Port Glasgow Voyage

Steam Pressure in Main Boilers 169 lb. Surveyed Afloat or in Dry Dock Clyde S. B. Co. Slip. Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

in Donkey Boilers 1/10

Last Report No. Port

Particulars of Examination and Repairs (if any) + N.B. + L.M.C.

(Periodical Surveys, when held, must be reported in detail and variation in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined? Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? Yes

Do. " Donkey " " " No.

If this was not done, state for what reasons? Donkey boiler removed ashore and scrapped.

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler?

Yes To what pressure were they afterwards adjusted under steam? 16.3.

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boiler?

Yes, and of the Donkey Boiler?

Did the Surveyor examine the drain plugs of the Main Boilers?

None, and of the Donkey Boiler?

Did the Surveyor examine all the mountings of the Main Boiler?

Yes, and of the Donkey Boiler?

Has screw shaft now been drawn and examined?

Yes Is it fitted with continuous liner? Yes Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? No.

Has shaft now been changed? No If so, state reasons

Is the shaft now fitted new? Has it a continuous liner

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft? Close (re-wooded).

If the Survey is not complete state what arrangements have been made for its completion and what remains to be done? Complete.

Now done:- Examined. Cylinders, Pistons, Slide valves and faces. Crank Thrust and Tunnel shafts. Air Circulating. Feed and Bilge pumps and their connections, and put in order. Condenser tested and found tight. Sea connections and their fastenings examined and found good. Tail shaft drawn in, examined and found good. Propeller renewed. Feed and General service pumps opened up, examined and put in order. Windlass and Steering engines opened up, examined and put in order. Main steam pipe annealed and re-tested. New Main Boiler (see G.R. Rpt. No. 18448) now securely fitted on board and its Safety valves adjusted under steam as stated. The Donkey boiler has now been removed ashore and it is stated, will not be replaced.

General Observations, Opinion, and Recommendation:- The machinery of this vessel is (State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.: thus, for example, B.S. 9,11, B.&M.S. 9,11, or L.M.C. 9,11, 140 lb., F.D., &c.)

now in good order and condition, and eligible, in my opinion, to remain as classed, with fresh record of survey + L.M.C. 9.25 and T.S. 9.25. C.L. and notation of + N.B. 9.25. The record of, D.B. not to be used, in the Special Reasons List may now be expunged.

Survey Fee (per Section 28) £ 8.0

Fitting New Main Boiler £ 3.3

Special Damage Report Fee (if any) (per Section 29.)

Travelling Expenses (if chargeable)

Fees applied for

H. 9. 1925

Received by me,

10/9/25

Committee's Minute

GLASGOW 8-SEP 1925

Assigned + L.M.C. 9.25

CERTIFICATE WRITTEN + N.B. 9.25

16/9/25

Note Shaft

Engineer Surveyor to Lloyd's Register of Shipping.

Lloyd's Register Foundation

W 405-0131



S.I. No. 1. due 5.24 full screw shaft cannot  
 thin boiler removed donkey boiler removed  
 from vessel

N.B. - If this Report is copied by Copying Press special care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

It is submitted that  
 this vessel is eligible for  
 THE RECORD. + L.M.C. 9.25 without

special instructions

S. 9.25 + N.B. 9.25

1st 1st B up 140 lb (\$ 304  
 9.1.63 R. 1.2/10 NHP 126

10/9/25.

Continuation. Grk Rpt.

88" ACHROITE

# Repairs.

New Main boiler complete with safety valves and mounting  
 securely fitted on board the vessel. Centre collision chocks and  
 rolling stays renewed.

H.P. Piston rod skinned up. new neck ring and gland bushes fitted.

HP & IP Valve rods

Feed & Bilge pump rods

HP & MP crank pin bushes re-metalled. Top half No 1 Main bearing  
 re-metalled.

Centrifugal pump. New Impeller shaft fitted. New rings in steam piston.

Feed Donkey. New rings in Feed and Waterends.

Stem bush re-lined with lignum-vitae wood.

Steering engine. New piston rings and new valve spindles fitted.



© 2019

Lloyd's Register  
 Foundation

THE SUPERVISORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.

F.

Rpt.

Date

No.

Re

12

Ma

En

Bo

Reg

MT

(Le

Bo

No.

safe

Are

Sma

Mat

D.