

(Received at London Office)

III 15 1940

07 on the Machinery of the Wood, Iron or Steel S.S. Arkledown Year. Month.

Gross 5414 Vessel built at Port Glasgow By whom Lithgows & Co Ltd When 1933-4
3207 By whom D. Rowan & Co Ltd When 1933

Net 520 Engines made at Wassgou By whom Aux
Final 544 Boilers when made (Main) 1933 (Donkey) 1933

| | | |
|----------------|-----------------------------|---|
| Power | Boilers, 3 | Owners' Address |
| Main Boilers 2 | Owners National S.S. Co Ltd | (if not already recorded in Appendix to Register Book.) |
| | J. C. Harrison Ltd | Port London Voyage |

Donkey Boilers 1
Pressure—
Boilers 220 lbs
If Surveyed Afloat or in Dry Dock Mount Stuart Dry Dock
Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

| | | | | |
|------------------------|-----------------------|----------|---|---|
| 2200 Monkey Boilers | (State name of Dock.) | J. J. J. | CHARACTER. * for Special Survey Date of last Survey and of Periodical Surveys. | Machinery and Boiler Surveys (Including date of N.B., if any) |
|------------------------|-----------------------|----------|---|---|

Particulars of Examination and Repairs (if any) Docking & Repairs + 100 A 1
10-30 B.S. 24

[illegible]

unit of Damage (the cause or description of the damage) should be briefly summarized at the end of the report. If the damage is being detailed in the body of the report, the summary should be brief and to the point. If the damage is being detailed in the body of the report, the summary should be brief and to the point. If the damage is being detailed in the body of the report, the summary should be brief and to the point.

image cases where the survivor has
offered his services for this purpose, and why they were declined

a damage report made by anyone else? If so, by whom? _____

_____ Main Roller separately and make a thorough examination at this time? no

the Surveyor personally go inside each main tunnel to examine the
 " *Quarry* " " *No*
 " *Do they* " " *are have been completed at Worthington*

is was not done, state for what reasons? Baker Survey stated a fair value

what parts of the Boilers could not be thus thoroughly examined?

in the absence of internal examination, were adopted by the _____

_____ of each Boiler?

what special means, in the case of the boiler, to insure the thoroughness of the examination of each boiler? _____ Present condition of funnel () good.

the Surveyor examine the Safety Valves of the Main Boiler? _____ To what pressure were they afterwards adjusted under steam? _____

the Surveyor examine the Safety Valves of Donkey Boiler? _____ To what pressure were they _____, and of the Donkey Boilers?

the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?, and of the Donkey Boilers?

the Surveyor examine the drain plugs of the Main Boilers: _____, and of the Donkey Boilers? _____

the mountings of the Main Boilers? _____ and appliance fitted at the after end of { _____

the Surveyor examine all the mountings. _____ Is it fitted with continuous liner? _____ Is an approved appliance used _____
 _____ Has now been drawn and examined? No _____ the shaft to permit of it being efficiently lubricated? _____

shaft now been changed? ☒ If so, state reasons _____ Is an approved appliance fitted at the after end of _____
_____ and fit to permit of it being efficiently lubricated? ☒

the shaft now fitted been previously used? ☒ Has it a continuous liner? ☒ the shaft to permit of its being

State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft ☒

Is the after bearing fitted

Is electric light and/or power used _____

So, did the Surveyor examine the generators, motors, switchgear, cables and fuses? _____

the insulation resistance of the generators, circuits and apparatus.

State what arrangements have been made for its completion and what remains to be done.

Land and sea connection faster

Now done:- Vessel placed in dry dock. propeller shaft broken and

examined.

Repairs:- Part boiler all plain & 65 stay tubes renewed.

Spiders. Spent " " " 28 " " and built up by electric welding in a number of places where

Sube plates cleaned & examined. 1-28 rolls / 1" with satisfactory res

On completion of repairs boilers tested by hydraulic pressure 200 lbs.

21 M. 1. The vessel is

General Observations, Opinion, and Recommendation:—The Machinery of this vessel is in the existing classification of the Register Book, consequent upon this survey, as follows, viz. *Class* B.S. 2, 11, B.&M.S. 2, 11, & L.M.C.

(State clearly what alteration, if any, is suggested to be made in the machinery, boilers, working pressure, or other part of the vessel, and specify the nature of such alteration required to be made in the records of the vessel's machinery, boilers, working pressure, etc., as shown without fresh record of Survey.)

eligible in my opinion remains as classified -

8 11

Fees applied for

Survey Fee (per Section 29) £ : : 13 July 1942
313 : 0
Lamish W. G. Paton

Special ~~Surveyor~~ Repair Fee (if any)..... £ 5 5 8
(per Section 29.)
(if chargeable)..... £ : :
Received by me, _____ 19 _____
Engineer Surveyor to Lloyd's Register of _____

Travelling expenses (if chargeable) _____

TUE 28 JUL 1940

Attos's Minute

Committee's Minute _____
Assigned _____ As now _____

Assigned _____

100