

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office) DEC 6 1939

Date of writing Report 10 When handed in at Local Office 29 NOV 1939 Port of LIVERPOOL

No. in Reg. Book. Survey held at Birkenhead Date, First Survey 5/10/39 Last Survey 22/11/1939
28067 on the Machinery of the Wood, Iron or Steel Sc "Kyle Girth" (No. of Visits 9)

Tonnage Gross 450 Net 178 Vessel built at Cityr By whom Ailsa S.B. Co. Ltd. When 1905-4
Nominal Horse Power 64 R. Engines made at Irvine By whom Renfrew Bros & Co. Ltd. When 1905.
No. of Main Boilers 1 SB Boilers, when made (Main) 1905 (Donkey) ✓
No. of Donkey Boilers ✓ Owners' Address ✓
Steam Pressure in Main Boilers 130 lb Managers J. F. Lawson & Co. Ltd. (if not already reported in Appendix to Register Book.)
in Donkey Boilers ✓ Port Glasgow Voyage ✓

Last Report No. Port Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Particulars of Examination and Repairs (if any) T.S. & L.M.C.

(Periodical surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of repairs, if any, and, in detail, the nature and extent of examinations and subsequent repairs. Repairs on account of damage (the cause of which must be stated) should be separated from repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined ✓

Was a damage report made by anyone else? If so, by whom? ✓

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? Yes

Did the Surveyor personally go inside each Donkey Boiler separately and make a thorough examination at this time? ✓

If this was not done, state for what reasons? ✓

And what parts of the Boilers could not be thus thoroughly examined? ✓

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? ✓

State latest date of internal examination of each boiler 13/10/39 Present condition of funnel(s) renewed.

Did the Surveyor examine the Safety Valves of the Main Boiler? Yes To what pressure were they afterwards adjusted under steam? Not done.

Did the Surveyor examine the Safety Valves of Donkey Boiler? ✓ To what pressure were they afterwards adjusted under steam? ✓

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? Yes, and of the Donkey Boilers? ✓

Did the Surveyor examine the drain plugs of the Main Boilers? ✓, and of the Donkey Boilers? ✓

Did the Surveyor examine all the mountings of the Main Boilers? Yes, and of the Donkey Boilers? ✓

Has screw shaft now been drawn and examined? Yes Is it fitted with continuous liner? Yes Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? ✓

Has shaft now been changed? No If so, state reasons ✓

Has the shaft now fitted been previously used? ✓ Has it a continuous liner? ✓ Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? ✓

State date of examination of Screw Shaft 18/10/39 State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft Renewed.

Engine parts, when referred to by numbers, should be counted from forward. Is electric light and/or power fitted? No

So, did the Surveyor examine the generators, motors, switchgear, cables and fuses? ✓

Was the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? ✓

If the survey is not complete, state what arrangements have been made for its completion and what remains to be done To complete the survey the boiler safety valves require to be adjusted under steam. The Supr Engr states that this will be done within the next few weeks.

Now done: - Vessel placed in dry dock. The propeller & all outside fittings examined and found in good order. Sea connections opened out and found or placed in good condition. Screw shaft drawn & found satisfactory; stern bush renewed.

Cylinders, pistons, valves & casings, condenser, crank & thrust shafts main & aux pumps, all opened out & examined & found or placed in good order. Pumping arrangements examined. [See continuation sheet]

General Observations, Opinion, and Recommendation: - The machinery of this vessel is (State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9, 11, B.&M.S. 9, 11, L.M.C. 9, 11, or L.M.C. 140 lb., F.D., &c.)

now in safe working condition, eligible in my opinion to remain as classed, with fresh notation of T.S.-CC 1039 new, and record +L.M.C. 11.39 when the survey is completed.

Survey Fee (per Section 20) L.M.C. £ 7 : 0 : 0 Fees applied for

Special Damage or Repair Fee (if any) (per Section 20.) £ 3 3 : 0 29 NOV 1939

Surveying expenses (if chargeable) £ : : Received by me, 19

Committee's Minute Deferred LIVERPOOL - 5 DEC 1939

Assigned T.S. 10.39. W407-0031(11/2)

CHARACTER. For Special Survey Date of last Survey and of Periodical Surveys.	Years assigned how entered.	Machinery and Boiler Surveys (including date of N.B., if any).
+ 100 A1		+ L.M.C.-2.36
2.36		B.S. - 3.38
		T.S. CC-1.36
SS. Bkn 2 nd No 3-11.30		
SS Bkn No 1 - 36		
Cargo Boilers not fitted.		

REPAIR

A.W.B. Edwards
Engineer Surveyor to Lloyd's Register of Shipping.
WED 20 DEC 1939

Lloyd's Register Foundation

Insert Character of Ship and Machinery precisely as in the Register Book

If a Certificate required? If so, to be sent to

Machinery of S.S. "Kyle Firth"

Steampipes examined & two lengths of copper main steam pipe annealed & hyd tested to 260 lbs.

Boiler & mountings opened out and examined internally

Repairs now done, to Owner's account:-

Boiler:- 18 plain & 4 stay tubes renewed. A number of corroded C.C. back & side stays renewed. Centre C.C. bottom plate seams E.W. locally. Fore & aft end plate reinforced by E.W. in way of grooving below centre furnace flange. Fore collision shock renewed.

Starboard lower manhole door studs renewed, & P lower manhole opening built up by E.W. Smokeboxes repaired & funnel renewed.

Main deck valve chest renewed & sundry other minor repairs effected.

Two main steampipe flanges rebrazed & two lengths of copper feed pipe renewed.

H.P. slide valve refaced & false face in valve chest renewed.

Main engine circ pump body built up by E.W. on corroded landings.

" " feed & bilge pump valves refitted & two feed valves skimmed up & rebushed.

Thrust shoes reinstalled.

A number of bilge & tank suction pipes renewed.

Repairs examined & found satisfactory

AWSB.



© 2019

Lloyd's Register
Foundation

W407-00312121

Noted.

As the year of grace has expired
it is submitted to notation
+ the 11.39 might be assigned
subject to the Order 11's being
adjusted under steam.

DA

15/12/51

[Faint, mostly illegible handwritten text, possibly bleed-through from the reverse side of the page.]



© 2019

Lloyd's Register
Foundation