

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office

19 OCT 1939

Date of writing Report 9-10-1939 When handed in at Local Office 9. 10. 1939 Port of Glasgow
 No. in Survey held at Troon Date, First Survey and Last Survey 7-10-1939
 Reg. Book. 20017 on the Machinery of the Wood, Iron or Steel S.S. "ARIS" (No. of Visits 1)

Gross 4810 Net 3020 Vessel built at Stockton By whom Richardson, Duck, & Co. Ltd. When 1914 6
 Engines made at Stockton By whom Blair & Co. Ltd. When 1914
 Nominal Horse Power 385 Boilers, when made (Main) 1914 (Donkey)
 No. of Main Boilers 3 S.B. Owners Michael M. Xylas Owners' Address Port of Troon Voyage
 No. of Donkey Boilers 1 S.B. Managers Michael M. Xylas If surveyed Afloat or in Dry Dock Troon D.D.
 in Main Boilers 1 S.B. (State name of Dock.)
 in Donkey Boilers 1 S.B.

Last Report No. PortParticulars of Examination and Repairs (if any) Docking

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined.

Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? No

" " Donkey " " B.S. not due
 If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

State latest date of internal examination of each boiler

Present condition of funnel Good

Did the Surveyor examine the Safety Valves of the Main Boiler?

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?

, and of the Donkey Boilers?

Did the Surveyor examine the drain plugs of the Main Boilers?

, and of the Donkey Boilers?

Did the Surveyor examine all the mountings of the Main Boilers?

, and of the Donkey Boilers?

Was screw shaft now been drawn and examined? No Is it fitted with continuous liner?

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

Was shaft now been changed? If so, state reasons

Was the shaft now fitted been previously used? Has it a continuous liner?

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

State date of examination of Screw Shaft

State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft 7/32"

Engine parts, when referred to by numbers, should be counted from forward.

Is electric light and/or power fitted? Yes.

So, did the Surveyor examine the generators, motors, switchgear, cables and fuses?

Was the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms?

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done Complete

Now Done.

Vessel placed in dry dock, propeller, after end of stern tube and outside fastenings of under water sea connections examined and found in good order.

Estb

9/10/39

General Observations, Opinion, and Recommendation:— The machinery of this

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9,11, E.&M.S. 9,11, L.M.C. 9,11, or L.M.C. 140 lb., F.D., &c.)

vessel so far as now seen is in efficient condition and eligible in my opinion to remain as classed without fresh record of survey

Survey Fee (per Section 29) £ : ✓ Fees applied for
 Special Damage or Repair Fee (if any) £ :
 Travelling expenses (if chargeable) £ :
 Received by me, £ :
 19

Committee's Minute GLASGOWAssigned As now

19 OCT 1939

RH

W. Russell 1919
 Engineer Surveyor to Lloyd's Register of Shipping.

Lloyd's Register
 Foundation

W421-0205

Natid

TRm

23.10.39



© 2019

Lloyd's Register
Foundation