

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report July 30th 1937 When handed in at Local Office 19 Port of SAN FRANCISCO
No. in Survey held at Oakland Date, First Survey June 28th Last Survey July 10, 1937
Reg. Book. 21337 (No. of Visits 1)
71630 on the Wood, Iron or Steel T.S.M.V. "BEULAH"
TONNAGE: Built at Fevig By whom Randolph A/S Skibs When 1923 3
GROSS 1389 Owners CARRISO, INC. Owners' Address (if not already recorded in Appendix to Register Book).
UNDER DK. 1216 Managers Flood Bros. Port belonging to Panama
NET 1042

Surveyed Afloat or in Dry Dock? Both Name of Dock Moore Dry Dock Co. Destined Voyage

WB=Cell DBordBa feet; uE&B feet; f feet
total capacity tons FPT tons; APT tons; MT feet tons.

N.B.—All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 4435 Port Vcr.

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

CHARACTER. For Special Survey. Date of last Survey and of Periodical Surveys.	Year Assigned New Survey.	Machinery and Boiler Surveys (including date of N.B., if any).
<u># 100 A 1-6-36</u>		<u>* LMC 10-33</u>
<u>SS L.A.No. 3, 10-33</u>		<u>* LMC(M) 6-36</u>
		<u>DBS - 6-36</u>
		<u>O.G. - 10-33</u>
		<u>DB.14 Fit. 32.</u>

Society's Freeboard (if assigned) as ft. ins.
painted on Ship and now verified Board of Marine
Underwriters of
San Francisco, Inc.

REPAIRS, OR EXAMINATION AS PER RULE, FOR damage stated to have been sustained

due to grounding at Mazatlan, June 10th, 1937 and part S. S. 2nd No. 1.

Vessel placed on drydock. Bottom and Rudder cleaned, examined and coated.

Cables ranged 240 Fath. 1-11/16" to 1-13/16" dia. 5 anchors

Windlass opened up, examined throughout and tested. New piston rings now fitted.

After deep tanks, Port and Starboard tested to rule requirements and proven tight. A number rivets and seams caulked as necessary in way of shell and bulkheads.

Part S. S. 2nd No. 1

Examined Forepeak and Forward Deep Tanks internally.

Forepeak Tank tested.

P. T. O.

SUMMARY OF DAMAGE REPAIRS:—

	Shell Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Paired or Repaired								
Paired or Repaired in place								

PRESENT CONDITION OF THE

Decks <u>Good</u> ✓	State if Tanks have been examined inside <u>as above</u>	Air and Sounding Pipes <u>Good</u>	Copper, or Y.M. of Wood Vessels <u>—</u>
Caulking of Decks <u>"</u>	State if Tanks now tested <u>as above</u>	Dblng. Plates under Sounding Pipes <u>Yes</u>	(State if on Felt). When put on, Month <u>—</u> Year <u>—</u>
Coamings <u>"</u>	Bulkheads <u>Good</u> ✓	Engine Room Skylights <u>Good</u> ✓	Boats <u>Good</u>
Beams & Fastenings <u>"</u>	Ceiling <u>"</u>	Coal Bunkers, Open'gs, Lids, &c. <u>—</u>	Masts, Yards, &c. <u>"</u>
Outside Plating <u>"</u>	Cement or Asphalt <u>Cement</u>	Oil Bunkers <u>Good</u>	Condition, how ascertained <u>From Deck</u>
" in way of sidelights <u>"</u>	(State which.) <u>Good</u> ✓	Scuppers <u>"</u>	(State if wedges removed) <u>—</u>
Breasthooks <u>"</u>	Rudder <u>"</u> ✓	Cargo Hatchways <u>"</u> ✓	Sails <u>—</u>
Transoms <u>—</u>	Steering gear and its connections <u>"</u> ✓	Hatches <u>"</u> ✓	Equipment letter <u>—</u>
Frames <u>Good</u> ✓	Windlass <u>"</u> ✓	Planking of Wood Vessels <u>—</u>	Anchors, No. of <u>5</u>
Reverse Frames <u>"</u> ✓	Have pumps now been examined and found efficient? <u>Yes</u>	Caulking ditto <u>—</u>	Chain Locker <u>Good</u>
Longitudinals <u>"</u> ✓	Have Sluice Valves now been examined and found efficient? <u>—</u>	Treenails ditto <u>—</u>	Cables (State if now ranged) <u>Yes</u>
Transverses <u>"</u> ✓	Have Watertight Doors now been examined and found efficient? <u>—</u>	Breasthooks & Stemson ditto <u>—</u>	" length <u>240</u> mean diam. <u>1-11/16</u> ✓
Floors <u>"</u> ✓	Have Ventilators and their Coamings been examined and found efficient? <u>Yes</u> ✓	Transoms Pointers, & Crutches ditto <u>—</u>	" Rule length <u>—</u> size <u>—</u> ✓
Keelsons <u>"</u> ✓		Timbers of Frame at openings ditto <u>—</u>	Hawser & Warps <u>Good</u>
Stringers <u>"</u> ✓		Ditto Ditto at other places ditto <u>—</u>	Standing and Running Rigging <u>Good</u>
Inner Bottom Plating <u>—</u> ✓		Stringers, Clamps & Sheffs ditto <u>—</u>	
		Salting ditto <u>—</u>	
		(State if examined.)	

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24 and ptND24, &c."

This vessel is eligible in my opinion to remain as classed with fresh record of survey 7-37 and notation S. S. S.Fo. No. 1 - 37, when the survey has been completed.

Survey Fee (per Section 20) \$20.00
Special Damage or Repair Fee (if any) \$40.00
Travelling Expenses (if chargeable) \$4.50
Second Surveyor's Fee (if any) 2

Fees applied for,
July 20, 1937
Received by me,
19

Committee's Minute

Character Assigned 100A1

NEW YORK AUG 11 1937

Surveyor to Lloyd's Register of Shipping.

R. J. Boomer

Lloyd's Register
Foundation

NOTE - S. S. No. 1 partly held
D.B.S. 6, 37 T. S. N. 7, 37.

W425-0084

1081535

TO COMPLETE S. S. 2nd No. 001

ernally

test.

ed.

Between the two there have been several

ANCHORS.

If Patent state name of Patentee.

If Stockless, state Mechanical Tests

Iron Stream Chain
or Steel Wire....



Lloyd's Register
Foundation