

# Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

14 SEP 1939

Date of writing Report 17 SEP 1939 When handed in at Local Office 17 SEP 1939 Port of LIVERPOOL  
 in Survey held at Liverpool Date, First Survey 27/7/39 Last Survey 11/9/1939  
 Book. 11/9/1939 (No. of Visits 10)

11/9/1939 on the Machinery of the Wood Iron or Steel 1/1 "COUNSELLOR"  
 Gross 5068 Vessel built at Glasgow By whom C. Connell & Co Ltd Year. Month. 1926. 8.  
 Net 3158 Engines made at do. By whom D. Brown & Co Ltd When 1926.  
 464. Boilers, when made (Main) 1926. (Donkey) 1926.  
 of Main Boilers 2 DB (S) Owners Cherwell S.S. Co Ltd Owners' Address (if not already recorded in Appendix to Register Book.)  
 of Donkey Boilers 1 Managers T. J. Hamman Port Liverpool Voyage ✓  
 Main Pressure 200 1/1 Surveyed Afloat in Dry Dock Laughton  
 Main Boilers 200 (State name of Dock.)  
 Donkey Boilers 120

st Report No. Port  
 Particulars of Examination and Repairs (if any) LMC  
 Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the nature of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and slides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.  
 Damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined.

Is a damage report made by anyone else? If so, by whom?  
 Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?  
 " " Donkey " " " "

What parts of the Boilers could not be thus thoroughly examined?  
 What special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Latest date of internal examination of each boiler 27/7/39. Donkey 3/8/39.  
 Present condition of funnel(s) Efficient

Did the Surveyor examine the Safety Valves of the Main Boiler?  
 To what pressure were they afterwards adjusted under steam? 200 lbs/sq. in.

Did the Surveyor examine the Safety Valves of Donkey Boiler?  
 To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?  
 , and of the Donkey Boilers?

Did the Surveyor examine the drain plugs of the Main Boilers?  
 , and of the Donkey Boilers?

Did the Surveyor examine all the mountings of the Main Boilers?  
 , and of the Donkey Boilers?

Has screw shaft now been drawn and examined? No. Is it fitted with continuous liner?  
 Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

Has shaft now been changed? ✓ If so, state reasons  
 Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

Has the shaft now fitted been previously used? ✓ Has it a continuous liner?  
 Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

Date of examination of Screw Shaft ✓ State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft 3/16  
 Is electric light and/or power fitted?

Engine parts, when referred to by numbers, should be counted from forward.  
 Did the Surveyor examine the generators, motors, switchgear, cables and fuses?

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms?  
 The Survey is not complete, state what arrangements have been made for its completion and what remains to be done.

have done. Vessel placed in dry dock. Propeller, all sea cocks & valves & outside fastenings of its connections, all cylinders, pistons, slides valves & rings, the whole of the crank, turntable & tunnel shafting, with its bearings, frames & shoes, the main condenser, the air, circulating, feed, bilge & sanitary pumps, with their brackets, valves & connections, the main & donkey boilers with their mountings, doors & fastenings, examined.  
 All main & auxiliary steam pipes of 3" dia & over hydraulically tested to 100 lbs/sq. in.  
 The SVs of the main & donkey boilers adjusted under steam as above.  
 The main condenser re. tested & tested.

Repairs. D.E. Bolters 2. Co Keys Renewed & minor E.W. repairs carried out.  
Pumps generally overhauled & put in good order.

General Observations, Opinion, and Recommendation:—  
 (State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, S.S. 9, 11, S.M.S. 9, 11, & L.M.C. 9, 11, or L.M.C. 140 lb., F.D., &c.)  
The machinery of this vessel, as far as I am concerned, is in good order & eligible in my opinion to remain as classified & to have full record of + L.M.C. - 9.39.

Survey Fee (per Section 29) LMC £ 13 0 0 Fees applied for  
 Special Damage or Repair Fee (if any) EL £ 1 - - Received by me,  
 (per Section 29.)  
 Voluntary expenses (if chargeable) £ : :  
 Committee's Minute  
 signed + L.M.C. 9.39.

LIVERPOOL 12 SEP 1939  
L. Hamman Stuart & J. B. Bickley  
 Engineer Surveyor to Lloyd's Register of Shipping.

W433-0100  
 Lloyd's Register Foundation

Insert Character of Ship and Machinery precisely as in the Register Book

Is a Certificate required? If so, to be sent to



Counsellor.

Electrical Equipment Examined and tested under Working Conditions.  
Generator switch board, fittings etc Examined. Insulation test Carried out.  
Repairs. Low insulation faults located and cleared. Generator overhauled  
cleaned & varnished. Minor repairs to lighting circuit. Affected



15. 9. 39

1843