

S/S "SVARTON" (2359 Gr.Reg.Tons) Nils Lund, Master.
bewerst af af bns best psgtj

I like to go to California II, x 22 x 22 "A" size
beverage of all kinds that I

This is to certify that the undersigned is a

A.J.J.VAN DEN ANDER, Engineer and Shipsurveyer to the Joint
Underwriters Union of AMSTERDAM and J.B.SLEEBE, Engineer- and
Shipsurveyer to Lloyds Register at AMSTERDAM, appointed by
Mr.C.A.Brems, Consul General of Sweden at Amsterdam, for the
purpose of surveying and estimating the damage sustained to
the S/S "SVARTON", Capt. Nils Lund and belonging to the

Rederi-Aktiebolag Lulea-Afeten at Stockholm, by collision
of either with an underwater floating mine or other explosive object,
on 25th February 1915, in the "North" Sea, and afterwards towed
into Ymuiden, proceeded 26th February 1915 and subsequent
days on board of the S/S "SVARTON", while standing in the
dry dock at Amsterdam, the particulars seen the Sea-protocol
at 's Hradet-Amsterdam 3. bewonen of of bns neerd "SAGE"
"je x "s "IS after careful examination Undersigned found the
principal damage on Starboard side, in way of No. x1 Hold and
ed explosion bulkhead, where a hole was struck in the outside-
plating from the margin-plate to the hold-stringer about
16 feet long and 13 feet wide, by which the fore-peak and
No. 1 Hold had been flooded.

Please specify the date.

They specify the damage as follows.

but I have not yet had time to do so. I will do so as soon as possible.

OUTSIDE-PLATING-STARBOARD-SIDE

1 Plate in A-strake 12' 4" x 32" x 9/16", 2 plates in B-strake
11' 2" x 32" x 9/16" and 10' 10" x 42" x 9/16", 2 plates in
C-strake 9' 4" x 38" x 1/2" and 12' x 33 $\frac{1}{2}$ " x 1/2", 2 plates
in D-strake 20' 8" x 73" x 1/2" and 19' x 43 $\frac{1}{2}$ " x 9/16", 2 plates



W 438-0065

Lloyd's Register
Foundation

in E-strake 18' 10" x 53" x 7/16" and 19' 8" x 63" x 1/2",
2 plates in F-strake 17' 9" x 55" x 7/16" and 20' 2" x 59" x
7/16", 1 plate in G-strake 17' 4" x 51" x 7/16" broken or
badly bent and to be renewed.
1 plate in C-strake 11' x 55" x 1/2" bent and to be removed
faired and refitted. It said plate is of side
stainless steel in G-strake bent and to be faired in place. L.L.A.
has -
OUTSIDE-PLATING-PORT-Side.
of herneque MACINTYRE has been advised by L.L.A.
1 plate in Sheerstrake 19' 8" x 47" x 1/2" badly bent and
said plate is now to be renewed to original condition. C.G.C.M.
to be renewed.
of herneque stainless steel plates has been advised to be renewed
1 plate in J-strake bent and to be faired in place.
said plate is of stainless steel and "MOTRAVE" S/S said
FRAMES-STARBOARD-No. Held. is now to be renewed to original condition.
7 Frames, bulb-angle 31' 2" x 9 1/2" x 1 3/8" x 7/16" and 14 intermediate
be(frames, bulb-angle 41' 5" x 6 1/2" x 3 1/2" x 7/16" broken and to be
renewed; has been advised to be renewed to original condition of said
FRAMES-STARBOARD-FORE-PEAK. "MOTRAVE" S/S said to be renewed as follows:
1 Double-frame of collision-bulkhead, angle 31' 2" x 4 1/2" x 4 1/2"
x 9/16" broken and to be renewed. 3 Frames, bulb-angle 21' 4"
x 9 1/2" x 5 1/2" x 1 1/2" and 27' 10" x 9 1/2" x 3 1/2" x 1 1/2" and 21' 4" x 9 1/2"
x 3 1/2" x 1 1/2" broken and partially to be renewed. 3 intermediate
-sh frames, bulb-angle 7' 5" x 6 1/2" x 3 1/2" x 7/16" broken and to be
renewed. Said plate is of stainless steel and to be renewed to original
condition. Said plate is of stainless steel and to be renewed to original
FRAMES. PORT-SIDE No. 1 Held.

2 Frames, bulb-angle 11' 6" x 9 $\frac{1}{2}$ " x 3 $\frac{1}{2}$ " x $\frac{1}{2}$ " broken and partially to be renewed. 1 Frame bent and to be faired in place. 2 intermediate frames bulb-angle 14' 4" x 6 $\frac{1}{2}$ " x 3 $\frac{1}{2}$ " x $\frac{1}{2}$ " to 7 $\frac{1}{2}$ " broken and to be renewed. 1 stringer-plate A to be fitted at each end 2' 6" x 1' 11" OI OI bma 3 $\frac{1}{2}$ ' x 9 $\frac{1}{2}$ " x 2' 11" stringer-plates-starboard-sime-in No. 1 Hold.

3/8", 1 Stringer-angle-bar 14'11" x 6" x 4" x $\frac{1}{2}$ ", 7 shell-lugs 26" x 3 $\frac{1}{2}$ " x 3 $\frac{1}{2}$ " x $\frac{1}{2}$ " and 6 lug-pieces 9" x 3 $\frac{1}{2}$ " x 3 $\frac{1}{2}$ " x $\frac{1}{2}$ ". 1 Stringer-plate 30' x 14" x 3/8", 1 stringer-angle-bar 30' x 6" x 4" x $\frac{1}{2}$ ", 14 shell-lugs 26" x 3 $\frac{1}{2}$ " x 3 $\frac{1}{2}$ " x $\frac{1}{2}$ " and 14 lug-pieces 9" x 3 $\frac{1}{2}$ " x 3 $\frac{1}{2}$ " x $\frac{1}{2}$ ". 1 Stringer-plate 21'4" x 43" x 7/16", 1 stringer-angle-bar 23' x 4" x 4" x $\frac{1}{2}$ ", 11 shell-lugs 26" x 3 $\frac{1}{2}$ " x 3 $\frac{1}{2}$ " x $\frac{1}{2}$ ", 11 lug-pieces 9" x 3 $\frac{1}{2}$ " x 3 $\frac{1}{2}$ " x $\frac{1}{2}$ " and 1 angle-bar 3'3" x 5 $\frac{1}{2}$ " x 4" x $\frac{1}{2}$ " broken and to be renewed.

1/2" x 4 $\frac{1}{2}$ " x 1/8" rad-angles 1, "8 $\frac{1}{2}$ " x "14" x "1" 1/2" smooth

STRINGER-PLATES-STARBOARD-SIDE IN FORE-PEAK.

1 Stringer-plate 3'3" x 33 $\frac{1}{2}$ " x 3/8" broken and to be renewed.

1 Stringer-plate 10' x 20" x 3/8" bent, to be removed, faired and refitted. 2 Double-angle-bars on collision-bulkhead, 2' x 3 $\frac{1}{2}$ " x 3 $\frac{1}{2}$ " x $\frac{1}{2}$ " and 10' x 4" x 4" x $\frac{1}{2}$ ", to be removed, faired and refitted.

STRINGER-PLATES-PORT-SIDE IN No.1 HOLD.

1 Stringer-plate 25'7" x 14" x 3/8", 1 stringer-angle-bar 25'7" x 6" x 4" x $\frac{1}{2}$ ", 12 shell-lugs 26" x 3 $\frac{1}{2}$ " x 3 $\frac{1}{2}$ " x $\frac{1}{2}$ " and 12 lug-pieces 9" x 3 $\frac{1}{2}$ " x 3 $\frac{1}{2}$ " x $\frac{1}{2}$ " broken or bent and to be renewed. 1 Stringer-plate bent and to be faired in place.

COLLISION-BULKHEAD.

3 Plates $14'1'' \times 63'' \times 3/8''$, $7'7'' \times 43'' \times 3/8''$ and $18'4'' \times 45'' \times 7/16''$, 2 Horizontal-stiffeners, bulb-angle, $25' \times 8'' \times 3'' \times 7/16''$ and $23' \times 8'' \times 3'' \times 7/16''$, 1 Vertical-stiffener $11'4'' \times 5\frac{1}{2}'' \times 3\frac{1}{2}'' \times 3/8''$ and 2 bracket-plates $30'' \times 30'' \times 3/8''$.
broken and to be renewed.
1 Plate $12'4'' \times 67'' \times 3/8''$, 1 bracket-plate $30'' \times 30'' \times 3/8''$,
1 Vertical-stiffener $4'6'' \times 5\frac{1}{2}'' \times 3\frac{1}{2}'' \times 3/8''$ and 1 bracket-plate $6'' \times 20'' \times 3/8''$ bent, to be removed, faired and refitted. 2 Vertical-stiffeners bent and to be faired in place.

-flent DOUBLE-BOTTOM. "0 x "11' 1" red-slags-regnita I . "8/8
x "1/8 x "1/8 1 Margin-plate 17' 4" x 36" x $\frac{1}{2}$ ", 1 angle-bar 27' 3" x 3 $\frac{1}{2}$ "
red-slags-regnita x 3 $\frac{1}{2}$ x $\frac{1}{2}$, 7 bracket-frames 5' 3" x 36" x 3/8", 7 angle-
bars $\frac{1}{2}$ x "1" bars 4" x 4" x 3 $\frac{1}{2}$ x $\frac{1}{2}$, 7 angle-bars 2' 4" x 4 $\frac{1}{2}$ " x 3" x $\frac{1}{8}$
and 1 iron-air-pipe on No.1 Tank broken and to be renewed.
red-slags-regnita 2 Tank-top-plates 12' 3" x 59" x 5/16" and 13' 6" x 63" x
"1" x "5/16" bent, to be removed, faired and refitted.
x "3" red-slags-fibre $\frac{1}{2}$ x "1/8" x "1/8" regnita II

FLOORS AND SIDE-INTERCOSTAL-PLATES.

2 Floors 15' 1" x 44" x 3/8", 1 angle-bar 15' 1" x 3 $\frac{1}{2}$ " x 3 $\frac{1}{2}$ "
x $\frac{1}{2}$ ", 1 side-intercostal-plate 3' 3" x 24" x 3/8" bent, to
be removed, faired and refitted.

bewener ed of the hold 3' 3" x "0" x "0" regnita I

HOLD-BEAMS IN No.1 HOLD.

Hold-beams, bulb-angle 39' 4" x 9 $\frac{1}{2}$ " x 3 $\frac{1}{2}$ " x $\frac{1}{2}$ " and angle-
bar 39' 4" x 3 $\frac{1}{2}$ " x 3 $\frac{1}{2}$ " x 3/8", 4 bracket-plates 27 $\frac{1}{2}$ " x 27 $\frac{1}{2}$ "
x 3/8" broken and to be renewed. 1 Bracket-plate on hold
beam under hatchway 33" x 27" x 3/8" and 1 Tee-bar on same
red-slags-regnita 17' x 6" x 4" x $\frac{1}{2}$ " broken and to be renewed. 2 Bulb-angle-
bars $\frac{1}{2}$ x "1/8" bars 2' 8" x 8" x 3 $\frac{1}{2}$ " x $\frac{1}{2}$ " bent, to be removed, faired and
ed of the hold 2' 8" x 8" x 3 $\frac{1}{2}$ " x $\frac{1}{2}$ " refitted. 1 Bracket-plate connecting frame and deck-plating
29 $\frac{1}{2}$ " x 29 $\frac{1}{2}$ " x 3/8" broken and to be renewed.

HOLDBEAM IN FORE-PEAK.

x "4" 81 bars 1 Holdbeam bent and to be faired in place. 1 Bracket-plate
x "8" x "2" 24" x 24" x 3/8" broken and to be renewed.

2 Hold-pillars, 6" diam. 1 dito 3 $\frac{1}{2}$ " diam. 1 dito 3" diam.

and 2 dito 2 $\frac{1}{2}$ " diam. bent, to be removed, straightened and
refitted. 2 Hold-ladders 22' x 2 $\frac{1}{2}$ " diam. broken and to be
renewed. 21 Steps broken or bent and to be renewed.

HOLD-PILLARS IN No.1 HOLD.

1 Hold-pillar bent, to be removed, straightened and refitted.

DECK-PLATING.

otib 8 bns 11 Deck-stringer-plate at Port-side 21' 4" x 48" x 7/16" and
of irregular 1-deck-plate 21' x 63" x 3/8" broken and to be renewed.
bewener ed 1 Deck-plate 18' 8" x 61" x 3/8", 1 double-plate 4' 5" x
beringer 32" x 3/8", 1 hatchway-stanchion 3' x 7" x 1 $\frac{1}{2}$ " bulb-bar
beggal ed obent, to be removed, faired and refitted. 1 Deck-plate at
bns qu-bene Port-side bents and to be faired in place. 1 Deck-beam,
roll hatch-coaming at Port-side bent and to be faired in
bewener ed shifting-beam-No.1 hatch, broken and to be renewed.
bns beggal For the execution of these repairs 3 bulwark-stanchions
bewener ed 4' 5" x 6 $\frac{1}{2}$ " x 4" x 1 $\frac{1}{2}$ " 2-bitts and W.C. have to be removed
and refitted ed of the beggal qu-bene qu-beam

CEILING IN No.1 HOLD.

Ceiling broken or partially lost through the
aperture in outside-plating and to be renewed; 925 square
feet, 3" double thick, fir, and side-ceiling 1225 square
feet, 2 $\frac{1}{2}$ " thick, fir. bns qu-bene ed of
ceiling to renew 3 bewener ed of the hold to shot.

CEILING IN No.2 HOLD.

Ceiling to be removed and partially renewed for cleaning
ed of the hold 2' 8" x 8" x 3 $\frac{1}{2}$ " bns bewener ed of the
tanktop and testing tank, 3300 square feet, 3" thick, fir.

CEILING IN AFTER-HOLD.

Doubling under hatches No.III and No.IV, 310 square feet
3 $\frac{1}{2}$ " thick, fir, to be removed for testing tanks and renewed.


ENGINE AND BOILERS.

Engine to be opened for inspection. Propeller to be
unshipped and propeller-shaft drawn in for inspection.

While steaming to Utrecht, after the accident,
the engines made about 50 per cent more revolutions as
ordinary, in consequence of the lifting of the stern by the
water in No.1 Hold and the fore-peak and therefore 6 main-
bearing-top-brasses, 2 feed-pump- and 2 bilge-pump-plungers

W438-0065

34



Lloyd's Register
Foundation

have been damaged.

4 Main-bearing-top-brasses have to be remetalled and 2 dito to be planed and skimmed up. 2 Iron-feed-pump-plungers to be skimmed up and 2 iron-bilge-pump-plungers to be renewed and rebushed. 2 Main-steam-pipes to be annealed, repaired and tested, 2 flanges to be renewed and pipes to be lagged. Holding-down-belts worked loose and to be tightened-up and 24 bolts to be renewed. Condenser to be opened for inspection, 10 condenser-pipes damaged and to be renewed. Condenser to be tested. Lagging of port-boiler damaged and to be renewed. 2 Boiler-fastenings broken and to be renewed. Steam-feed-pump damaged and to be repaired.

STEAM-WINDLASS.

Steam-windlass shaken by the heavy shock of the explosion and star-board-anchor and cable ran out. Steam-windlass to be dismounted and remounted. Main-shaft to be skimmed up and compressor-nut to be renewed. 2 Tie-rods of brake broken and to be renewed. 2 Liners of lifters and friction-sheaves to be skimmed up. 1 Piston-rod broken and to be renewed and rebushed. 1 Piston-rod bent, to be straightened and rebushed. 6 Piston-packing-rings broken and to be renewed. 1 Slide-valve-rod-bent and to be straightened and rebushed. 1 Crank-shaft and eccentric-sheave broken and to be renewed.

STEAMWINCH No.II.

3 Steam-pipes damaged and to be repaired.

SUNDRIES.

Chain-cables to be unshipped and shipped. Chain-locker to be cleaned. No.I Tank and fore-peak to be cleaned, cemented and painted. No.I Hold and limbers to be cleaned. Tank-tops in No.I and No.II Hold to be cleaned and tarred.

Tank No.I, II and IV to be opened, closed and tested

and leakages to be repaired. 2 Iron-sounding-pipes in No.II Hold to be renewed. 2 Lead-bilge-suction-pipes in No.II Hold to be partially renewed. Hatches of No.I Hatch wholly and of No.II Hatch, partially to be renewed.

Under-side fore-castle-deck to be repaired. 5 Scuttle-glasses in crew-space broken and to be renewed. 1 Door in crew-space damaged and to be repaired. 1 Door-lock in chart-room and in crew-space broken and to be renewed. 1 Paint-locker in fore-peak damaged and to be repaired.

Ship to be placed in dry-dock, incl. tugs to and from dry-dock. Rudder to be lifted for inspection. All repaired or renewed parts to be painted. Outside-plating to be painted.

INVENTORY.

- 1 Straining-screw of Port-chain-cable broken and to be renewed.
- 1 Iron-spoke of windlass broken and to be renewed.
- 2 Wooden-hawse-plugs lost and to be replaced.
- No.I Derrick-gooseneck broken and to be renewed.
- 3 Scaling-hammers, 4 scrapers and 1 sledge-hammer lost overboard and to be replaced.
- 4 Stoves and pipes damaged and to be renewed and refastened.
- Clock in saloon damaged and to be repaired.
- Compasses damaged, to be repaired and adjusted, including tugs.
- 6 Lamps and lanterns damaged and to be renewed.
- 13 Lamps and lanterns damaged and to be repaired.
- 2 Hatch-battens of No.I Hatch broken and to be renewed.
- 1 Flag-staff on fore-castle lost and to be replaced.
- 1 Copper-bell broken and to be renewed.
- 2 Life-boats, with complete inventory lost and to be replaced.

W438-006S 414

W438-0066

©2020

Lloyd's Register
Foundation

bejed bus besoel, beriged ed of VI bns II, I.O.M. tank
replaced by new ones.

mi seqiq-anibnou-novl S. beriged ed of segnab bns
1 Binocular, 2 life-buoys and 1 box with blue lights

mi seqiq-noldon-expid-had S. bewener ed of bns II, O.M.
lost with the life-boats and to be replaced.

I.O.M. to seidell. bewener vilisitig ed of bns II, O.M.
4 Tarpaulings of No.I and No.II hatches damaged and
bewener ed of vilisitig, had II, O.M. to bns vilisitig dojsk
to be renewed.

-elijf S. beriged ed of moeb-eldao-erol abia-uebu
2 Canvas covers for chain-pipes, 2 dito for ventilators

ni door I. bewener ed of bns noldon eosqa-wero mi aensalp
and 2 weather-clothes on bridge damaged and to be
mi wool-wool f. beriged ed of bns begamab eosqa-wero
renewed.

.bewener ed of bns noldon eosqa-wero mi bns moek-trislo
10 L. varnish spoiled and to be replaced.

.beriged ed of bns begamab eosqa-erol mi wool-trislo I.

While steaming and towing to Utrecht and
most bns of agud assisted by trawler, 120 fathoms ratline, 1 hawser 3"
beriged III. assisted by trawler, 120 fathoms ratline, 1 hawser 3"
ed of manilla, 30 fathoms 2" manilla and 90 fathoms 2½" manilla,
90 Fathoms 3½" steel wire and 30 fathoms 4" steel wire
broken, badly chafed and to be renewed.

As the crew could not remain in the crew-space
ed of bns noldon eldao-nido-potf to weroa-guisid S.
in fore-castle during the repairs, a temporary residence

has been made aft, where 16 new bunks, banks, lockers and
bewener ed of bns noldon assibniw to eosqa-novl I
doors have been made.

.beqiqed ed of bns jaol aqiq-eewsi-neboof S.

Undersigned estimate the total repairing- and

.bewener ed of bns noldon eosqa-wero mi wool-trislo
replacing-costs of this damage at f 31.515.-

feol temmadi-egbela I bns aqiqed S. gremmed-gniblof S.

Say: Thirty-one thousand five hundred and fifteen Dutch florins.

.benigaster bus bewener ed of bns begamab aeqiq bns aavof S.
They estimate the value of the S/S "SVARTÖN" in
beriged ed of bns begamab noolsa mi wool
the damaged condition in which she has been towed into the
anibuloni. beriged ed of bns begamab eosqa-novl
Harbour of Utrecht and afterwards placed in the dry-dock
at Amsterdam, on 26th February 1915 at f 260.000.-

.bewener ed of bns begamab arriefnesi bns aqiqed S.


Say: Two hundred sixty thousand Dutch florins. val 81

.bewener ed of bns noldon dojsk I.O.M. to aenitad-notsk S.

.beqiqed ed of bns jaol eljaso-erol no Tista-gaif I.

Amsterdam, 29th March 1915. ed of bns noldon Med-isqqo S.

ed of bns jaol viojnevni estiqmoo diliw, atmod-erid S.



© 2020

Lloyd's Register
Foundation