

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office FEB 13 1939)

Date of writing Report 17:1:39 When handed in at Local Office _____ 19 _____ Port of BANGKOK
 No. in Reg. Book 78916 Survey held at Bangkok Date, First Survey 9:1:39 Last Survey 11:1:39 19 _____
 on the Machinery of the Wood, Iron or Steel M.V. MALINI (No. of Visits 2)

Tonnage { Gross 1278 Vessel built at Nakokov. By whom A/S Nakokov Skibsvaert When 1925 7
 Net 788 Engines made at Holeby By whom Holeby Diesel Mufk. When 1925
 Nominal Horse Power 245 Boilers, when made (Main) _____ (Donkey) _____
 No. of Main Boilers _____ Owners Siam Steam Nav. Co. Ltd. Owners' Address _____
 No. of Donkey Boilers _____ Managers _____ Port Bangkok Voyage _____
 Steam Pressure in Main Boilers _____
 in Donkey Boilers _____
 If Surveyed Afloat or in Dry Dock Drydock (State name of Dock.) _____

Last Report No. 1239 Port Bangkok.
 Particulars of Examination and Repairs (if any) + L.M.C. (C.S.)

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined _____

Was a damage report made by anyone else? If so, by whom? _____

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

" " Donkey " " " "

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

State latest date of internal examination of each boiler _____ Present condition of funnel(s) _____

Did the Surveyor examine the Safety Valves of the Main Boiler? To what pressure were they afterwards adjusted under steam? _____

Did the Surveyor examine the Safety Valves of Donkey Boiler? To what pressure were they afterwards adjusted under steam? _____

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? and of the Donkey Boilers?

Did the Surveyor examine the drain plugs of the Main Boilers? and of the Donkey Boilers?

Did the Surveyor examine all the mountings of the Main Boilers? and of the Donkey Boilers?

Has screw shaft now been drawn and examined? No Is it fitted with continuous liner? Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

Has shaft now been changed? If so, state reasons _____ Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

Has the shaft now fitted been previously used? Has it a continuous liner? Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

State date of examination of Screw Shaft _____ State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft S. 1/4 P. 1/8

Engine parts, when referred to by numbers, should be counted from forward. Is electric light and/or power fitted?

If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses?

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms?

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done _____

Now Done for + L.M.C. (C.S.) Examined N°5 Stard cylinder, piston, rings, valves, valve gear, cover, connecting rod, top end, bottom end, crankpin. N°2 Diesel Generator complete, with compressor, starting air bottle. New crankshaft (N°4352-19-10-39) fitted, and new main bearings. Main engine port & stard. compressor inter-cooler. Port engine lubricating oil pump. Sea connections & fastenings. Repairs for Damage, new brass ring & set pins fitted to aft end port stern bush. Propeller refitted.

General Observations, Opinion, and Recommendation:— That the machinery of this vessel, is eligible, in my opinion, to remain as classed with fresh record of + L.M.C. (C.S.) with date
 (State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 0,11, E.&M.S. 0,11, X L.M.C. 0,11, or X L.M.C. 140 lb., F.D., &c.)

Survey Fee (per Section 29) £ 4:4:0 Fees applied for 17:1:39
 Special Damage or Repair Fee (if any) (per Section 29.) £ _____
 Travelling expenses (if chargeable) £ _____
 Received by me, L.A. Richardson 19 _____
 Engineer Surveyor to Lloyd's Register of Shipping.

Committee's Minute _____
 Assigned As now
 FRI. 3 MAR 1939
 Lloyd's Register Foundation
 W458-0038

Insert Character of ship and Machinery precisely as in the Register Book

Is a Certificate required? If so, to be sent to _____