

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

12 OCT 1939

Date of writing Report 19 When handed in at Local Office 11/10/39 Port of NEWCASTLE-on-TYNE
 No. in Reg. Book Survey held at Wellington Quay in Lync Date, First Survey 23rd Sep Last Survey 29th Sep 1939
 27/14 on the Machinery of the Wood, Iron or Steel 1/2 CANDLESTON CASTLE. (No. of Visits 3)

Tonnage { Gross 2494 Vessel built at Burntisland By whom Burntisland S.B. Co. Ld. When 1920, 7.
 Net 1470 Engines made at Spruandland By whom R. E. Marine Eng. Co. Ld. When 1920
 Nominal Horse Power 237 Boilers, when made (Main) 1920 (Donkey)
 No. of Main Boilers 2 Owners J. & S. C. S. S. Co. Ld. Owners' Address (if not already recorded in Appendix to Register Book)
 No. of Donkey Boilers 1 Managers Ohlson S S Co. Port Cardiff Voyage
 Steam Pressure in Main Boilers 180 lb. If Surveyed Afloat or in Dry Dock Afloat
 in Donkey Boilers (State name of Dock.) Clelands Shipway.

Last Report No. 97819 Port Nure

Particulars of Examination and Repairs (if any) B.S.

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined.

Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? Yes.

" " Donkey " " "

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

State latest date of internal examination of each boiler Port 3rd Dec. 23/9/39.

Present condition of funnel(s)

Did the Surveyor examine the Safety Valves of the Main Boiler?

To what pressure were they afterwards adjusted under steam? 180 lb./sq.

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?

, and of the Donkey Boilers?

Did the Surveyor examine the drain plugs of the Main Boilers?

, and of the Donkey Boilers?

Did the Surveyor examine all the mountings of the Main Boilers?

, and of the Donkey Boilers?

Has screw shaft now been drawn and examined?

Is it fitted with continuous liner?

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

Has shaft now been changed? If so, state reasons.

Has the shaft now fitted been previously used?

Has it a continuous liner?

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

State date of examination of Screw Shaft.

State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft.

Engine parts, when referred to by numbers, should be counted from forward.

Is electric light and/or power fitted?

If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses?

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms?

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done.

This vessel has recently been bought by Messrs The Olsson Steamship Co. of Hull. The boilers were surveyed 4, 39. (See Nure. Rpt. No. 97819) and the Owners now ask whether, as the vessel has been laid up and the boilers not used since the last survey, a later date might be assigned.

Now done: The boilers re-examined inside and outside and no deterioration found to have taken place. Safety valves adjusted under steam to pressure stated above.

General Observations, Opinion, and Recommendation:—

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9, 11, B.S.M.S. 9, 11, L.M.C. 9, 11, or L.M.C. 140 lb., F.D., &c.)

is eligible in my opinion to remain as classed and to have records of + L.M.C. 8, 39. B.S. 9, 39. in the Register Book.

Survey Fee (per Section 29) £ :

Special Damage or Repair Fee (if any) (per Section 29.) £ :

Travelling expenses (if chargeable) £ :

Fees applied for

19

Received by me,

10

Committee's Minute

FRI. 20 OCT 1939

Assigned

Tamb. 9.39

William G. G. G.

Engineer Surveyor to Lloyd's Register of Shipping

Lloyd's Register Foundation

W458-0179

Boiler examined

after lay up.

It is submitted that

the vessel is eligible for

THE RECORD.

without special conditions or adjustment

of safe guards.

18/10/39

18/10/39

18/10/39

18/10/39

18/10/39

18/10/39

18/10/39

18/10/39

18/10/39

18/10/39

18/10/39

18/10/39

18/10/39

18/10/39

18/10/39

18/10/39

18/10/39

18/10/39

18/10/39

18/10/39

18/10/39

18/10/39

18/10/39

18/10/39

18/10/39