

## Report of Survey for Repairs, &amp;c., of Engines and Boilers.

(Received at London Office)

JUL 29 1939

Date of writing Report 22-7-1939 When handed in at Local Office 27/7/1939 Port of NEWCASTLE-ON-TYNE

No. in Reg. Book. Survey held at Hethorn, N-Tyne Date, First Survey 5-6-39 Last Survey 21-7-1939 (No. of Visits 5)

23418 on the Machinery of the Wood, Iron or Steel SS "Donie Star"

Tonnage Gross 10086 Vessel built at Port Glasgow By whom Litchgows Ltd. When 1921-10 mo

Net 6347 Engines made at Manchester By whom Tait &amp; Phipps Ltd. Co. Ltd. When 1921

Nominal Horse Power 1398 Boilers, when made (Main) 1921 (Donkey) -

No. of Main Boilers 6 Owners Union Coal Storage Co. Ltd. Owners' Address (if not already recorded in Appendix to Register Book)

No. of Donkey Boilers 1 Managers Blue Star Line Ltd. Port London Voyage London - Australia

Steam Pressure 200 lb. If Surveyed Afloat or in Dry Dock afloat &amp; Palmer's Dock. Particulars of Classification (which must be inserted precisely as in Register Book &amp; Supplements).

in Donkey Boilers - Last Report No. Port Particulars of Examination and Repairs (if any) T.S. &amp; Repairs

(Periodical Surveys, when held, must be reported in detail and verbatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined

Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

" " Donkey " " " "

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

State latest date of internal examination of each boiler Present condition of funnel(s)

Did the Surveyor examine the Safety Valves of the Main Boiler? To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler? To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? , and of the Donkey Boilers?

Did the Surveyor examine the drain plugs of the Main Boilers? , and of the Donkey Boilers?

Did the Surveyor examine all the mountings of the Main Boilers? , and of the Donkey Boilers?

Has screw shaft now been drawn and examined? Yes Is it fitted with continuous liner? Yes Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

Has shaft now been changed? If so, state reasons Has the shaft now fitted been previously used? Has it a continuous liner? Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

State date of examination of Screw Shaft 19.7.39 State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft Reversed

Engine parts, when referred to by numbers, should be counted from forward. Is electric light and/or power fitted? Yes

If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses?

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms?

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done Complete

How done:- Vessel in drydock. Examined propeller, screw shaft, stern bush &amp; outside fastenings of all connections. H.P. &amp; L.P. turbine rotors &amp; bearings.

Repairs:- Stern bush lower half renewed. L.P. turbine N°4 diaphragm plate renewed, saddle disc at fore end of shaft renewed.

Repairs damage:- stated caused by fire on the 21st ult. whilst lying alongside quay at Hethorn, Palmer's. Hethorn:- Ford &amp; after start boiler partly relagged. Tank &amp; bilge piping in way renewed, examined, regulated as necessary &amp; refilled. Some flanges, where doubtful, welded to pipes. Ash coals also down opened out &amp; examined. Reexamined gear for tanks &amp; tubes. White, enhanced, parts renewed as required, tested &amp; refilled.

General Observations, Opinion, and Recommendation:- The Machinery of this vessel,

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &amp;c.; thus, for example, E.S. 9,11, E.&amp;M.S. 9,11, &amp; L.M.C. 9,11, or S.L.M.C. 140 lb., F.D., &amp;c.)

as far as now seen, is eligible in our opinion to remain as classed with fresh record, of T.S. 7.39 C.L.

Survey Fee (per Section 29) £ : : Fees applied for 27 JUL 1939

Special Damage or Repair Fee (if any) £ 22/0 Received by me, 16/8 1939

Travelling expenses (if chargeable) £ : : Committee's Minute

Assigned As now

57.39

Lloyd's Register Foundation

W468-0006

Insert Character of Ship and Machinery precisely as in the Register Book

Is a Certificate required? If so, to be sent to